

MAGNETI

Ford Mustang '19 BEV

Vehicle information


Make:	Ford	License:	
Gearbox:	Automatic	Body color:	
Model:	Mustang '19 BEV	VIN:	WF0TK1EM9MMA14521
Fuel type:	Electric	Power:	190 kW
Version:	Mustang EV 75kWh RWD St.Ran.	First registration	31/05/2021
Mileage:	152048 km	N° of doors:	

Damage summary

Front	1
Left	3
Right	1

Commercial pictures





Batterijcertificaat

Datum van diagnose: 13/07/2026



Raadpleeg het Moba-certificaat door deze QR-code te scannen

94%

Status van de gezondheid (SOH)*

Ford Mustang MACH e Standard Range


VIN : WF0TK1EM9MMA14521
Kilometerstand : 152.048 km

*SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie

Meer weten over: www.get-moba.com





Options according to the inspector			
Central consol F	Yes	GPS	Yes
Radio multimedia	Yes	Rear view camera	Yes
		Headlights Xenon/LED/Laser	Yes
		Telephone equipment	Yes
Damages			
Bonnet Scratch(es) Repair and paint (complete) Front			
Door FL Dent(s) and scratch(es) Repair and paint (complete) Left			
Wing RL Scratch(es) Repair and paint (complete) Left			
Wing RL Scratch(es) Repair and paint (complete) Left			
Wing RR Bad repair Repair and paint (complete) Right			

Tyres		
	Front Left Winter 225/60/18/104/V Continental 2.4 mm	
	Front Right Winter 225/60/18/104/V Continental 4.7 mm	
	Rear Left Winter 225/60/18/104/V Continental 3.3 mm	
	Rear Right Winter 225/60/18/104/V Continental 4.9 mm	

Checks		
CO2 Emission	0 Digital maintenance	Yes
GPS storage	Yes Luggage cover	Yes
Number head rests	5 Number of charging cables (rapid charge)	2
Number of keys total	2 Reset to factory settings	Yes, vehicle is reset to factory settings
Service book	N/A User's manual	Yes

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.