



Expertise

Protocol number: 46328933
Order No. / Reference: 26685439
Inspection date: 6 Jul 2026

Manufacturer: Opel	Model: Insignia Sports Tourer 2.0 Diesel Aut. Business Elegance
VIN: W0VZT8GP9M1018003	



ALPHABET



ALPHABET

Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Insignia Sports Tourer 2.0 Diesel Aut. Business Elegance	
Vehicle Identification number	W0VZT8GP9M1018003
Mileage (Read)	138,514 km
First registration	21 Jun 2021
Number of holders	1
Next periodical technical inspection	06/2028
(Report on hand)	
Power / Engine displacement	128 kw / 1,995 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Carbon Braun Metallic
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black
readiness to drive	Not roadworthy / moveable



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	95 %
Last service on / at	06/2026 at 138,305 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA206308
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	With complaint
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	1844 / AMC 00114		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,215 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 101V	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	225/55 R17 101V	Winter tyres on Light alloy	Pirelli	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 100Y	Summer tyres on Light alloy	Bridgestone	3mm / 3mm
2)	245/45 R18 100Y	Summer tyres on Light alloy	Bridgestone	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
Tirefit		Expiration date 04/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Airbag: Front and rear outer head airbags
- Ambient lighting
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- Roof rails, silver anodized
- Tachometer
- Electronic Stability Program (ESP Plus)
- Front collision warning system with pedestrian detection and automatic emergency braking
- Speed controller
- rear window wiper
- Automatic climate control, two zones
- Rear headrests (3 pieces)
- LED fog lights
- Steering column adjustable for height and reach
- Illuminated makeup mirrors in both sun visors
- Package: Charging (Sports Tourer)
- Package: Innovations 1
- Electric parking brake
- Upholstery: Monita fabric/Premium leather look
- Radio: Digital radio reception DAB+
- Radio accessories: 2 USB ports
- Tire repair kit (including tire sealant and 12-volt compressor (without jack))
- Power steering
- Seat belts: Three-point seat belts in all seats
- Visibility equipment
- Lane Keeping Assist
- Start/Stop System
- Traction Control (TC) Plus
- Immobiliser
- Central locking with remote control
- Airbag: Front airbags (multi-stage) and side airbags, driver and front passenger
- Anti-lock braking system (ABS)
- Hill Start Assist
- third brake light
- Diesel particulate filter
- Electronic brake force distribution (EBD)
- Electric windows front and rear
- Pedestrian protection including active hood
- luggage compartment cover
- Transmission: 8-speed automatic transmission
- Child safety lock in the rear doors, manual
- Front headrests
- LED headlights
- LED daytime running lights including LED indicators, front and LED taillights
- Center armrest, front
- Package: Easy-Access
- Park & Go with reversing camera, digital
- Parkpilot, front and rear parking aid
- Quickheat rapid heating system
- Radio: Multimedia Navi Pro with 8" color touchscreen display
- Tire pressure gauge
- Rear seat backrest with FlexFold function, foldable in a 40:20:40 ratio
- safety net
- Seats: Ergonomic active seat (AGR) for driver and front passenger
- Bumpers painted in body color
- Pre-installation for child seat mounting system "ISOFIX"
- Thermal insulation glazing, green tinted
- Second folding ignition key

Extra equipment

- Airbag: Side airbags, rear outer (seatbelt warning for unfastened seatbelts, rear (child seat attachment system remains activated))
- Paint finish: Metallic
- Package: Innovations 2 (Sports Tourer automatic transmission) (Head-up display, Adaptive cruise control (Generation 3), Stop & Go function, Forward collision alert with pedestrian detection and automatic emergency braking, active from 4 km/h, range 150 m. In case of collision risk, the braking system is prepared and, if necessary, emergency braking/automatic emergency braking is initiated. Lane keeping assist, keyless entry and start system, sensor-controlled electric tailgate, stainless steel loading sill protector)
- Swiveling trailer hitch (including trailer stability program)
- Chassis: FlexRide Premium chassis (Innovative chassis system with adaptive driving style recognition and three selectable driving modes: Standard, Sport (personalizable) and Tour, including: - Electronic damper control - Speed-sensitive power steering - Networking of all driving dynamics systems)
- Package: Sound (Noise-reducing, laminated side windows (front) - Bose sound system)
- Wheels: 8.5 J x 18 alloy wheels in high-gloss black (multi-spoke) (with 245/45 R 18 tires)
- Solar Protect heat-insulating glazing (in the rear, heavily tinted)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed, problem has been detected This is due to the following reason.: Motorkontrolle Leuchtet
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Due - Replace
2	Vehicle glazing	Rear window - Scratch(es) - Loss in value
3	Roof	Roof - dent(s) - Smart repair
4	Instrument panel	Indicator light (Motorkontrolle) - on - Perform diagnosis
5	2nd wheel set	1 alloy rim (Wurde bearbeitet, verschürft) - Unprofessionally repaired - Replace
6	2nd wheel set	1 alloy rim (Wurde bearbeitet) - Unprofessionally repaired - Replace
7	Side panel - rear left side	Side panel - Scratch(es) - Repair and paint
8	Side panel - rear right side	Side panel - Scratch(es) - Repair and paint
9	Rear bumper	Rear bumper - Scratched - Repair and paint
10	Boot lid / rear door	Boot lid (mit Entkleben) - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 14 Apr 2023	3.452,53 €

Repainting

No.	Repainting
1	Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Door - front right side	226 µm
-------------------------	--------



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

-Der montierte Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.





Figure 27: Misc.




Damage 1: Equipment: Tirefit filler - Due - Replace




Damage 2: Vehicle glazing: Rear window - Scratch(es) - Loss in value



Damage 2: Vehicle glazing: Rear window - Scratch(es) - Loss in value



Damage 3: Roof: Roof - dent(s) - Smart repair



Damage 3: Roof: Roof - dent(s) - Smart repair



Damage 3: Roof: Roof - dent(s) - Smart repair



Damage 4: Instrument panel: Indicator light (Motorkontrolle) - on - Perform diagnosis



Damage 5: 2nd wheel set: 1 alloy rim (Wurde bearbeitet, verschürt) - Unprofessionally repaired - Replace



Damage 5: 2nd wheel set: 1 alloy rim (Wurde bearbeitet, verschürt) - Unprofessionally repaired - Replace



Damage 5: 2nd wheel set: 1 alloy rim (Wurde bearbeitet, verschürft) - Unprofessionally repaired - Replace



Damage 5: 2nd wheel set: 1 alloy rim (Wurde bearbeitet, verschürft) - Unprofessionally repaired - Replace



Damage 5: 2nd wheel set: 1 alloy rim (Wurde bearbeitet, verschürft) - Unprofessionally repaired - Replace



Damage 6: 2nd wheel set: 1 alloy rim (Wurde bearbeitet) - Unprofessionally repaired - Replace




Damage 6: 2nd wheel set: 1 alloy rim (Wurde bearbeitet) - Unprofessionally repaired - Replace




Damage 6: 2nd wheel set: 1 alloy rim (Wurde bearbeitet) - Unprofessionally repaired - Replace



Damage 7: Side panel - rear left side: Side panel - Scratch(es) - Repair and paint



Damage 7: Side panel - rear left side: Side panel - Scratch(es) - Repair and paint



Damage 8: Side panel - rear right side: Side panel - Scratch(es) - Repair and paint



Damage 8: Side panel - rear right side: Side panel - Scratch(es) - Repair and paint




Damage 9: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 9: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage 9: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage 10: Boot lid / rear door: Boot lid (mit Entkleben) - Dent / paintcoat damage - Repair and paint



Damage 10: Boot lid / rear door: Boot lid (mit Entkleben) - Dent / paintcoat damage - Repair and paint



Damage 10: Boot lid / rear door: Boot lid (mit Entkleben) - Dent / paintcoat damage - Repair and paint



Damage 10: Boot lid / rear door: Boot lid (mit Entkleben) - Dent / paintcoat damage - Repair and paint



Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction



Repainting 1: Door - front right side



Door - front right side: 226 µm



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VZT8GP9M1018003
Hersteller / Modell: OPEL OPEL Insignia Sports Tourer 2.0 Diesel Aut. Business Elegance

Datum	KM-Stand	Beschreibung
16.06.2026	138.305	HU + AU; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
23.02.2026	138.298	Reparatur Sonstiges; Spannrolle ern; Systemtest/Eigendiagnose; Wartung Sonstiges; Zahnriemen/Steuerkett ern
06.01.2026	131.389	Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne
21.10.2025	124.489	Systemtest/Eigendiagnose
16.10.2025	124.200	Systemtest/Eigendiagnose
23.05.2025	111.969	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
04.04.2025	107.706	Ladeluftschlauch ern; Systemtest/Eigendiagnose
07.03.2025	101.035	Bremsinspektion vo + hi; Bremse Sonstiges; Bremsscheiben + Klötze v; Bremsscheiben hinten
10.12.2024	101.035	Batterie ern
31.05.2024	85.062	HU + AU; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
05.07.2023	60.193	Bremsinspektion vo + hi; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsklötze vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
20.06.2022	29.848	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges