



Expertise

Protocol number: 46417159
Order No. / Reference: 26583899
Inspection date: 9 Jul 2026

Manufacturer: Opel

Model: Movano 2.3 D (CDTI) L2H2 DPF 2WD VA

VIN: W0VMRY60XKB169503



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Movano 2.3 D (CDTI) L2H2 DPF 2WD VA	
Vehicle Identification number	W0VMRY60XKB169503
Mileage (Read)	89,211 km
First registration	20 Mar 2019
Number of holders	1
Next periodical technical inspection	03/2027
(Report on hand)	
Power / Engine displacement	96 kw / 2,299 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Brilliant Silber Metallic
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	36,329 km
Last service on / at	03/2026 at 85,045 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FG026266
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / AAZ 01311		
Emission standard	EURO6;Y;PI/CI; N1 III, N2	fine dust sticker	
Permitted total weight	3,300 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/65 R16 110T	Winter tyres on Steel rim with wheel cover	Goodyear	5mm / 5mm
2)	225/65 R16 110T	Winter tyres on Steel rim with wheel cover	Goodyear	8mm / 8mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/65 R16 112R	Summer tyres on Steel	Michelin	7mm / 7mm
2)	225/65 R16 112R	Summer tyres on Steel	Michelin	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	225/65 R16 112R C	Summer tyres on Steel	Michelin	7 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment above the windshield
- Driver's side airbag
- Tachometer
- Vehicle key (3-button) for selective door unlocking
- Transmission: 6-speed transmission
- Headrests (3) height adjustable
- Cargo area lighting
- Particulate filter: Soot particle filter for diesel engines with SCR
- Wheels: Steel wheels 6.5 J x 16
- Bumper without integrated step
- Doors: Sheet metal insert without window, driver's side
- Anchoring points in the cargo area
- Immobiliser
- Central locking with remote control
- ABS electronic
- Electrically adjustable and heated exterior mirrors
- ESP, Electronic Stability Program
- Electric front windows
- Seat belts: 3-point safety belts in the front
- Fuel tank 80 l
- Steering column, height adjustable
- Pollen filter
- Upholstery - Fabric
- Power steering
- Blind spot mirror in passenger-side sun visor
- Doors: Sliding door, passenger side, without window
- Lashing eyes on the loading platform
- Thermal insulation glazing, green tinted

Extra equipment

- Extendable step
- Bott installations
- External start system
- Heated rear window
- Paint finish: Two-coat metallic
- Package: Light 1 (Automatic low beam - Rain sensor - Fog lights)
- Radio CD 16 BT USB (Stereo CD radio, MP3-compatible - Bluetooth interface - 2 x 15 watts - Aux-In with USB connection and jack plug)
- Seat: Comfort driver's seat (with lumbar support, armrest, 4-way adjustable)
- Install voltage converter and GPS
- Partition wall, closed with fixed window
- On-board computer
- Rear gullwing doors, 180° opening angle, glazed
- Rubber mats at the front
- Air conditioning with pollen filter
- Package: Cool & Sound (Air conditioning with pollen filter - Stereo CD radio CD 16 BT, Bluetooth interface, Aux-In and USB port and jack plug)
- Wheels: Spare wheel, steel
- Seat cover for driver's seat
- Seat: Comfort single seat, front passenger (with lumbar support, 4-way adjustable, with armrest)
- Seat heating for driver and front passenger individual seats
- Auxiliary heater (water heater) with radio remote control (air outlet via vents in the dashboard area)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Sliding door, right	Sliding door - dent(s) - Smart repair
2	Rear of vehicle	Foot plate (Korrosion) - Paint defect - Loss in value
3	Door - front left side	Door - Dent / paintcoat damage - Repair and paint
4	Sill - left side	Sill - Dent / paintcoat damage - Repair and paint

Missing parts

Description

Heating system - Remote control auxiliary heating

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Side - left, Provided by user / customer, from 8 Feb 2023	4.029,59 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.



Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Der montierte Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.





Figure 36: Misc.



Figure 37: Misc.



Damage 1: Sliding door, right: Sliding door - dent(s) - Smart repair



Damage 1: Sliding door, right: Sliding door - dent(s) - Smart repair



Damage 2: Rear of vehicle: Foot plate (Korrosion) - Paint defect - Loss in value



Damage 2: Rear of vehicle: Foot plate (Korrosion) - Paint defect - Loss in value



Damage 2: Rear of vehicle: Foot plate (Korrosion) - Paint defect - Loss in value



Damage 3: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 3: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 3: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 4: Sill - left side: Sill - Dent / paintcoat damage - Repair and paint



Damage 4: Sill - left side: Sill - Dent / paintcoat damage - Repair and paint



Damage 4: Sill - left side: Sill - Dent / paintcoat damage - Repair and paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VMRY60XKB169503

Hersteller / Modell: OPEL OPEL Movano 2.3 D (CDTI) L2H2 DPF 2WD VA

Datum	KM-Stand	Beschreibung
12.03.2026	85.045	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
06.01.2026	82.601	Batterie ern
08.09.2025	80.047	Bremsklötze hinten; Bremsscheiben + Klötze h; Bremsscheiben hinten; Lichtmaschine ern/inst; Reparatur Sonstiges; Systemtest/Eigendiagnose
27.03.2025	72.749	AU
18.04.2024	62.118	Bremsscheiben + Klötze v; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
23.03.2023	47.412	AU
03.05.2022	37.879	Bremsklötze vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges