



Expertise

Protocol number: 46494078
Order No. / Reference: 26488445
Inspection date: 10 Jul 2026

Manufacturer: Opel	Model: Astra 1.2 Turbo Start/Stop Sports Tourer Edition
VIN: W0VBD8ESXM8022204	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Astra 1.2 Turbo Start/Stop Sports Tourer Edition	
Vehicle Identification number	W0VBD8ESXM8022204
Mileage (Read)	159,271 km
First registration	27 Aug 2021
Number of holders	1
Power / Engine displacement	96 kw / 1,199 ccm
Fuel type / Cylinder	Petrol / 3
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Argonsilber Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black



Vehicle details			
Maintenance booklet / proof	digital evidence / incomplete	Next maintenance in	29 %
Last service on / at	11/2025 at 140,871 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA238879
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / AKX 00141		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,870 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Kumho	6mm / 6mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Dunlop	7mm / 7mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91V	Summer tyres on Light alloy	Continental	4mm / 4mm
2)	205/55 R16 91V	Summer tyres on Light alloy	Continental	5mm / 5mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	115/70 R16 92M	Summer tyres on Steel	Continental	6 mm
Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.				

Equipment

Standard equipment

- 2 ignition keys
- Airbag for driver and passenger side
- Airbag: Head airbags, 1st and 2nd row (outer seats)
- Anti-lock braking system (ABS)
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- third brake light
- black roof rails
- Tachometer
- Electric windows front and rear
- Transmission: 6-speed manual transmission
- rear window wiper
- Instruments, black, with high-gloss chrome rings, 3.5" driver information display
- Rear headrests (3)
- Cargo area cover
- Steering wheel: Leather steering wheel
- Lighting equipment
- Otto particulate filter
- Upholstery: Cloth
- Radio: Multimedia radio with 7" touchscreen color display
- Wheels: Design wheels, 6.5 J x 16 with tires 205/55 R16
- Power steering
- Luggage compartment safety net
- Seats: Comfort seats, front
- 12V power outlet in the center console
- Pre-installation for child seat mounting system "ISOFIX"
- Heat-insulating glazing, green tinted, and windshield

Extra equipment

- Detachable trailer hitch (including trailer stability program TSP)
- Fog light
- Radio: Multimedia Navi (Multimedia Radio, 7" touchscreen color display with USB port, hands-free system, voice control, Bluetooth audio streaming, smartphone integration via Apple CarPlay and Android Auto - Navigation system with integrated memory - Road map for over 30 European countries - Map display in 2D and 3D - Dynamic route guidance via map and/or arrow display and voice prompts - Dynamic destination guidance via enhanced Traffic Message Channel (TMCpro))

- Storage compartments
- Airbag: Chest-pelvis side airbag for driver and front passenger side
- Automatic activation of the hazard warning lights
- Hill Start Assist
- On-board computer
- Roof design line, above in black
- Decorative trim strips Antelao Sand/Polar Silver
- Electronic Stability Program Plus (ESP Plus)
- Speed controller with limiter
- Back window, heater
- Interior lighting, front and rear
- Air conditioning
- trunk light
- Front headrests
- LED daytime running lights
- Steering column, height and reach adjustable
- Sliding center armrest, front
- Pedals: Disengaging safety pedals
- Radio: Digital radio reception DAB/DAB+/DMB-R
- Tire pressure monitoring system
- Rear seat backrest folds forward in a 60:40 split
- Seat belts: Three-point seat belts in all seats
- Visibility equipment
- Start/Stop System
- Traction Control (TC) Plus
- Immobiliser
- Central locking with remote control and interior switches

- Paint finish: Metallic
- LED headlights
- Parkpilot, front and rear parking aid (with acoustic warning signal when parking forwards and backwards)
- Wheels: Emergency spare wheel, steel 4Jx16
- Seats: Ergonomic active seat (certified by the Campaign for Healthy Backs (AGR) Driver's seat: - Length, height and tilt adjustable - Electropneumatic lumbar support adjustable in height and length - Extendable thigh support - Pocket on the back of the front seats, driver and front passenger)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	2nd wheel set	1 wheel cover - Scratched - Replace
2	2nd wheel set	1 wheel cover - Scratched - Replace
3	2nd wheel set	1 wheel cover - Scratched - Replace
4	Steering system	Steering wheel (Knöpfe abgenutzt) - Paint defect - Loss in value
5	Door - front left side	Door handle - inside - Paint defect - Loss in value
6	Gearbox	Gear knob - Abrasion - Loss in value
7	Side panel - rear left side	Sill - Dent / paintcoat damage - Smart repair
8	Side panel - rear right side	Sill - Scratch(es) - Smart repair
9	Rear bumper	Rear bumper - Scratch(es) - Smart repair
10	Seat - rear	Seat upholstery - 3 seater bench - Soiled - Clean
11	Body	Body (Gewaltschaden Seite rechts) - Scratch(es) - Paint

Missing parts

Description

Interior - Luggage net

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 2 Mar 2022	910,19 €
2	Rear, Side - left, Provided by user / customer, from 17 Jun 2024	1.400,11 €
3	Side - left, Provided by user / customer, from 25 Feb 2022	1.774,83 €



Repainting

No. Repainting

- 1 Roof, Professionally carried out, Invoice of repair done Non-existent
- 2 Roof rail - left side, Professionally carried out, Invoice of repair done Non-existent
- 3 Roof rail - right side, Professionally carried out, Invoice of repair done Non-existent
- 4 Mudguard - left side, Professionally carried out, Invoice of repair done Non-existent
- 5 Mudguard - right side, Professionally carried out, Invoice of repair done Non-existent
- 6 Bonnet, Professionally carried out, Invoice of repair done Non-existent
- 7 Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent
- 8 Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent
- 9 Door - rear left side, Professionally carried out, Invoice of repair done Non-existent
- 10 Door - rear right side, Professionally carried out, Invoice of repair done Non-existent
- 11 Door - front left side, Professionally carried out, Invoice of repair done Non-existent
- 12 Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Roof	261 µm	Roof rail - left side	270 µm
Roof rail - right side	348 µm	Mudguard - left side	280 µm
Mudguard - right side	217 µm	Bonnet	222 µm
Side panel - rear left side	289 µm	Side panel - rear right side	236 µm
Door - rear left side	278 µm	Door - rear right side	230 µm
Door - front left side	300 µm	Door - front right side	234 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.
- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: Cargo area




Figure 12: VIN



Figure 13: Mounted tyres



Figure 14: Documents



Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Documents



Figure 19: Additional tyres




Figure 20: Navigation



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Damage 1: 2nd wheel set: 1 wheel cover - Scratched - Replace



Damage 1: 2nd wheel set: 1 wheel cover - Scratched - Replace



Damage 1: 2nd wheel set: 1 wheel cover - Scratched - Replace



Damage 2: 2nd wheel set: 1 wheel cover - Scratched - Replace



Damage 2: 2nd wheel set: 1 wheel cover - Scratched - Replace



Damage 3: 2nd wheel set: 1 wheel cover - Scratched - Replace



Damage 3: 2nd wheel set: 1 wheel cover - Scratched - Replace




Damage 3: 2nd wheel set: 1 wheel cover - Scratched - Replace



Damage 4: Steering system: Steering wheel (Knöpfe abgenutzt) - Paint defect - Loss in value




Damage 4: Steering system: Steering wheel (Knöpfe abgenutzt) - Paint defect - Loss in value



Damage 4: Steering system: Steering wheel (Knöpfe abgenutzt) - Paint defect - Loss in value




Damage 5: Door - front left side: Door handle - inside - Paint defect - Loss in value



Damage 5: Door - front left side: Door handle - inside - Paint defect - Loss in value



Damage 5: Door - front left side: Door handle - inside - Paint defect - Loss in value



Damage 6: Gearbox: Gear knob - Abrasion - Loss in value



Damage 6: Gearbox: Gear knob - Abrasion - Loss in value




Damage 7: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 7: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 7: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 8: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 8: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 8: Side panel - rear right side: Sill - Scratch(es) - Smart repair




Damage 9: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 9: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 9: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 9: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 9: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 9: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 10: Seat - rear: Seat upholstery - 3 seater bench - Soiled - Clean



Damage 10: Seat - rear: Seat upholstery - 3 seater bench - Soiled - Clean



Damage 10: Seat - rear: Seat upholstery - 3 seater bench - Soiled - Clean



Damage 10: Seat - rear: Seat upholstery - 3 seater bench - Soiled - Clean



Damage 11: Body: Body (Gewaltschaden Seite rechts) - Scratch(es) - Paint



Damage 11: Body: Body (Gewaltschaden Seite rechts) - Scratch(es) - Paint




Damage 11: Body: Body (Gewaltschaden Seite rechts) - Scratch(es) - Paint



Damage 11: Body: Body (Gewaltschaden Seite rechts) - Scratch(es) - Paint



Damage 11: Body: Body (Gewaltschaden Seite rechts) - Scratch(es) - Paint



Damage 11: Body: Body (Gewaltschaden Seite rechts) - Scratch(es) - Paint



Repainting 1: Roof



Repainting 1: Roof



Repainting 2: Roof rail - left side



Repainting 2: Roof rail - left side



Repainting 3: Roof rail - right side



Repainting 3: Roof rail - right side



Repainting 4: Mudguard - left side



Repainting 4: Mudguard - left side



Repainting 5: Mudguard - right side



Repainting 5: Mudguard - right side



Repainting 6: Bonnet



Repainting 6: Bonnet



Repainting 7: Side panel - rear left side



Repainting 7: Side panel - rear left side



Repainting 8: Side panel - rear right side



Repainting 8: Side panel - rear right side



Repainting 9: Door - rear left side



Repainting 9: Door - rear left side



Repainting 10: Door - rear right side



Repainting 10: Door - rear right side



Repainting 11: Door - front left side



Repainting 11: Door - front left side



Repainting 12: Door - front right side



Repainting 12: Door - front right side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VBD8ESXM8022204

Hersteller / Modell: OPEL OPEL Astra 1.2 Turbo Start/Stop Sports Tourer Edition

Datum	KM-Stand	Beschreibung
25.11.2025	140.871	Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne; Keilrippenriemen; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
19.02.2025	110.979	Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Reparatur Sonstiges; Systemtest/Eigendiagnose; Turbolader ern; Wartung Sonstiges; Zündkerzen ern
08.10.2024	98.380	AU
30.04.2024	84.417	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
27.12.2023	72.760	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben vorne
24.05.2023	53.256	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
15.08.2022	27.665	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges