



Expertise

Protocol number: 46478901
Order No. / Reference: 26565413
Inspection date: 13 Jul 2026

Manufacturer: Ford

Model: Galaxy 2.5 Duratec FHEV TITANIUM

VIN: WF0KXXWPCHPC18307



Vehicle details

Manufacturer / Type / Model / Equipment

Ford Galaxy 2.5 Duratec FHEV TITANIUM

Vehicle Identification number WF0KXXWPCHPC18307

Mileage (Read) 121,279 km

First registration 29 Mar 2023

Number of holders 1

Power / Engine displacement 110 kw / 2,488 ccm

Fuel type / Cylinder Hybrid Petrol / E / 4

Gearbox / Number of gears Direct drive / 1

Type of drive Front drive

Type of vehicle Station wagon

Colour / colour code Agate Black Metallic

Doors / Seats 5 / 7

Upholstery type Cloth

Colour of upholstery Anthracite-Black



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	33 %
Last service on / at	03/2026 at 113,468 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP513284
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BVI 00109		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,595 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R17 103V	Winter tyres on Light alloy	Continental	6mm / 6mm
2)	235/55 R17 103V	Winter tyres on Light alloy	Continental	6mm / 6mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R17 103V	Summer tyres on Light alloy	Continental	3mm / 3mm
2)	235/55 R17 103V	Summer tyres on Light alloy	Continental	4mm / 4mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 01/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Airbag: Passenger airbag deactivation
- Anti-lock braking system (ABS)
- Attachment points for safety partition grilles
- Tires: 7.5 J x 17 alloy wheels (4) with 235/55 R 17 tires
- Hill start assist
- Roof rails "aluminum look"
- Lane keeping assist including lane keeping assist and driver fatigue warning
- Ford KeyFree system
- FordPass Connect including eCall, live traffic information and Wi-Fi hotspot
- Back window, heater
- Interior lighting with delay circuit
- Isofix bracket
- Air conditioning with automatic temperature control
- Steering wheel: Steering column, adjustable in height and reach
- Front center console with padded armrest
- Ford navigation system including Ford SYNC 3 with AppLink, touchscreen, DAB/DAB+ and FordPass Connect
- Package: Winter
- Upholstery: Cloth
- Tire Pressure Monitoring System (TPMS)
- Headlight assistant with day/night sensor
- Electromechanical power steering
- Seats: 3rd row of seats with 2 individual seats (FoldFlatSystem)
- Seats: Comfort seats, front
- Seats: Trays on the front seat backrests
- Power outlet: 230-volt connection (150 watts)
- Front bumper painted in body color
- Velour carpet floor mats
- Lashing eyes in the luggage compartment
- thermal insulation glazing
- Cigarette lighter
- Ambient lighting at the front with LED technology
- Exterior mirrors painted in body color, electrically adjustable, heated and foldable
- Tires: Tire repair kit
- third brake light
- Tachometer
- Electric windows front and rear
- Electronic parking brake
- Ford Power Start function
- Cruise control system with intelligent speed limiter
- Transmission: CVT automatic
- rear window wiper
- Intelligent security system
- Electric child safety lock
- Front headrests, 4-way height and tilt adjustable
- Steering wheel: Multifunction leather steering wheel
- Reading lights front and rear
- MyKey key system (individually programmable second key)
- Fog lights with LED technology
- Emergency brake light
- Front and rear parking pilot system
- Rain sensor
- Headlight dipped beam with switch-off delay including "greeting function"
- Seats: 2nd row of seats with 3 individual seats (FoldFlat System)
- Seats: Driver and passenger seats, 4-way manually adjustable
- Power outlet: 12-volt connection in the luggage compartment and in the center console
- LED daytime running lights
- Traffic sign recognition system
- Electronic immobilizer
- Central locking with remote control



Extra equipment

- Detachable towbar (including ESP trailer stabilization)
- Adaptive cruise control with pre-collision assist and pedestrian detection (distance display and distance warning, forward alert system (FA) and active emergency braking assist - intelligent speed limiter - traffic jam assist with stop&go function)
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Safety partition net behind the 2nd row of seats for the luggage compartment
- Seats: Ford ergonomic seat (driver and front passenger seat adjustable in 18 ways: - length, height and tilt of the seat - extendable thigh support - adjustable backrest - lumbar support electrically adjustable in 4 ways - fabric seat material Calder/Omni)
- Sunshade blinds integrated into the rear doors
- Tires: 7.5 J x 17 alloy wheels (4) with 235/55 R 17 tires (in 10x2-spoke design)
- Paint finish: Metallic
- Rear level control, automatic
- Package: Business III (Automatic) (Sony Navigation incl. Ford SYNC 3, AppLink, Touchscreen, Voice Control, Radio/CD Player, MP3-compatible, 2 USB ports, 390-watt premium sound system, 12 speakers, steering wheel remote control, Bluetooth hands-free system, FordPass Connect, eCall, DAB/DAB+, Adaptive LED headlights with glare-free high beam, ACC, Traffic Jam Assist, Pre-Collision Assist, Forward Collision Warning, Emergency Brake Assist, Front and Rear View Camera, Blind Spot Assist, Cross Traffic Alert, Dynamic Distance Control, Power Tailgate with Sensors, Ford Key Free System, Park Assist)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Electrical system	Power socket (12V) - Broken / torn - Loss in value
3	Steering system	Steering wheel - Abrasion - Smart repair
4	Door - front left side	Door - dent(s) - Smooth repair work
5	Door - rear right side	Door - dent(s) - Smooth repair work
6	Interior	Sun visor - right side - Loose - Replace
7	Mudguard - left side	Mudguard - left side - Scratch(es) - Smart repair
8	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
9	Interior	Interior (Flecken) - Soiled - Clean
10	Door - rear left side	Door - Scratch(es) - Paint
11	Bonnet	Bonnet (Sandstrahleffekt) - Stone chips - Paint
12	Rear bumper	Rear bumper - Scratched - Paint
13	Front bumper	Front bumper (Steinschlag) - Scratch(es) - Paint
14	Boot lid / rear door	Boot lid (+ Leiste unten) - Scratched - Paint



Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Interior	Cargo area floor (Laderaum) - Scratch(es) - No deduction
3	Side panel - rear left side	Side panel - dent(s) - Smooth repair work

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Interior - Boot cover / roller cover

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side - left, Provided by user / customer, from 23 Dec 2023	1.707,09 €

Repainting

No. Repainting

1 Door - rear left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Door - rear left side 161 µm |

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Additional tyres



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Damage 2: Electrical system: Power socket (12V) - Broken / torn - Loss in value



Damage 2: Electrical system: Power socket (12V) - Broken / torn - Loss in value




Damage 3: Steering system: Steering wheel - Abrasion - Smart repair




Damage 3: Steering system: Steering wheel - Abrasion - Smart repair




Damage 4: Door - front left side: Door - dent(s) - Smooth repair work



Damage 4: Door - front left side: Door - dent(s) - Smooth repair work




Damage 5: Door - rear right side: Door - dent(s) - Smooth repair work




Damage 5: Door - rear right side: Door - dent(s) - Smooth repair work




Damage 6: Interior: Sun visor - right side - Loose - Replace




Damage 6: Interior: Sun visor - right side - Loose - Replace




Damage 6: Interior: Sun visor - right side - Loose - Replace



Damage 7: Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair



Damage 7: Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair



Damage 8: Side panel - rear right side: Side panel - Scratch(es) - Smart repair




Damage 8: Side panel - rear right side: Side panel - Scratch(es) - Smart repair




Damage 9: Interior: Interior (Flecken) - Soiled - Clean



Damage 9: Interior: Interior (Flecken) - Soiled - Clean



Damage 9: Interior: Interior (Flecken) - Soiled - Clean




Damage 9: Interior: Interior (Flecken) - Soiled - Clean



Damage 10: Door - rear left side: Door - Scratch(es) - Paint



Damage 10: Door - rear left side: Door - Scratch(es) - Paint



Damage 10: Door - rear left side: Door - Scratch(es) - Paint



Damage 10: Door - rear left side: Door - Scratch(es) - Paint



Damage 10: Door - rear left side: Door - Scratch(es) - Paint



Damage 10: Door - rear left side: Door - Scratch(es) - Paint



Damage 11: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint




Damage 11: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



Damage 11: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint




Damage 11: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



Damage 11: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



Damage 11: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



Damage 12: Rear bumper: Rear bumper - Scratched - Paint



Damage 12: Rear bumper: Rear bumper - Scratched - Paint




Damage 12: Rear bumper: Rear bumper - Scratched - Paint




Damage 12: Rear bumper: Rear bumper - Scratched - Paint




Damage 13: Front bumper: Front bumper (Steinschlag) - Scratch(es) - Paint



Damage 13: Front bumper: Front bumper (Steinschlag) - Scratch(es) - Paint



Damage 13: Front bumper: Front bumper (Steinschlag) - Scratch(es) - Paint



Damage 13: Front bumper: Front bumper (Steinschlag) - Scratch(es) - Paint



Damage 13: Front bumper: Front bumper (Steinschlag) - Scratch(es) - Paint



Damage 13: Front bumper: Front bumper (Steinschlag) - Scratch(es) - Paint



Damage 13: Front bumper: Front bumper (Steinschlag) - Scratch(es) - Paint



Damage 13: Front bumper: Front bumper (Steinschlag) - Scratch(es) - Paint



Damage 13: Front bumper: Front bumper (Steinschlag) - Scratch(es) - Paint



Damage 14: Boot lid / rear door: Boot lid (+ Leiste unten) - Scratched - Paint




Damage 14: Boot lid / rear door: Boot lid (+ Leiste unten) - Scratched - Paint



Damage 14: Boot lid / rear door: Boot lid (+ Leiste unten) - Scratched - Paint



Damage 14: Boot lid / rear door: Boot lid (+ Leiste unten) - Scratched - Paint



Damage 14: Boot lid / rear door: Boot lid (+ Leiste unten) - Scratched - Paint



Wear and tear 3: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Wear and tear 3: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Repainting 1: Door - rear left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0KXXWPCHPC18307
Hersteller / Modell: FORD FORD Galaxy 2.5 Duratec FHEV TITANIUM

Datum	KM-Stand	Beschreibung
10.03.2026	113.468	AU; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
12.09.2025	98.088	Bremsflüssigkeit; Bremsflüssigkeit ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern
06.05.2025	87.669	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne
07.03.2025	81.434	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
02.12.2024	69.629	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
04.06.2024	50.423	Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern
05.01.2024	37.314	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
27.09.2023	25.522	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges