



Expertise

Protocol number: 46461857
Order No. / Reference: 26699334
Inspection date: 9 Jul 2026

Manufacturer: Ford

Model: Mondeo Turnier 2.0 EcoBlue Trend

VIN: WF0FXXWPCFNY69870



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Mondeo Turnier 2.0 EcoBlue Trend	
Vehicle Identification number	WF0FXXWPCFNY69870
Mileage (Read)	115,715 km
First registration	31 May 2022
Number of holders	1
Next periodical technical inspection	06/2027
(Report on hand)	
Power / Engine displacement	110 kw / 1,995 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Blazer Blau
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Black



Vehicle details			
Maintenance booklet / proof	Available / complete	Next maintenance in	30,000 km
Last service on / at	06/2026 at 115,709 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GH430000
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BJB 00106		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,330 kg	Empty weight	

Tyres			
Mounted tyres			
#	Tyre size	Type of tyre	Tread depth
1)	215/60 R16 99V	Summer tyres on Light alloy	6mm / 6mm
2)	215/60 R16 99V	Summer tyres on Light alloy	3mm / 3mm
Additional tyres			
#	Tyre size	Type of tyre	Tread depth
1)	215/60 R16 99H	Winter tyres on Steel rim with wheel cover	5mm / 5mm
2)	215/60 R16 99H	Winter tyres on Steel rim with wheel cover	3mm / 3mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Activated carbon filter
- Anti-lock braking system (ABS) with electronic brake force distribution (EBD)
- Attachment points for safety partition grilles
- Tires: 6.5 J x 16 alloy wheels (4) with 215/60 R 16 tires
- Tires: Tire pressure monitoring system (TPMS)
- third brake light
- Roof rails, black
- Tachometer
- Driver information system - 10.7 cm color display
- Electric windows front and rear
- High Beam Assist
- Ford Easy Fuel
- FordPass Connect including eCall and Wi-Fi hotspot
- Luggage compartment lighting
- Transmission: 6-speed manual transmission
- rear window wiper
- Interior mirror automatically dimming
- Isofix bracket
- Air conditioning with automatic temperature control
- Front headrests, 4-way height and tilt adjustable
- Leather gear knob
- Adjustable steering column
- Front center console with padded armrests
- Fog light
- Upholstery: Cloth
- Radio equipment: Ford SYNC 3 audio system with AppLink and touchscreen and digital radio reception DAB/DAB+
- Headlight dipped beam with switch-off delay including "greeting function"
- Seats: Driver and passenger seats, 4-way manually adjustable
- Start-stop system
- 12-volt socket in the front interior
- Daytime running light
- Traffic sign recognition system
- Warning system for unfastened seat belts in the front and second row of seats
- Cigarette lighter
- Ambient lighting in the front, including door storage compartment, front door handle and footwell lighting.
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated
- Tires: Tire repair kit
- Hill start assist
- headliner, light
- Diesel particulate filter (DPF)
- Electronic Safety and Stability Program (ESP)
- Lane keeping assist including lane keeping assist and driver fatigue warning
- Electronic parking brake
- Ford Power Start function
- luggage compartment cover
- Cruise control system with intelligent speed limiter
- Back window, heater
- Interior lighting with delay circuit
- Intelligent security system
- Electric child safety lock
- Rear headrests (3), height adjustable
- Paint finish: Solid
- Steering wheel: Multifunction leather steering wheel
- Reading lights front and rear
- MyKey key system (individually programmable second key)
- Emergency brake light
- Pre-Collision Assist
- LED taillights
- Rear seat backrest, foldable, 60:40 split
- Windscreen wipers with rain sensor
- Headlight assistant with day/night sensor
- Electromechanical speed-dependent power steering
- Seats: Map pocket on the back of the front passenger seat
- Seats: Map pocket on the driver's seat backrest
- 12-volt power outlet in the luggage compartment
- Front bumper painted in body color
- Carpet floor mats front and rear
- Lashing eyes in the luggage compartment floor
- Immobiliser
- Central locking



Extra equipment

- Package: Business 1 (Exterior mirrors, electrically adjustable and heated, additionally electrically folding and with ambient lighting - Park Assist with parallel and perpendicular parking function incl. Park Pilot system - Ford Navigation system incl. Ford SYNC 3 with AppLink, 8" touchscreen (20.3 cm) with DAB/DAB+ - Audible and visual route guidance, Live Traffic in conjunction with FordPass - 8 speakers - Steering wheel remote control - Bluetooth hands-free system and audio streaming - 2 USB ports - Voice control for audio and telephone - LED design daytime running lights - Rearview camera)
- Adaptive cruise control with collision warning system (including distance display and distance warning and pre-collision assist with speed limiter)
- Detachable towbar (ESP trailer stabilization - continuous power supply - switched power supply - hill start assist)
- Safety partition net behind the 2nd row of seats for the luggage compartment

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Boot lining - Malposition - Un- / install
2	Sill - right side	Sill - Scratch(es) - Smart repair
3	Sill - left side	Sill - Scratch(es) - Smart repair
4	Door - rear right side	Door edge - Scratch(es) - Smart repair
5	Body	Body - Scratch(es) - Smart repair
6	Door - front left side	Door - Dent / paintcoat damage - Smart repair
7	Mudguard - left side	Mudguard - left side - Scratched - Paint
8	Rear bumper	Rear bumper - Scratched - Paint
9	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Repair and paint
10	Door - rear right side	Door - Scratch(es) - Paint
11	Front bumper	Front bumper - Scratched - Paint
12	Bonnet	Bonnet - Dent / paintcoat damage - Paint

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction
3	Body	Underbody panelling - Scratched - No deduction
4	Engine	Engine cowling - lower - Damaged - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Missing parts

Description

Equipment - Tirefit filler

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel




Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.




Figure 35: Misc.




Figure 36: Misc.



Figure 37: Misc.




Figure 38: Misc.




Figure 39: Misc.



Figure 40: Misc.



Figure 41: Misc.



Figure 42: Misc.



Figure 43: Misc.



Figure 44: Misc.




Figure 45: Misc.



Figure 46: Misc.



Figure 47: Misc.





Figure 48: Misc.




Figure 49: Misc.



Damage 1: Trim / covers: Boot lining - Malposition - Un- / install



Damage 1: Trim / covers: Boot lining - Malposition - Un- / install



Damage 2: Sill - right side: Sill - Scratch(es) - Smart repair




Damage 2: Sill - right side: Sill - Scratch(es) - Smart repair




Damage 3: Sill - left side: Sill - Scratch(es) - Smart repair




Damage 3: Sill - left side: Sill - Scratch(es) - Smart repair




Damage 4: Door - rear right side: Door edge - Scratch(es) - Smart repair




Damage 4: Door - rear right side: Door edge - Scratch(es) - Smart repair




Damage 5: Body: Body - Scratch(es) - Smart repair




Damage 5: Body: Body - Scratch(es) - Smart repair




Damage 5: Body: Body - Scratch(es) - Smart repair




Damage 5: Body: Body - Scratch(es) - Smart repair




Damage 5: Body: Body - Scratch(es) - Smart repair




Damage 5: Body: Body - Scratch(es) - Smart repair



Damage 5: Body: Body - Scratch(es) - Smart repair



Damage 6: Door - front left side: Door - Dent / paintcoat damage - Smart repair




Damage 6: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Damage 7: Mudguard - left side: Mudguard - left side - Scratched - Paint



Damage 7: Mudguard - left side: Mudguard - left side - Scratched - Paint




Damage 7: Mudguard - left side: Mudguard - left side - Scratched - Paint



Damage 7: Mudguard - left side: Mudguard - left side - Scratched - Paint



Damage 8: Rear bumper: Rear bumper - Scratched - Paint




Damage 8: Rear bumper: Rear bumper - Scratched - Paint



Damage 8: Rear bumper: Rear bumper - Scratched - Paint



Damage 8: Rear bumper: Rear bumper - Scratched - Paint




Damage 9: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint




Damage 9: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 9: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 10: Door - rear right side: Door - Scratch(es) - Paint



Damage 10: Door - rear right side: Door - Scratch(es) - Paint



Damage 11: Front bumper: Front bumper - Scratched - Paint




Damage 11: Front bumper: Front bumper - Scratched - Paint



Damage 11: Front bumper: Front bumper - Scratched - Paint



Damage 11: Front bumper: Front bumper - Scratched - Paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Paint




Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Paint



Wear and tear 2: Trim / covers: Boot lid - interior trim - Scratch(es) - No deduction



Wear and tear 2: Trim / covers: Boot lid - interior trim - Scratch(es) - No deduction



Wear and tear 3: Body: Underbody panelling - Scratched - No deduction




Wear and tear 3: Body: Underbody panelling - Scratched - No deduction




Wear and tear 3: Body: Underbody panelling - Scratched - No deduction




Wear and tear 4: Engine: Engine cowling - lower - Damaged - No deduction



Wear and tear 4: Engine: Engine cowling - lower - Damaged - No deduction



Wear and tear 4: Engine: Engine cowling - lower - Damaged - No deduction



Wear and tear 4: Engine: Engine cowling - lower - Damaged - No deduction



Missing part 1: Equipment: Tirefit filler - Missing - Perform