



Expertise

Protocol number: 46860871
Order No. / Reference: 26763492
Inspection date: 4 Aug 2026

Manufacturer: Opel

Model: Insignia Sports Tourer 1.5 Diesel Elegance

VIN: W0VZT8EN9N1019588



Vehicle details

Manufacturer / Type / Model / Equipment

Opel Insignia Sports Tourer 1.5 Diesel Elegance

Vehicle Identification number	W0VZT8EN9N1019588
Mileage (Read)	152,760 km
First registration	4 Aug 2022
Number of holders	1
Next periodical technical inspection	07/2027
(Report on hand)	

Fuel type	Diesel
Engine displacement / Cylinder	1,496 ccm / 3
Power	90 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Station wagon

Colour / colour code	Jade Weiß
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle with smoke odor	no
-------------------------	----



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	77 %
Last service on / at	05/2026 at 148,508 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ688365
Previous damage / Accident	None detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / AME 00281		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,175 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 94W	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	215/55 R17 94W	Summer tyres on Light alloy	Pirelli	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 07/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- Klimaautomatik

Standard equipment

- Storage compartments
- Airbag: Front airbags and side airbags, driver and front passenger
- Anti-lock braking system (ABS)
- Hill Start Assist
- third brake light
- Roof rails, silver anodized
- Diesel particulate filter
- Electronic brake force distribution (EBD)
- Driver information display, 3.5"
- Front collision warning system with pedestrian detection and automatic emergency braking
- Noise-reducing, laminated front side windows
- Transmission: 6-speed manual transmission
- rear window wiper
- Automatic climate control, two zones
- Rear headrests (3 pieces)
- LED headlights
- LED daytime running lights including LED indicators, front and LED taillights
- Center armrest, front
- Electric parking brake
- Upholstery: Billy fabric, black
- Radio: Digital radio reception DAB+
- Tire repair kit
- Wheels: 7.5 J x 17 alloy wheels in a 5 double-spoke design
- Seat belts: Three-point seat belts in all seats
- Visibility equipment
- Lane Keeping Assist
- Bumpers painted in body color
- Pre-installation for child seat mounting system "ISOFIX"
- Thermal insulation glazing, green tinted

Extra equipment

- Swiveling trailer hitch (including trailer stability program)
- Park & Go with digital reversing camera (digital reversing camera - reversing assistant - lane change assistant - blind spot warning in both exterior mirrors)

- Adaptive brake light
- Airbag: Front and rear outer head airbags
- Ambient lighting
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- Glasses compartment in the headliner
- Decorative strip hexagon
- Tachometer
- Electronic Stability Program (ESP Plus)
- Electric windows front and rear
- Pedestrian protection including active hood
- luggage compartment cover
- Speed controller
- Back window, heater
- Child safety lock in the rear doors, manual
- Front headrests
- Paint finish: Solid
- LED fog lights
- Steering column adjustable for height and reach
- Illuminated makeup mirrors in both sun visors
- Package: Innovations 1
- Parkpilot, front and rear parking aid
- Quickheat rapid heating system
- Radio: Multimedia Radio 7" Touchscreen Color Display
- Tire pressure gauge
- Rear seat backrest folds forward in a 60:40 split
- Power steering
- safety net
- Seats: Ergonomic active seat (AGR) driver
- Start/Stop System
- Traction Control (TC) Plus
- Immobiliser
- Central locking with remote control

- Package: Winter 1 (Heated seats, multi-stage, driver and front passenger - Heated leather steering wheel - Heated ThermoTec windshield)
- Radio: Multimedia Navi Pro with 8" color touchscreen display (voice control for audio, telephone and navigation, USB port, Bluetooth audio streaming, navigation system with SD card storage, connected navigation services, predictive navigation, online map updates, real-time traffic information, 8" driver information display, steering wheel controls, Apple CarPlay and Android Auto)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Floor mats - Broken / torn - Replace
2	Equipment	Tirefit filler - Expired - Replace
3	Side panel - rear left side	Elbow - dent(s) - Smooth repair work
4	Wheel / tyres	Tyre - rear right side - Damaged - Replace
5	Wheel / tyres	Alloy rim - rear right side - Scratched - Replace
6	Mudguard - left side	Mudguard - left side - dent(s) - Repair and paint
7	Sill - left side	Sill - Dent / paintcoat damage - Repair and paint

Repainting

No. Repainting

1	Roof, Roof rail - left side, Roof rail - right side, Boot lid / rear door, Side panel - rear right side, Door - front left side, Door - front right side, Professionally carried out, Invoice of repair done Non-existent
---	---

Paint coat thickness measurement

Roof	234 µm	Roof rail - left side	191 µm
Roof rail - right side	227 µm	Boot lid / rear door	219 µm
Side panel - rear right side	201 µm	Door - front left side	288 µm
Door - front right side	223 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.





Figure 36: Misc.




Figure 37: Misc.




Damage 1: Trim / covers: Floor mats - Broken / torn - Replace




Damage 1: Trim / covers: Floor mats - Broken / torn - Replace



Damage 2: Equipment: Tirefit filler - Expired - Replace



Damage 3: Side panel - rear left side: Elbow - dent(s) - Smooth repair work



Damage 3: Side panel - rear left side: Elbow - dent(s) - Smooth repair work



Damage 4: Wheel / tyres: Tyre - rear right side - Damaged - Replace



Damage 4: Wheel / tyres: Tyre - rear right side - Damaged - Replace



Damage 5: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 5: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 5: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 5: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 5: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace




Damage 5: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 6: Mudguard - left side: Mudguard - left side - dent(s) - Repair and paint



Damage 6: Mudguard - left side: Mudguard - left side - dent(s) - Repair and paint



Damage 6: Mudguard - left side: Mudguard - left side - dent(s) - Repair and paint



Damage 6: Mudguard - left side: Mudguard - left side - dent(s) - Repair and paint



Damage 7: Sill - left side: Sill - Dent / paintcoat damage - Repair and paint



Damage 7: Sill - left side: Sill - Dent / paintcoat damage - Repair and paint



Roof: 234 µm



Roof rail - left side: 191 µm



Roof rail - right side: 227 µm



Boot lid / rear door: 219 µm



Side panel - rear right side: 201 µm



Door - front left side: 288 µm



Door - front right side: 223 µm



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VZT8EN9N1019588

Hersteller / Modell: OPEL OPEL Insignia Sports Tourer 1.5 Diesel Elegance

Datum	KM-Stand	Beschreibung
12.05.2026	148.508	Keilrippenriemen; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
04.12.2025	133.165	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
08.09.2025	123.375	Systemtest/Eigendiagnose
29.07.2025	118.496	AU; Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben vorne
19.06.2025	114.125	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
18.12.2024	97.390	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
15.12.2023	63.037	Bremsklötze hinten; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
11.07.2023	42.619	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
23.02.2023	27.868	Motoröl b. Wartung; Regelwartungsdienst