



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	VOLVO
Model / version:	V90 DIESEL - 2016
Vin:	YV1PW72TDK1105522
Plate:	
Mileage:	167021
First registration:	27/02/2019
Color:	719 LUMINOUS

ADDITIONAL INFORMATION




Category:	
Transmission:	
Interior color:	
Metallic paint:	✓
Type of lining:	
Board computer reset:	✓

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES





VIN INFORMATION

Radio
Téléphone
Traction avant
Bandeaux de protection latérale
Lettre repère (J)
Largeur avant 8,0
Diamètre arrière 17
Indice de vitesse avant V
Largeur arrière 225
Diesel
110 kw

Système navigation
Transmission automatique
Numéro de châssis
Entourage de vitres chromé
Diamètre avant 17
Largeur arrière 8,0
Hauteur avant 55
Indice de vitesse arrière V
Accoudoir central arrière
1969 cm3
150 ch

12 haut-parleurs
8 rapports
Buses de lave-vitre avant chauffantes
Matière : alliage
Diamètre arrière 17
Diamètre avant 17
Hauteur arrière 55
Largeur avant 225
Finition intérieure cuir
2.00 litres
Métallisée vernissée

Rétroviseurs livrés peints	Rétroviseur intérieur jour/nuit automatique	Suspension pneumatique
Aide au stationnement avant	Aide au stationnement arrière	Régulateur automatique de la distance
Ouverture du coffre électriquement	Pare-brise chauffant	Lunette arrière teintée foncée
Vitres de portes avant feuilletées	Vitres portes arrière teintées foncées	Vitres de custode teintées foncées
Fixotoit chromé	Airbag passager désactivable	Airbag de genoux
Freinage d'urgence assistée autonome (urbain)	Avertisseur de collision avant	système "IAQS"
purificateur d'air	rétroviseurs électrique "8D08"	rétroviseurs convexes
lecteur DVD dans les appuis-tête av	rallonge d'assise des sièges av	sièges av chauffants
siège enfant intégré	écran grille de calandre chromé noir	grille de calandre active Shutter-System
protection sous mécanique Alu	sécurité enfants électrique	encarts décoratifs "Iron Ore"
combiné instruments avec moniteur de 12,3"	embouts des tuyaux d'échappement ovales	spoiler av/ar "Embassy Black"
bandeau de protection du pare-chocs ar	écrans bas de caisse Alu	écran bas de caisse ar
Torslanda (Suède)		

EQUIPMENT

Board computer:		Central locking:	
Compressor:		Cruise control:	
Gps:		Power steering:	
Rear parking sensor:		Repair kit:	
Front seats heated:		Steering wheel:	
Electric windows:		Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	4 mm			Summer	Aluminium	
Front right	4 mm			Summer	Aluminium	
Rear left	4 mm			Summer	Aluminium	
Rear right	4 mm			Summer	Aluminium	

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Dashboard - Boordcomputer resetten	Not original part
4	Bumper R	Dent(s) and scratch(es)
5	Wing RL	Scratch(es)
6	Bumper F - + slecht hersteld	Dent(s) and scratch(es)
7	Wing FR	Bad repair
8	Alloy rim FR	Grooved
9	Outer sill R	Scratch(es)
9	Door FR	Scratch(es)
10	Alloy rim RR	Grooved

Total: 9

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
2	Interior	Damaged			
3	Bodywork	Dent(s) and scratch(es)			


Total: 2

DAMAGES DETAILS

1 - Dashboard - Boordcomputer resetten - Not original part



4 - Bumper R - Dent(s) and scratch(es)



5 - Wing RL - Scratch(es)



6 - Bumper F - + slecht hersteld - Dent(s) and scratch(es)





7 - Wing FR - Bad repair



8 - Alloy rim FR - Grooved



9 - Outer sill R - Scratch(es)



9 - Door FR - Scratch(es)







10 - Alloy rim RR - Grooved



2 - Interior - Damaged - Renta®



3 - Bodywork - Dent(s) and scratch(es) - Renta®





SIGNATURE

Expert
29/07/2026 13:40

