



Expertise

Protocol number: 46916898
Order No. / Reference: 26767057
Inspection date: 6 Aug 2026

Manufacturer: Ford

Model: Kuga 1.5 EcoBlue Aut. TITANIUM

VIN: WF0FXXWPMFNJ50142



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Kuga 1.5 EcoBlue Aut. TITANIUM	
Vehicle Identification number	WF0FXXWPMFNJ50142
Mileage (Read)	79,213 km
First registration	22 Aug 2022
Number of holders	3
Next periodical technical inspection	08/2027
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	88 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Chrome Blue Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Black
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	0 %
Last service on / at	08/2025 at 62,479 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HP204118
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8566 / BTJ 00289		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,110 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/65 R17 102V	Summer tyres on Light alloy	Bridgestone	4mm / 4mm
2)	225/65 R17 102V	Summer tyres on Light alloy	Bridgestone	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/65 R17 106H	Winter tyres on Light alloy	Fulda	6mm / 6mm
2)	225/65 R17 106H	Winter tyres on Light alloy	Fulda	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Equipment

- Klimaautomatik

Standard equipment

- Ambient lighting
- Electrically adjustable, heated and folding exterior mirrors
- Tires: 7 J x 17 alloy wheels (4) in 5x2-spoke design
- third brake light
- Roof rails, silver-colored
- Diesel particulate filter
- Dual exhaust system
- Electronic Stability Program (ESP)
- Lane keeping assist including lane keeping assist
- Electric parking brake with auto hold function
- Ford EcoCoach
- FordPass Connect
- Luggage compartment lighting
- Transmission: 8-speed automatic
- Heated rear window
- Interior mirror, automatically dimming
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- LED taillights
- Steering column, adjustable in height and reach
- Front center console with integrated armrest
- Navigation system: Ford navigation system including Ford SYNC 3
- Front and rear parking pilot system
- Upholstery: Cloth
- Pre-Collision Assist
- Rear view camera
- Projection lens headlights with LED daytime running lights
- Headlight assistant with day/night sensor
- Seats: Driver and passenger seats, 8-way manually adjustable
- Seats: Rear bench seat, sliding, with split-folding backrest
- Seats: Front seats, individually and variably heated
- Start-stop system
- Carpet floor mats front and rear, velour
- Immobiliser
- Anti-lock braking system
- Passenger airbag deactivation
- Tires: Tire repair kit
- Fabric headliner
- Roof spoiler
- 12.3-inch digital instrument panel
- Tachometer
- Driving mode switch selective
- Electric windows front and rear
- Ford Easy Fuel
- Ford Power Start Function & Ford Key Free System
- Luggage compartment cover, roller blind, removable
- Cruise control
- Illuminated glove compartment
- rear window wiper
- Intelligent Protection System (IPS)
- Air conditioning with automatic temperature control
- Front and rear headrests (5) height adjustable
- Steering wheel: Steering wheel, 3-spoke design, in Sensico synthetic leather
- MyKey key system
- Fog light
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Post-Collision Assist
- Tire Pressure Monitoring System (TPMS)
- Windscreen wipers with rain sensor
- Headlights with delayed shut-off
- Power steering
- Seats: Map pockets on the driver's and front passenger's seat backrests
- Seats: Front sports seats with integrated headrests
- Sun visor on driver and passenger side
- Power outlet: 12-volt connection in the luggage compartment
- Central locking with remote control and remote luggage compartment release

Extra equipment

- Detachable towbar (including ESP trailer stabilization)
- Electric tailgate, sensor-controlled (opens and closes via foot movement)
- Paint finish: Special metallic paint finish
- Package: Winter II (Heated windscreen - Heated leather steering wheel - Heated outer rear seats)
- Safety partition net (including attachment points behind the first and second rows of seats)
- Mounting points behind the first and second row of seats according to ISO 27955, (required for the installation of the safety partition available as an accessory from your participating Ford dealer)
- Panoramic sliding sunroof, electric, including roof console with glasses storage compartment



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Wheel arch - Scratch(es) - Loss in value
2	Mudguard - right side	Wheel arch - Scratch(es) - Loss in value
3	Equipment	Tirefit filler - Expired - Replace
4	Engine	Engine cover - top / cover - Damage caused by marten / rodent - Replace
5	Door - rear left side	Door - dent(s) - Smooth repair work
6	Mudguard - left side	Mudguard - left side - dent(s) - Smooth repair work
7	Side panel - rear right side	Sill - Scratch(es) - Smart repair
8	Side panel - rear left side	Sill - Scratch(es) - Smart repair
9	Sill - right side	Sill - dent(s) - Smart repair
10	Misc.	Inspection / maintenance - Due - Replace
11	Rear bumper	Rear bumper - Scratched - Paint
12	Door - rear right side	Door - Dent / paintcoat damage - Repair and paint
13	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
14	Mudguard - right side	Mudguard - right side - Dent / paintcoat damage - Repair and paint
15	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Repair and paint
16	Body	Body - Damage by hail - repair according to calculation

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Interior - Boot cover / roller cover

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Side - left, Provided by user / customer, from 22 Apr 2025	5.209,16 €



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.




Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.




Damage 1: Side panel - rear right side: Wheel arch - Scratch(es) - Loss in value



Damage 1: Side panel - rear right side: Wheel arch - Scratch(es) - Loss in value




Damage 2: Mudguard - right side: Wheel arch - Scratch(es) - Loss in value



Damage 2: Mudguard - right side: Wheel arch - Scratch(es) - Loss in value



Damage 3: Equipment: Tirefit filler - Expired - Replace



Damage 4: Engine: Engine cover - top / cover - Damage caused by marten / rodent - Replace




Damage 4: Engine: Engine cover - top / cover - Damage caused by marten / rodent - Replace



Damage 5: Door - rear left side: Door - dent(s) - Smooth repair work




Damage 5: Door - rear left side: Door - dent(s) - Smooth repair work



Damage 6: Mudguard - left side: Mudguard - left side - dent(s) - Smooth repair work



Damage 6: Mudguard - left side: Mudguard - left side - dent(s) - Smooth repair work




Damage 7: Side panel - rear right side: Sill - Scratch(es) - Smart repair




Damage 7: Side panel - rear right side: Sill - Scratch(es) - Smart repair




Damage 8: Side panel - rear left side: Sill - Scratch(es) - Smart repair




Damage 8: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 9: Sill - right side: Sill - dent(s) - Smart repair




Damage 9: Sill - right side: Sill - dent(s) - Smart repair



Damage 10: Misc.: Inspection / maintenance - Due - Replace




Damage 11: Rear bumper: Rear bumper - Scratched - Paint




Damage 11: Rear bumper: Rear bumper - Scratched - Paint



Damage 11: Rear bumper: Rear bumper - Scratched - Paint




Damage 12: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 13: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 13: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 13: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 14: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint




Damage 14: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 15: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 15: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation




Damage 16: Body: Body - Damage by hail - repair according to calculation




Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0FXXWPMFJ50142

Hersteller / Modell: FORD FORD Kuga 1.5 EcoBlue Aut. TITANIUM

Datum	KM-Stand	Beschreibung
05.08.2025	62.479	Bremse Sonstiges; Bremsklötze hinten; Bremsscheiben + Klötze h; Bremsscheiben hinten; HU + AU
09.01.2025	50.671	Motoröl b. Wartung; Ölwechsel