



Expertise

Protocol number: 46907288
Order No. / Reference: 26774990
Inspection date: 5 Aug 2026

Manufacturer: Peugeot

Model: 508 SW BlueHdi 130 EAT8 Allure Pack

VIN: VR3FCYHZTPY509951



Vehicle details	
Manufacturer / Type / Model / Equipment	
Peugeot 508 SW BlueHdi 130 EAT8 Allure Pack	
Vehicle Identification number	VR3FCYHZTPY509951
Mileage (Read)	143,713 km
First registration	26 Apr 2023
Number of holders	1
Next periodical technical inspection	04/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	96 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Perla Nera Schwarz Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Grey
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	300 km
Last service on / at	02/2026 at 124,087 km		
Key is / should be	2 / 2	FZG documents	Registration and title documents unavailable
		Letter No.	GG050713
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1889 / AEA 00045		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,043 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 94W	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	215/55 R17 94W	Summer tyres on Light alloy	Pirelli	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98V	Winter tyres on Light alloy	Goodyear	3mm / 3mm
2)	215/55 R17 98V	Winter tyres on Light alloy	Goodyear	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS (Anti-lock Braking System)
- Airbag for driver and front passenger
- Airbag: Curtain airbags front and rear
- ACC automatic cruise control with STOP & GO function
- Exterior mirrors in Perla Nera Black
- Hill start assist
- On-board computer
- Roof rails in high-gloss black
- Digital instrument cluster with high-resolution 12.3" screen, adjustable and customizable
- Front parking aid, acoustic and visual
- Driving mode selector (Sport - Normal - Eco)
- Electric windows front and rear
- electric parking brake
- Front collision warning
- front and rear floor mats
- Transmission: 8-speed automatic transmission EAT8
- Seat belts: 3-point safety belts in all seats
- Rear window and side windows in the second row are more heavily tinted.
- Interior mirror automatically dimming
- Keyless system
- Automatic climate control (2-zone)
- Radiator grille with chrome facets and black surround
- Blue LED ambient lighting on the front door panels
- LED daytime running lights
- Steering wheel: Small multifunction leather steering wheel, flattened at the top and bottom.
- Rear center armrest with pass-through flap
- Multifunctional touchscreen
- Multimedia: Mirror Screen
- Navigation system: 3D navigation system NAC
- Particulate filter: FAP diesel particulate filter
- Upholstery: Fabric/faux leather
- Radio accessories: 2 USB ports (Type A) in row 2
- Rain sensor
- Wheels: Tire repair kit (compressor + tire sealant spray)
- paddle shifters on the steering wheel
- Seats: Passenger seat height adjustable
- Seats: Electric lumbar support
- Lane keeping assist with steering intervention
- Chrome-plated decorative exhaust tailpipes
- Traffic sign recognition
- Central locking can be activated from inside using a remote control.
- Active Safety Brake Plus
- Airbag: Side airbag
- Active Blind Spot Assist
- Electrically adjustable, heated and folding exterior mirrors
- Illuminated glove compartment
- Turn signals with lane change indicator function
- third brake light
- Decorative inlays in carbon look
- EBV (Electronic Brakeforce Distribution)
- Rear parking aid, acoustic and visual
- Electronic Stability Program (ESP)
- Misfueling protection
- High beam assist
- Follow-me-home function (automatic)
- Full LED headlights with headlight range control
- luggage compartment roller blind
- Cup holder in the center console
- Heated rear window
- rear window wiper
- Rear apron with diffuser look in black
- Map pockets on the front seatbacks
- Manual child lock
- Height-adjustable headrests
- LED ambient lighting in the front footwell
- LED ceiling lighting at the front
- "Merion" 17" alloy wheels, two-tone
- light sensor
- makeup mirror
- Front center armrests with illuminated storage compartment
- Fatigue warning
- Emergency brake assist
- Break warning
- Radio: Audio
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring system
- Reversing camera with 180° surround view
- Electric power steering
- Seats: Driver's seat height adjustable
- Seats: Rear bench seat and backrest 40/60 split folding
- Stop&Start system
- Glazing: Laminated glass windshield, noise-reducing
- Immobiliser
- Decorative trim in high-gloss black on the side windows



Extra equipment

- Package: Comfort (Ergonomic comfort seats with AGR seal of approval - Extendable thigh support - Electric seat tilt adjustment - Seat heating)
- Mechanically swiveling towbar with ball head
- Paint finish: Special metallic paint

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 1 (registration document) and the vehicle registration certificate Part 2 (title) were not available.
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Body	Underbody panelling - Scratched - Loss in value
2	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
3	Door - rear left side	Door - dent(s) - Smooth repair work
4	Door - rear right side	Door (2 Dellen nebeneinander) - dent(s) - Smooth repair work
5	Side panel - rear right side	Elbow - dent(s) - Smooth repair work
6	Rear bumper	Rear bumper - Scratch(es) - Paint
7	Front bumper	Front bumper - Scratched - Paint
8	Vehicle glazing	Windscreen (Zu viele Steinschläge) - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	2nd wheel set	2 tyres (2. Radsatz nicht in Ausstattungsliste) - Worn - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.




Damage 1: Body: Underbody panelling - Scratched - Loss in value



Damage 1: Body: Underbody panelling - Scratched - Loss in value



Damage 2: Side panel - rear left side: Side panel - dent(s) - Smooth repair work




Damage 2: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 3: Door - rear left side: Door - dent(s) - Smooth repair work




Damage 3: Door - rear left side: Door - dent(s) - Smooth repair work




Damage 4: Door - rear right side: Door (2 Dellen nebeneinander) - dent(s) - Smooth repair work




Damage 4: Door - rear right side: Door (2 Dellen nebeneinander) - dent(s) - Smooth repair work



Damage 5: Side panel - rear right side: Elbow - dent(s) - Smooth repair work



Damage 5: Side panel - rear right side: Elbow - dent(s) - Smooth repair work



Damage 5: Side panel - rear right side: Elbow - dent(s) - Smooth repair work



Damage 5: Side panel - rear right side: Elbow - dent(s) - Smooth repair work



Damage 6: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 6: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 7: Front bumper: Front bumper - Scratched - Paint



Damage 7: Front bumper: Front bumper - Scratched - Paint



Damage 8: Vehicle glazing: Windscreen (Zu viele Steinschläge) - Stone chips - Replace



Damage 8: Vehicle glazing: Windscreen (Zu viele Steinschläge) - Stone chips - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VR3FCYHZTPY509951

Hersteller / Modell: PEUGEOT PEUGEOT 508 SW BlueHDi 130 EAT8 Allure Pack

Datum	KM-Stand	Beschreibung
13.05.2026	134.210	HU + AU
09.02.2026	124.087	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
22.08.2025	107.087	Bremse Sonstiges; Bremsklötze hinten; Bremsscheiben + Klötze h; Bremsscheiben hinten; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
14.03.2025	87.576	Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
03.07.2024	57.368	Bremse Sonstiges; Bremsklötze hinten; Bremsscheiben + Klötze h; Bremsscheiben hinten; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
05.01.2024	30.643	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges