



**BMW X1:** [Redacted]

Vinnumber:	<b>WBA71AB0505V43231</b>	Versionname:	
First Registrationdate:		Fiscalpower:	
Expertise Mileage:	<b>125996</b>	Power Kw:	
Bodytype:		Body colour:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>2307</b>
Fueltype:	<b>Diesel</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

**Options**

Number of keys total:	<b>2</b>	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	<b>No Tow bar</b>
Radio multimedia:			
Type of headlighting:	<b>Headlighting LED</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining artificial leather</b>		
Type of climate control:	<b>Autom climate control</b>		

**Limited Technical Inspection**

**Tyres**

225/55/17/97 W				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Bridgestone: 3 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				225/55 R 17 97 W
Tyre size FR				225/55 R 17 97 W
Tyre size RL				225/55 R 17 97 W
Tyre size RR				225/55 R 17 97 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				255

**Assistance equipment**

Number of charging cables (normal):	<b>1</b>
Number of charging cables (rapid charge):	<b>1</b>

Total cost ex VAT	1164,74
Interior, Damaged, Acceptable	0,00



Bumper F, Scratch(es), Repair and paint (complete) 296,58



Alloy rim FL, Scratch(es), Replace 454,88



Door FL, Scratch(es), Acceptable 0,00



Door RL, Dent(s), Paintless dent repair 95,47



Door RL, Scratch(es), Polish 0,00



Door RL, Dent(s) and scratch(es), Acceptable 0,00



Alloy rim RL, Scratch(es), Repair and paint (complete) 133,03



Alloy rim RR, Scratch(es), Repair and paint (complete)

133,03



Wing RR, Scratch(es), Polish

0,00



Door RR, Scratch(es), Acceptable

0,00



Door FR, Scratch(es), Acceptable

0,00



Alloy rim FR, Scratch(es), Acceptable

0,00



Wing trim FR, Scratch(es), Acceptable

0,00



Fuel cap cover, Deformed / Strained, Replace and paint

51,75



Roof, Dent(s), Acceptable

0,00

