



Expertise

Protocol number: 46627503
Order No. / Reference: 26685754
Inspection date: 21 Jul 2026

Manufacturer: CUPRA

Model: Formentor 2.0 TDI

VIN: VSSZZZKM7PR009364



Vehicle details	
Manufacturer / Type / Model / Equipment	
CUPRA Formentor 2.0 TDI	
Vehicle Identification number	VSSZZZKM7PR009364
Mileage (Read)	63,496 km
First registration	25 Oct 2022
Number of holders	1
Next periodical technical inspection	10/2027
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Magnetic Grau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	Available / complete	Next maintenance in	16,800 km
Last service on / at	09/2025 at 52,648 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GN375847
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	7593 / ARD 00033		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,030 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98V	Winter tyres on Light alloy	Semperit	8mm / 8mm
2)	215/55 R17 98V	Winter tyres on Light alloy	Semperit	8mm / 8mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 96W	Summer tyres on Light alloy	Goodyear	3mm / 4mm
2)	245/45 R18 96W	Summer tyres on Light alloy	Goodyear	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2030		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in the doors
- Adaptive Cruise Control (ACC) up to 210 km/h
- third brake light
- CUPRA Drive Profile
- Diesel particulate filter
- Double-tone signal horn
- Three-point automatic seat belts, front and rear
- Electronic parking brake including auto-hold function
- Electric window regulator with anti-pinch protection and one-touch function
- High beam assist
- Luggage compartment lighting
- Transmission: 6-speed manual transmission
- Heated rear window
- Kessy Advanced and Keyless GO
- Paint finish: Solid
- Steering wheel: CUPRA sports multifunction steering wheel
- front center armrest
- Emergency call service
- Package: Full LED package
- Radio: Media System Plus
- Radio accessories: Bluetooth interface
- Radio accessories: 2 USB-C ports front / 2 rear (charging function)
- Wheels: Tyre fit
- Side windows from the 2nd row of seats and rear window are dark tinted.
- Seats: CUPRA sports seats in the front, upholstered in "Sharp Textile"
- Seats: Lumbar support for driver and front passenger
- Seats: Rear seat backrest asymmetrically split and foldable
- Lane departure warning system
- Illuminated door sill trims, front
- Front Assist area monitoring system with City Emergency Braking function
- Virtual Cockpit
- thermal insulation glazing
- Airbag: Airbags (7)
- Electrically adjustable, folding and heated exterior mirrors
- Climatronic with 3-zone temperature control
- Roof rails in Glossy Black
- Front axle differential lock (VAQ)
- Tachometer
- Parking aid - ultrasonic, rear
- Electronic Stability Control (ESC)
- Remote release for folding down the rear seat backrest in the boot
- luggage compartment cover
- Speed limiter
- Illuminated glove compartment
- rear window wiper
- Headrests, 2 front, 3 rear
- Trim strips on the side windows (outside) in Glossy Black
- Reading lights front and rear
- Rear center armrest with pass-through option
- Fatigue detection
- Package: Light and Visibility
- Radio: Digital radio reception DAB+
- Radio accessories: 7 speakers
- Radio accessories: CUPRA CONNECT
- Tire pressure monitoring system
- Wheels: "Performance I" alloy wheels
- Gear knob in leather look
- Servotronic
- Seats: Passenger seat with height adjustment
- Seats: Driver's seat with height adjustment
- Seats: ISOFIX child seat restraint system, in the 2nd row left and right
- Sun visor on driver and passenger side with make-up mirror and lighting
- Power outlets: 12V socket in the front, 230V socket in the trunk
- Variable luggage compartment floor
- Lashing eyes in the luggage compartment
- Electronic immobilizer

Extra equipment

- Paint finish: Metallic
- Package: Driver Assistance Package L for navigation system (Side Assist incl. Blind Spot Assist - Exit Assist & Exit warning - Traffic Sign Recognition - Predictive Speed Control for ACC)
- Package: Winter (heated front seats)
- Smart Ambient Light (Room-wide ambient lighting - Welcome ceremony - Interaction with driver assistance systems and Drive Profile)
- Navigation: Navigation system (Navigation system prepared for activation of the CUPRA CONNECT online infotainment service package - Navigation system with 10" display - 3D navigation - Voice control - MAPCARE with integrated map for Europe)
- Radio accessories: Wireless Full Link Connectivity (including Android Auto and Apple CarPlay)
- Winter complete wheels aluminum



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Wheel well extension - Scratch(es) - Smart repair
2	Seat - rear	Backrest cover - Porous / cracked - Replace

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Door - front right side	Door - Scratch(es) - No deduction
4	Rear bumper	Rear bumper - Scratch(es) - No deduction
5	Door - front left side	Door edge - Scratch(es) - No deduction
6	Roof	Roof - Stone chips - No deduction
7	Front bumper	Front bumper - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Der montierte Winterradsatz ist Bestandteil der Auslieferungsumfangs.

ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Documents




Figure 16: Documents



Figure 17: Additional tyres




Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.



Damage 1: Side panel - rear right side: Wheel well extension - Scratch(es) - Smart repair



Damage 1: Side panel - rear right side: Wheel well extension - Scratch(es) - Smart repair



Damage 2: Seat - rear: Backrest cover - Porous / cracked - Replace



Damage 2: Seat - rear: Backrest cover - Porous / cracked - Replace



Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 3: Door - front right side: Door - Scratch(es) - No deduction



Wear and tear 3: Door - front right side: Door - Scratch(es) - No deduction



Wear and tear 4: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 4: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 7: Front bumper: Front bumper - Stone chips - No deduction



Wear and tear 7: Front bumper: Front bumper - Stone chips - No deduction