



Expertise

Protocol number: 46829658  
Order No. / Reference: 26566424-1  
Inspection date: 6 Jul 2026

Manufacturer: Opel

Model: Combo Life 1.2 Turbo Start/Stop Edition

VIN: W0VERHNP2NN553699



Vehicle details

Manufacturer / Type / Model / Equipment

Opel Combo Life 1.2 Turbo Start/Stop Edition

|                                      |                   |
|--------------------------------------|-------------------|
| Vehicle Identification number        | W0VERHNP2NN553699 |
| Mileage (Read)                       | 15,481 km         |
| First registration                   | 7 Jun 2023        |
| Number of holders                    | 1                 |
| Next periodical technical inspection | 06/2026           |
| (Report not on hand)                 |                   |

|                                |               |
|--------------------------------|---------------|
| Fuel type                      | Petrol        |
| Engine displacement / Cylinder | 1,199 ccm / 3 |
| Power                          | 81 kW         |
| Gearbox / Number of gears      | Manual / 6    |
| Type of drive                  | Front drive   |
| Type of vehicle                | Van           |

|                      |                                               |
|----------------------|-----------------------------------------------|
| Colour / colour code | TYPE HABILLAGE<br>EXTERIEUR PLATE<br>STANDARD |
| Doors / Seats        | 5 / 4                                         |
| Upholstery type      | Cloth                                         |
| Colour of upholstery | Grey-Black                                    |
| readiness to drive   | Roadworthy                                    |



## Vehicle details

|                                                  |                      |                                |                                                            |
|--------------------------------------------------|----------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | Available / complete | <b>Next maintenance in</b>     | 56 Tag(e)                                                  |
| <b>Last service on / at</b>                      | 08/2025 at 8,133 km  |                                |                                                            |
| <b>Key is / should be</b>                        | 2 / 2                | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                      | <b>Letter No.</b>              | GQ355001                                                   |
| <b>Previous damage / Accident</b>                | None detectable      | <b>Repainting</b>              | None detectable                                            |
| <b>Inspection conditions</b>                     | sufficient           | <b>Lifting equipment / pit</b> | yes                                                        |
| <b>Test drive</b>                                | Not performed        | <b>Engine function test</b>    | Performed                                                  |
| <b>readiness to drive</b>                        | Roadworthy           |                                |                                                            |
| <b>Manufacturer key number/ type code number</b> | 1844 / AHI 00362     |                                |                                                            |
| <b>Emission standard</b>                         | EURO6                | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 2,310 kg             | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size      | Type of tyre                                   | Manufacturer | Tread depth |
|----|----------------|------------------------------------------------|--------------|-------------|
| 1) | 205/60 R16 96V | All-season tyres on Steel rim with wheel cover | Firestone    | 5mm / 5mm   |
| 2) | 205/60 R16 96V | All-season tyres on Steel rim with wheel cover | Firestone    | 5mm / 5mm   |

### Replacement

| Typ | Tyre size | Type of tyre            | Manufacturer | Tread depth |
|-----|-----------|-------------------------|--------------|-------------|
|     | Tirefit   | Expiration date 07/2027 |              |             |

**Legend:** Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



## Equipment



## Standard equipment

- Low beam automatically
- Airbag system (front airbags, driver and front passenger - side airbags, driver and front passenger - head airbags, front and rear outer (front and side airbag, front passenger, manually deactivatable))
- Anti-lock braking system (ABS) (with cornering brake control (CBC) and brake assist)
- Exterior mirrors, electrically adjustable, heated and manually foldable
- Exterior mirror housings in black
- Hill Start Assist
- third brake light
- Electronic Stability Program (ESP Plus)
- Front collision warning with automatic emergency braking and pedestrian detection (monitors the distance (close, medium, far) to the vehicle ahead; if the vehicle approaches a vehicle or pedestrian too quickly, a warning tone sounds and a message appears in the driver information display. If a collision is imminent, the braking system is prepared and, if necessary, emergency braking is initiated to minimize the consequences of a potential collision. Automatic emergency braking is initiated at speeds up to 30 km/h; at speeds up to 140 km/h, the system provides brake assistance.)
- Front headrests (height adjustable)
- Paint finish: Solid
- Driver fatigue detection (Based on steering behavior and driving time, it detects signs of potential driver fatigue and issues a visual and audible warning (three-stage warning). Warning in case of unintentional lane departure above 60 km/h.)
- Upholstery: Cloth
- Radio: Digital radio reception DAB+ (Digital Audio Broadcasting)
- Tire pressure monitoring system
- Wheels: Steel 6.5 J x 16 with tires 205/60 R16 (incl. wheel cover, full surface)
- Side protection strips (black)
- Power steering (speed-dependent)
- Safety steering column, height and length adjustable
- Seats: Comfort passenger seat (4-way manually adjustable (length and backrest angle))
- Seats: Comfort driver's seat (6-way manually adjustable (length, seat height and backrest angle) with armrest)
- Seats: Bench seat in the 2nd row with 3 seats
- Spoiler in black
- Lane Keeping Assist (warning in case of unintentional lane departure (between 65 km/h and 180 km/h) via a warning light in the driver information display. The Lane Keeping Assist also alerts the driver by gently counter-steering, but does not continuously steer the vehicle.)
- Tie-down points 4 in the luggage compartment
- Pre-installation for ISOFIX child seat mounting system (including top tether attachment points on all seats in the 2nd row)
- Central locking with remote control
- Storage compartments (storage compartment in the instrument panel, driver's side, closed; storage compartment in the center console, front; storage shelf above the windshield, open; storage compartment in the front doors, suitable for 1.5-liter beverage bottles; cup holders in the rear doors; cup holders on the dashboard, left and right; glove compartment, closed, upper compartment cooled; storage compartment on the dashboard, passenger side, closed; additional storage compartment above the speedometer unit)
- On-board computer
- Tachometer
- Electric front windows
- Luggage compartment cover
- Intelligent speed control and limiter
- Transmission: 6-speed manual transmission
- Glazed tailgate, with rear window wiper and heater
- Heating and ventilation system, front, with particle and odor filter
- Interior lighting, 1st and 2nd row of seats
- Instruments, 3.5" LCD driver information display
- Child safety lock in the rear doors, manual
- Air conditioning (front, with particle and odor filter - glove compartment split)
- Rear headrests (3 pieces) (height adjustable)
- Steering wheel: Comfort steering wheel (PU), flattened at the bottom, with steering wheel remote control
- Fog light
- Gasoline particulate filter (maintenance-free)
- Rear parking assist (acoustic warning signal when reversing into a parking space)
- Radio: BT with 5-inch touchscreen (USB interface - Bluetooth - audio streaming)
- Tire repair kit (including tire sealant and 12-volt compressor (without jack))
- Sliding door on driver and passenger side (with opening windows)
- Service interval indicator
- Seat belts: Three-point seat belts in all seats (belt force limiter, front and rear outer seats - Double belt tensioners, front seats - Belt tensioners, rear outer seats - Warning tone and light for unfastened seat belts, front and rear seats)
- Seats: Rear seat backrest split 60:40, foldable
- Sun visors for driver and passenger side, (makeup mirror on driver's side)
- 12V power outlet in the center console, front
- Daytime running light
- Traction control (TC Plus)
- Exterior door handles, in car color
- Traffic sign recognition (recognition of speed limits and their cancellation, as well as display of the recognized sign in the driver information display (depending on visibility and weather conditions))
- Immobiliser
- Heat-insulating glazing, tinted



- Ignition keys (2) (one of which is foldable)

### Extra equipment

- Radio: Multimedia radio with 8" color touchscreen display (automatic music recognition (title, album, artist, cover) for audio devices with USB connection, Bluetooth audio streaming, hands-free calling via Bluetooth interface, display of phonebook and call lists, pictures/movies/videos: display of images via USB interface, smartphone integration via Apple CarPlay, Android Auto: navigation (Google Maps, Apple Maps), music, telephone, reading aloud and dictation of text messages, USB interface, 6 speakers)
- All-weather tires
- Parkpilot, front and rear parking aid (with acoustic warning signal when parking forwards and backwards)
- Reversing camera: 180-degree panoramic reversing camera (display of the area behind the vehicle, including steering guidelines, when reverse gear is engaged in the color display of the infotainment system)

### Retrofitted equipment

- wheelchair transport conversion

## Brief expert findings

|                      |                                                                                                                                                                              |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.    |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle.                     |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                        |
| Engine function test | An engine test run was performed.                                                                                                                                            |
| readiness to drive   | The vehicle was roadworthy at the time of inspection.                                                                                                                        |

## Value reducing factors

| No. | Component group | Description                                  |
|-----|-----------------|----------------------------------------------|
| 1   | Misc.           | Main inspection - No evidence - No deduction |

## Wear and tear

| No. | Component group             | Description                                                |
|-----|-----------------------------|------------------------------------------------------------|
| 1   | Body                        | Underbody panelling - Scratch(es) - No deduction           |
| 2   | Rear bumper                 | Rear bumper (Umbau Behindertentransport) - No deduction    |
| 3   | Trim / covers               | Cargo area - lining - right side (Schalter) - No deduction |
| 4   | Side panel - rear left side | Side panel - dent(s) - No deduction                        |
| 5   | Vehicle glazing             | Windscreen - Stone chips - No deduction                    |
| 6   | Front bumper                | Front bumper (Blende rechts) - Scratch(es) - No deduction  |
| 7   | Boot lid / rear door        | Boot lid - Scratch(es) - No deduction                      |

The vehicle shows signs of wear and tear commensurate with its age and use.



## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
*(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
*(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

Das Fahrzeug verfügt über einen behindertengerechten Umbau zur Rollstuhlbeförderung/Transport; im Heckbereich sind hierzu eine Rampe sowie diverse erforderlichen Systeme nachgerüstet, die Sitze im Fond welche ab Werk vorhanden waren, sind hier mitgeliefert.





**Figure 1:** Diagonal front (left)



**Figure 2:** Diagonal front (right)



**Figure 3:** Diagonal rear (left)



**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear





Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view




Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres






Figure 13: Documents



Figure 14: Navigation



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.





Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.





Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.




Figure 34: Misc.




Figure 35: Misc.




Figure 36: Misc.





Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.



Figure 40: Misc.




Figure 41: Misc.




Figure 42: Misc.






**Wear and tear 2:** Rear bumper: Rear bumper (Umbau Behindertentransport) - No deduction



**Wear and tear 2:** Rear bumper: Rear bumper (Umbau Behindertentransport) - No deduction



**Wear and tear 3:** Trim / covers: Cargo area - lining - right side (Schalter) - No deduction



**Wear and tear 3:** Trim / covers: Cargo area - lining - right side (Schalter) - No deduction