



Expertise

Protocol number: 46383769
Order No. / Reference: 26483985
Inspection date: 7 Jul 2026

Manufacturer: Skoda
VIN: TMBAH7NP3N7020690

Model: Superb 2.0 TDI DSG Premium Edition



Vehicle details	
Manufacturer / Type / Model / Equipment	
Skoda Superb 2.0 TDI DSG Premium Edition	
Vehicle Identification number	TMBAH7NP3N7020690
Mileage (Read)	45,010 km
First registration	28 Jan 2022
Number of holders	1
Next periodical technical inspection	01/2027
(Report on hand)	
Power / Engine displacement	110 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Black-Magic Perleffekt
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	242 Tag(e)
Last service on / at	02/2026 at 43,800 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GG204915
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8004 / APK 01341		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,148 kg	Empty weight	

Tyres			
Mounted tyres			
#	Tyre size	Type of tyre	Tread depth
1)	215/55 R17 94V	Summer tyres on Light alloy	5mm / 5mm
2)	215/55 R17 94V	Summer tyres on Light alloy	5mm / 5mm
Additional tyres			
#	Tyre size	Type of tyre	Tread depth
1)	215/60 R16 95H	Winter tires (with run-flat tires) on Light alloy	5mm / 5mm
2)	215/60 R16 95H	Winter tires (with run-flat tires) on Light alloy	6mm / 6mm

Replacement			
Typ	Tyre size	Type of tyre	Tread depth
	Tirefit	Expiration date 09/2025	

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Closed storage compartments behind the wheel arches in the trunk, including cargo elements
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Traction control (ASR)
- Exterior mirrors and door handles in body color
- Illuminated glove compartment
- Hydraulic brake assist (HBA)
- Decorative inlay Argenzo Zebrano
- Digital instrument cluster (Virtual Cockpit) 10.2"
- Third brake light
- Electric tailgate opening
- Electronic transverse differential lock (XDS+)
- Driving light assistant and rain sensor
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Front and rear footwell lighting
- Transmission: 7-speed dual-clutch transmission (DSG)
- Tinted windows
- ISOFIX preparation on the outer rear seats, including top tether
- Comfort opening for the electric tailgate
- LED ambient lighting
- Remote release of the rear seat backrests in the trunk
- Steering wheel: 2-spoke leather steering wheel with multifunction buttons
- Matrix LED headlights
- Front center armrest with storage compartment
- Engine drag torque control (MSR)
- LED fog lights with integrated cornering lights
- Upholstery: Glamour leather interior
- Radio accessories: Digital radio reception DAB+
- Radio accessories: SmartLink+
- Radio accessories: Wireless SmartLink
- Tire pressure monitoring
- Wheels: 17" Drakon alloy wheels
- Superb seat belts
- Seats: Heated front seats
- Seats: Adjustable lumbar support in the front seats
- Seats: Electric operation of the front passenger seat from the rear
- Seats: Rear seat backrest split 60:40, foldable
- Sun visor on driver and passenger side with illuminated make-up mirror
- 12V socket in the center console, front and rear
- Textile floor mats
- Chrome-plated elements
- Immobiliser
- Storage compartments
- Airbag, driver and switchable passenger airbag
- Airbag, head airbags
- Anti-lock braking system (ABS)
- Electrically adjustable and heated exterior mirrors
- Electrically folding exterior mirrors
- Hill start assist
- Grey headliner
- Diesel particulate filter and SCR catalyst
- Tachometer
- Dynamic Light Assistant (Masked Continuous High Beam)
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC)
- Chassis: Sport chassis (15 mm lowering)
- Front radar assistant including city emergency braking function
- Cruise control system (cruise control) including speed limiter
- Heated rear window
- Kessy, keyless entry and start-stop system
- Air Care Climatronic air conditioning system (3 zones)
- Front and rear headrests are height-adjustable.
- LED taillights in crystal glass look and animated turn signals
- Steering wheel: height and reach adjustable
- Reading lights at the front and rear of the headliner
- Rear center armrest with cup holders and pass-through option
- Multi-collision brake
- Rear parking sensors
- Progressive steering
- Radio accessories: In-car communication
- Radio accessories: USB ports at the front (Type-C) and USB charging port (Type-A) in the center armrest
- Tire mobility kit
- Heated windshield washer nozzles
- Seat: Massage function for electric driver's seat
- Seats: Ventilated front seats for leather interiors
- Seats: Electrically adjustable front seats with memory function
- Seats: Height-adjustable front seats
- SKODA Care Connect
- Start/stop system including brake energy recuperation
- 12V socket in the trunk
- Telephone: Convenient Bluetooth hands-free phone system
- Lashing eyes in the trunk
- Central locking with remote control



Extra equipment

- Package: Business Amundsen (DSG) (Amundsen navigation system - voice control - Wi-Fi hotspot - Wireless Smartlink for Apple CarPlay - 8" capacitive touchscreen in glass design - Phonebox - Traveller assistance system (traffic sign recognition, predictive lane keeping assist pACC, adaptive lane keeping assist, emergency and traffic jam assist, capacitive steering wheel with hands-off detection) - 230 V socket and 3 USB ports, tablet holder - Sunset - Infotainment Online (3-year subscription))
- Package: Assistance (Lane Change Assist - Reversing Camera - Parking Assist - Preparation for a Trailer Hitch - (Active Tire Pressure Monitoring System) - Driver Fatigue Detection)
- Paint finish: Pearl effect

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Floor mats (Fußmatte vorne Links) - Broken / torn - Replace
2	Equipment	Tirefit filler - Expired - Replace
3	Side panel - rear right side	Side panel - Scratch(es) - Paint
4	Rear bumper	Rear bumper - Deformed - Repair and paint
5	Vehicle glazing	Windscreen - Broken / torn - Replace
6	Front bumper	Front bumper (inkl. diverse Anbauteile verformt & verkratzt) - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Scratch(es) - No deduction
2	Interior	Interior - Scratch(es) - No deduction
3	Sill - left side	Sill - Scratch(es) - No deduction
4	Wing mirror - right side	Cap - Stone chips - No deduction
5	Boot lid / rear door	Boot lid - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Accident damages

No.	Accident
1	Side - left



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents

Fz-Ident-Nr.: TMBAH7NP3	
Fz-Klasse: M1 / AA	
HSN: 8004	
TSN / VSN: APK / 01341	
Kilometerstand: 34357 km	
letzte HU: 00.00	

n genannter Untersuchungsart geprüft und abschließend folgendes Ergebnis		
plakette	(8) Nächste HU:	Wieder
erteilt	01.27	

ms- kennw. (-)	Berechn. Druck (bar)	Summe der Bremskräfte Σ FB Ist (daN)	Erforderliche Bremskräfte Σ FB Min (daN)	Bremskraft- anteil Ist (%)
3	-	715	589	68.4
3	-	442	322	31.6
	-	316	-	-

Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.




Figure 37: Misc.



Figure 38: Misc.




Damage 1: Trim / covers: Floor mats (Fußmatte vorne Links) - Broken / torn - Replace



Damage 2: Equipment: Tirefit filler - Expired - Replace



Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Paint




Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Paint




Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Paint




Damage 4: Rear bumper: Rear bumper - Deformed - Repair and paint




Damage 4: Rear bumper: Rear bumper - Deformed - Repair and paint




Damage 4: Rear bumper: Rear bumper - Deformed - Repair and paint



Damage 5: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 5: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 5: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 6: Front bumper: Front bumper (inkl. diverse Anbauteile verformt & verkratzt) - Broken / torn - Replace



Damage 6: Front bumper: Front bumper (inkl. diverse Anbauteile verformt & verkratzt) - Broken / torn - Replace




Damage 6: Front bumper: Front bumper (inkl. diverse Anbauteile verformt & verkratzt) - Broken / torn - Replace



Damage 6: Front bumper: Front bumper (inkl. diverse Anbauteile verformt & verkratzt) - Broken / torn - Replace



Damage 6: Front bumper: Front bumper (inkl. diverse Anbauteile verformt & verkratzt) - Broken / torn - Replace



Damage 6: Front bumper: Front bumper (inkl. diverse Anbauteile verformt & verkratzt) - Broken / torn - Replace



Damage 6: Front bumper: Front bumper (inkl. diverse Anbauteile verformt & verkratzt) - Broken / torn - Replace




Damage 6: Front bumper: Front bumper (inkl. diverse Anbauteile verformt & verkratzt) - Broken / torn - Replace




Damage 6: Front bumper: Front bumper (inkl. diverse Anbauteile verformt & verkratzt) - Broken / torn - Replace




Damage 6: Front bumper: Front bumper (inkl. diverse Anbauteile verformt & verkratzt) - Broken / torn - Replace




Damage 6: Front bumper: Front bumper (inkl. diverse Anbauteile verformt & verkratzt) - Broken / torn - Replace



Damage 6: Front bumper: Front bumper (inkl. diverse Anbauteile verformt & verkratzt) - Broken / torn - Replace



Damage 6: Front bumper: Front bumper (inkl. diverse Anbauteile verformt & verkratzt) - Broken / torn - Replace




Damage 6: Front bumper: Front bumper (inkl. diverse Anbauteile verformt & verkratzt) - Broken / torn - Replace




Damage 6: Front bumper: Front bumper (inkl. diverse Anbauteile verformt & verkratzt) - Broken / torn - Replace



Damage 6: Front bumper: Front bumper (inkl. diverse Anbauteile verformt & verkratzt) - Broken / torn - Replace




Wear and tear 1: Bonnet: Bonnet - Scratch(es) - No deduction



Wear and tear 1: Bonnet: Bonnet - Scratch(es) - No deduction




Wear and tear 4: Wing mirror - right side: Cap - Stone chips - No deduction



Wear and tear 5: Boot lid / rear door: Boot lid - Scratch(es) - No deduction



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: TMBAH7NP3N7020690

Hersteller / Modell: SKODA SKODA Superb 2.0 TDI DSG Premium Edition

Datum	KM-Stand	Beschreibung
20.02.2026	43.800	Bremsflüssigkeit; Bremsflüssigkeit ern; Regelwartungsdienst; Wartung Sonstiges
28.10.2025	41.024	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
31.01.2025	34.573	AU
15.12.2023	18.955	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges