

# MACDAM

## Ford Mustang '19 BEV

### Vehicle information

Make:	<b>Ford</b>	License:	
Gearbox:	<b>Automatic</b>	Body color:	
Model:	<b>Mustang '19 BEV</b>	VIN:	<b>WF0TK1EM5MMA22342</b>
Fuel type:	<b>Electric</b>	Power:	<b>190 kW</b>
Version:	<b>Mustang EV 75kWh RWD St.Ran.</b>	First registration	<b>05/08/2021</b>
Mileage:	<b>130529 km</b>	N° of doors:	

### Damage summary

Front	1
Left	3
Rear	1
Right	3

### Commercial pictures





### Options according to the inspector

Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser	Yes
Radio multimedia	Yes	Rear view camera	Yes	Telephone equipment	Yes

### Damages


--	--	--	--	--	--

**Bonnet**

Stone chip(s)

Repair and paint (complete)

Front




**Bumper R**

Scratch(es)

Repair and paint (complete)

Rear



**Door FL**

Dent(s)

Repair and paint (complete)

Left



**Door FR**

Dent(s)

Repair and paint (complete)

Right



**Door frame RL**

Scratch(es)  
Repair and paint (partial)  
Left



**Door RR**

Dent(s)  
Repair and paint (complete)  
Right



**Wing RL**

Scratch(es)  
Repair and paint (complete)  
Left



**Wing RR**

Dent(s)  
Repair and paint (complete)  
Right



## Tyres

### Front Left

Winter

225/60/18/100/H

Goodyear

4.1 mm

### Front Right

Winter

225/60/18/100/H

Goodyear

4.2 mm

### Rear Left

Winter

225/60/18/100/H

Goodyear

7.4 mm

### Rear Right

Winter

225/60/18/100/H

Goodyear

6.8 mm

## Checks

Certificate of Conformity	<b>No</b>	CO2 Emission	<b>0</b>
Digital maintenance	<b>Yes</b>	GPS storage	<b>Yes</b>
GPS storage	<b>HD</b>	Luggage cover	<b>Yes</b>
Number head rests	<b>5</b>	Number of charging cables (rapid charge)	<b>1</b>
Number of keys total	<b>2</b>	Reset to factory settings	<b>Yes, vehicle is reset to factory settings</b>
Service book	<b>N/A</b>	User's manual	<b>Yes</b>

### Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.