



Expertise

Protocol number: 46537488
Order No. / Reference: 26605196
Inspection date: 15 Jul 2026

Manufacturer: Kia

Model: Niro 1.6 GDI PHEV 2WD OPF Aut. Vision

VIN: KNACD81DGL5378295



Vehicle details	
Manufacturer / Type / Model / Equipment	
Kia Niro 1.6 GDI PHEV 2WD OPF Aut. Vision	
Vehicle Identification number	KNACD81DGL5378295
Mileage (Read)	198,633 km
First registration	20 May 2020
Number of holders	1
Next periodical technical inspection	05/2027
(Report not on hand)	
Power / Engine displacement	77 kw / 1,580 ccm
Fuel type / Cylinder	Hybr.B/E ext.aufll / 4
Gearbox / Number of gears	Automatic / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Schneeweiß
Doors / Seats	5 / 5
Upholstery type	Part leather
Colour of upholstery	Black-Grey
Re-import	no
readiness to drive	Roadworthy



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	1,249 km
Last service on / at	01/2026 at 184,882 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FU374456
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8253 / AGL 00014		
Emission standard	EURO6;WLTP;DG;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,000 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 92H	Summer tyres on Light alloy	Michelin	5mm / 5mm
2)	205/60 R16 92H	Summer tyres on Light alloy	Dunlop	4mm / 4mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 92H	Winter tyres on Steel	Dunlop	5mm / 5mm
2)	205/60 R16 92H	Winter tyres on Steel	Dunlop	7mm / 7mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2024		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in the luggage compartment floor
- Airbag: 2 front airbags (passenger airbag can be deactivated)
- Anti-lock braking system (ABS) (with electronic brake force distribution)
- Electrically adjustable exterior mirrors
- Exterior mirrors with integrated LED turn signals
- Brake Assist (BAS)
- Third brake light with LED
- twilight sensor
- Electronic Stability Program (ESP) with TCS (Traction Control)
- Forward Collision Avoidance Assist (FCA) with braking intervention and pedestrian detection
- Countersteering support (Vehicle Stability Management, VSM)
- Speed limiter
- 6-speed dual-clutch transmission
- Rear diffuser in aluminum look
- rear window wiper
- Interior rearview mirror self-dimming (electrochromatic)
- Insulating glazing for the windshield (for improved external noise insulation)
- Paint finish: Solid
- Leather steering wheel and leather gear knob
- Steering wheel: Steering wheel adjustable for height and reach
- Rear center armrest (with cup holders)
- Driver Alert System (DAW)
- Fog light
- Rear parking sensors
- Radio: Kia RDS radio (with 8-inch touchscreen, Apple CarPlay and Android Auto)
- Radio accessories: USB port
- Tire pressure monitoring system (TPMS) (pressure display for each wheel on the on-board computer display)
- Reversing camera (transmission to navigation screen)
- Rear seat backrest asymmetrically split (60:40), foldable
- Seat belts (three-point seat belts at all seats, seat belt warning system for all seats (SBR), front seat belts height-adjustable, front belt tensioners and belt force limiters)
- Active Lane Keeping Assist (LKA) (Active Lane Keeping Assist - with corrective steering intervention - Lane Keep Assist (LKA))
- Bumper underside, wheel arches and side sills black
- LED daytime running lights
- Phone accessories: Bluetooth hands-free kit
- Exterior door handles in chrome
- Electronic immobilizer
- thermal insulation glazing
- Auxiliary heater, electric
- Airbag: 1 knee airbag (driver's side)
- Airbag: 2 side airbags
- Airbag: 2 curtain airbags
- Dashboard and door trim with gloss black applications
- Electrically folding exterior mirrors
- Exterior mirrors with gloss black accents
- Hill Start Assist Control (HAC)
- Roof rails (in aluminum look)
- Drive Mode Select (driving mode selection via gear change)
- Electric windows front and rear (with one-touch function on the driver's side)
- Headlights with halogen technology (low and high beam)
- Floor mats
- luggage compartment cover
- Luggage compartment lighting
- Adaptive cruise control (including Stop&Go function (Smart Cruise Control, SCC with S&G))
- Back window, heater
- Interior color in black
- ISOFIX mounts on outer rear seats
- Automatic climate control (2 zones with anti-fog system)
- Headrests on all seats are height-adjustable.
- Charging cable (Schuko plug to Type 2 plug)
- Heated steering wheel
- Steering wheel: Multifunction steering wheel
- Steering wheel: Paddle shifters on the steering wheel
- Front center armrest (with integrated storage compartment)
- Electronic parking brake with auto-hold function
- Upholstery: Fabric-leather combination
- Radio accessories: 6 speakers (2 front speakers, 2 rear speakers, 2 front tweeters)
- Rain sensor
- Wheels: 16" alloy wheels (with 205/60 R 16 tires)
- Wheels: Tire repair kit
- LED taillights
- Power steering (electronically assisted)
- Seat: Passenger seat height adjustable
- Seat: Driver's seat height adjustable
- Seat: Front seat heating
- Sun visors with illuminated makeup mirrors (for driver and front passenger)
- Lane Follow Assist (LFA) - The system uses sensors to determine the safe distance to the vehicle in front and takes over acceleration, braking, and steering. - It recognizes the lane markings and thus keeps the Kia e-Niro centered in its lane.)
- Virtual Engine Sound System (VESS) for pedestrian protection
- Central locking with remote control



Extra equipment

- Preparation for detachable towbar (wiring kit and bodywork modifications carried out), additional costs for installation of the towbar carrier will apply)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Interior	Sun visor - left side - Broken / torn - Replace
2	Trim / covers	Floor mats - Broken / torn - Replace
3	Equipment	Tirefit filler - Expired - Replace
4	Trim / covers	Carpet - front left side - Broken / torn - Loss in value
5	Sill - right side	Sill - dent(s) - Smart repair
6	Door - front left side	Door - Dent / paintcoat damage - Smart repair
7	Rear bumper	Rear bumper - Scratch(es) - Smart repair
8	Body	Body - Glued / labelled - De-glue / neutralise
9	Roof	Roof (Korrosion) - Stone chips - Repair and paint

Wear and tear

No.	Component group	Description
1	Steering system	Steering wheel sheath - Abrasion - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.
- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.

ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Documents



Figure 17: Documents




Figure 18: Documents



Figure 19: Additional tyres



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.





Figure 33: Misc.



Figure 34: Misc.



Damage 1: Interior: Sun visor - left side - Broken / torn - Replace



Damage 1: Interior: Sun visor - left side - Broken / torn - Replace




Damage 1: Interior: Sun visor - left side - Broken / torn - Replace




Damage 2: Trim / covers: Floor mats - Broken / torn - Replace



Damage 2: Trim / covers: Floor mats - Broken / torn - Replace



Damage 3: Equipment: Tirefit filler - Expired - Replace




Damage 4: Trim / covers: Carpet - front left side - Broken / torn - Loss in value



Damage 4: Trim / covers: Carpet - front left side - Broken / torn - Loss in value



Damage 5: Sill - right side: Sill - dent(s) - Smart repair



Damage 5: Sill - right side: Sill - dent(s) - Smart repair



Damage 6: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Damage 6: Door - front left side: Door - Dent / paintcoat damage - Smart repair




Damage 6: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 7: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 8: Body: Body - Glued / labelled - De-glue / neutralise



Damage 8: Body: Body - Glued / labelled - De-glue / neutralise



Damage 8: Body: Body - Glued / labelled - De-glue / neutralise



Damage 8: Body: Body - Glued / labelled - De-glue / neutralise



Damage 9: Roof: Roof (Korrosion) - Stone chips - Repair and paint



Damage 9: Roof: Roof (Korrosion) - Stone chips - Repair and paint



Damage 9: Roof: Roof (Korrosion) - Stone chips - Repair and paint



Damage 9: Roof: Roof (Korrosion) - Stone chips - Repair and paint



Wear and tear 1: Steering system: Steering wheel sheath - Abrasion - No deduction



Wear and tear 1: Steering system: Steering wheel sheath - Abrasion - No deduction



Wear and tear 1: Steering system: Steering wheel sheath - Abrasion - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: KNACD81DGL5378295

Hersteller / Modell: KIA KIA Niro 1.6 GDI PHEV 2WD OPF Aut. Vision

Datum	KM-Stand	Beschreibung
23.01.2026	184.882	Motoröl b. Wartung; Regelwartungsdienst
16.06.2025	167.843	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern
16.05.2025	164.031	Batterie ern; HU + AU
10.02.2025	149.645	Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
23.04.2024	127.854	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
05.10.2023	107.998	Keilrippenriemen; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
11.04.2023	89.402	Bremsflüssigkeit ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Regelwartungsdienst
12.10.2022	72.080	Motoröl b. Wartung; Regelwartungsdienst
21.04.2022	53.650	Bremsflüssigkeit ern; Motoröl b. Wartung; Regelwartungsdienst
21.01.2021	16.771	Kleine Inspektion; Motoröl b. Wartung