



Expertise

Protocol number: 46840730
Order No. / Reference: 26786750
Inspection date: 3 Aug 2026

Manufacturer: Ford
VIN: WF0SXXWPGSPK43836

Model: Transit Connect 230 L2 Trend



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Transit Connect 230 L2 Trend	
Vehicle Identification number	WF0SXXWPGSPK43836
Mileage (Read)	144,203 km
First registration	31 May 2024
Number of holders	1
Next periodical technical inspection	05/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	73 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frozen White
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Grey
Re-import	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	88 %
Last service on / at	05/2026 at 142,416 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT876321
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8566 / BUU 01076		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,270 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Summer tyres on Steel rim with wheel cover	Continental	5mm / 5mm
2)	205/60 R16 96H	Summer tyres on Steel rim with wheel cover	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Steel	Goodyear	2mm / 3mm
2)	205/60 R16 96H	Winter tyres on Steel	Goodyear	3mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/60 R16 96H	Summer tyres on Steel	Continental	7 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Alternator/Generator
- Battery, reinforced
- Cargo area lining, side, half-height
- Central locking with remote control (door lock only on driver's door - 2 keys, one of which is a remote control key)
- Daytime running light
- Door handles, black
- Double-leaf rear doors without windows
- Electronic immobilizer (EPATS)
- Emergency Brake Assist (EBA)
- Emergency brake light (hazard warning flashing activated during heavy braking)
- Exterior mirrors, electrically adjustable and heated
- Fog light
- Ford Easy Fuel (comfortable fuel filler cap and misfuelling protection)
- Front air conditioning including semi-electronic recirculation system
- Front electric windows (with one-touch down function for driver's side)
- Front interior lighting with delay function
- Front overhead storage shelf (across the entire width of the interior, including side grab handles)
- Glove compartment with lid
- Partition wall to the cargo area without window
- Power outlet: 12-volt connection on the front center console
- Rubberized flooring, front
- Seat belts (front seat belt tensioners and force limiters - warning system for unfastened seat belts for driver and front passenger)
- Seats: Seat package 4 (driver's seat, 3-way manually adjustable (forward/backward, height, backrest) - single passenger seat, 2-way manually adjustable (forward/backward/backrest) - headrests, height-adjustable - lumbar support, manual (driver's seat) - "Capitol/City" fabric in Ebony (black))
- Side protection strips, plastic
- Third brake light
- Transmission: 6-speed transmission
- Wheels: Steel wheels 6.5 J x 16 with 205/60 R 16 tires and wheel trims
- ABS with EBD
- Automatic security door lock (45 sec.) (Automatic relocking if no door is opened within 45 seconds of unlocking via remote control)
- Cargo area floor protection plastic, molded
- Center console, front (open with storage area, 2 cup holders)
- Child safety lock on sliding doors
- Diesel particulate filter (DPF) (with SCR catalyst and AdBlue tank)
- Driver's side airbag
- Dust and pollen filter
- Electro-mechanical power steering (EPAS - Electric Power Assisted Steering)
- Electronic Stability Program (ESP) (with Traction Control (TCS) including Torque Vectoring Control and Adaptive Load Control)
- Exterior mirrors, narrow mirror format
- FordPass Connect (information about the current status or location of the vehicle as well as control of selected vehicle functions via smartphone with the FordPass app - incl. live traffic information in real time (in conjunction with Ford navigation system incl. Ford SYNC 3) - incl. Wi-Fi hotspot)
- Front bumper and rear bumper end caps painted in body color
- Front spoiler lip
- Heat-insulating glazing, lightly tinted
- Hill start assist
- Lashing eyes
- On-board computer including outside temperature display
- Paint finish: Solid
- Radio: Ford Audio System 2 (DAB/DAB+ radio - FM/AM radio - USB port - Bluetooth interface - Steering wheel audio remote control)
- Sliding door at rear, right
- Start-stop system
- Steering column, adjustable in height and reach
- Sun visor for driver and front passenger
- Tachometer



Extra equipment

- Seats: Seat Package 42 (Driver's seat, 3-way manually adjustable (forward/backward, height, backrest) - Single passenger seat, 2-way adjustable (forward/backward, backrest) - Height-adjustable headrests - Heated seats for driver and front passenger - Manually adjustable lumbar support in driver's seat - Airbag Package (Front airbag for front passenger, front head/shoulder airbags, side airbags for driver and front passenger) - "Capitol/City" fabric in Ebony (black))
- Radio: Ford Audio System 9 (Ford navigation system incl. Ford SYNC 3 with AppLink, 6" touchscreen radio (FM/AM), 2 USB ports, audio remote control on the steering wheel, Bluetooth hands-free system and audio streaming, emergency call assistant, SMS text-to-speech function, SMS sending function, voice control, reversing camera, phase diversity antenna, DAB/DAB+, acoustic and visual route guidance, road map for Europe, Apple CarPlay, Android Auto, live traffic, detailed 3D visualization, Michelin travel guide for Europe)
- Voltage converter (230 V/150 Watt (socket))
- Power outlet: 12-volt connection in the charging/luggage compartment
- "S0" 2x tension straps
- Heated windscreen (including electrically adjustable and heated exterior mirrors)
- Cargo area lighting, LED
- Front and rear parking pilot system
- Pre-Collision Assist, camera-based (with pedestrian and cyclist detection, including Automatic Emergency Braking (AEB), Dynamic Brake Support (DBS), Forward Collision Warning (FCW))
- Spare wheel: Steel wheel
- Headlight assistant with day/night sensor including automatically dimming interior mirror (including headlight dimming with switch-off delay, windscreen wipers with rain sensor)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	2nd wheel set	1 tyre - does not meet manufacturer specifications - No deduction
2	Body	Body - Glued / labelled - De-glue / neutralise

Wear and tear

No.	Component group	Description
1	Engine	Engine (Ölspuren erkennbar) - No deduction
2	Wheel / tyres	Wheel cover - rear right side - Scratch(es) - No deduction
3	Wheel / tyres	Wheel cover - front right side - Scratch(es) - No deduction
4	Side panel - rear left side	Side panel - dent(s) - No deduction
5	2nd wheel set	2nd wheel set - Does not meet the leasing specifications - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 2 Jun 2025	669,88 €



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Documents



Figure 17: Additional tyres




Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Damage 2: Body: Body - Glued / labelled - De-glue / neutralise




Damage 2: Body: Body - Glued / labelled - De-glue / neutralise




Damage 2: Body: Body - Glued / labelled - De-glue / neutralise



Wear and tear 1: Engine: Engine (Ölspuren erkennbar) - No deduction




Wear and tear 1: Engine: Engine (Ölspuren erkennbar) - No deduction



Wear and tear 1: Engine: Engine (Ölspuren erkennbar) - No deduction




Wear and tear 2: Wheel / tyres: Wheel cover - rear right side -
Scratch(es) - No deduction



Wear and tear 3: Wheel / tyres: Wheel cover - front right side -
Scratch(es) - No deduction



Wear and tear 4: Side panel - rear left side: Side panel - dent(s) - No
deduction



Wear and tear 4: Side panel - rear left side: Side panel - dent(s) - No
deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0SXXWPGSPK43836
Hersteller / Modell: FORD FORD Transit Connect 230 L2 Trend

Datum	KM-Stand	Beschreibung
11.05.2026	142.416	AU; Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
27.01.2026	121.401	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
03.09.2025	91.770	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
18.06.2025	76.973	Systemtest/Eigendiagnose
21.05.2025	70.647	Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne
25.03.2025	60.198	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
05.11.2024	32.153	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges