

MACDAM

Skoda Enyaq '21 BEV



Vehicle information



Make:	Skoda	License:	
Gearbox:	Automatic	Body color:	
Model:	Enyaq '21 BEV	VIN:	TMBJB7NY1NF009039
Fuel type:	Electric	Power:	132 kW
Version:	Enyaq iV60	First registration	13/09/2021
Mileage:	173820 km	N° of doors:	

Damage summary


Front	2
Interior	2
Left	2
Rear	5
Right	3

Commercial pictures





Options according to the inspector					
Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser	Yes
Panoramic roof	Yes	Radio multimedia	Yes	Sun Roof electric	Yes
Telephone equipment	Yes				

Damages				
Alloy rim RR Scratch(es) Repair and paint (complete) Right	 			
Bonnet Stone chip(s) Repair and paint (complete) Front	 			
Boot lid covering R Scratch(es) Smart repair Rear	 			
Bumper R Scratch(es) Repair and paint (complete) Rear	   			

Bumper trim F
Scratch(es)
Replace
Front



Bumper trim R
Scratch(es)
Replace
Rear



Charging cable (normal)
Missing
Replace
Rear



Door FL
Bad repair
Repair and paint (complete)
Left



Door FR
Bad repair
Repair and paint (complete)
Right



Door RL
Bad repair
Repair and paint (complete)
Left



Door RR
Bad repair
Repair and paint (complete)
Right



Interior
Stain
Cleaning
Interior



Malfunction
Not functioning (well)
Diagnosis
Interior



Tailgate / Boot
Scratch(es)
Repair and paint (partial)
Rear



Tyres			
Front Left			
Summer			
235/55/19/101/Y			
Pirelli			
3.9 mm			
Front Right			
Summer			
235/55/19/101/Y			
Pirelli			
3.6 mm			
Rear Left			
Summer			
235/55/19/101/Y			
Pirelli			
4.8 mm			
Rear Right			
Summer			
235/55/19/101/Y			
Pirelli			
4.6 mm			

Checks			
Certificate of Conformity	No	CO2 Emission	0
Digital maintenance	Yes	GPS storage	Yes
GPS storage	HD	Luggage cover	Yes
Number head rests	5	Number of charging cables (rapid charge)	1
Number of keys total	2	Service book	N/A
User's manual	Yes		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.