



Expertise

Protocol number: 47130676
Order No. / Reference: 26804714
Inspection date: 18 Aug 2026

Manufacturer: Toyota
VIN: JTMAABAA70A008336

Model: bZ4X



Vehicle details	
Manufacturer / Type / Model / Equipment	
Toyota bZ4X	
Vehicle Identification number	JTMAABAA70A008336
Mileage (Read)	30,729 km
First registration	16 May 2023
Number of holders	1
Fuel type	Electric
Power	73 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Onxyschwarz
Doors / Seats	5 / 5
Upholstery type	Artificial leather
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	49,000 km
Last service on / at	07/2025 at 19,196 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV447469
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	7104 / AAR 00004		
Emission standard	2017/1151	fine dust sticker	
Permitted total weight	2,465 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/60 R18 107V	Winter tyres on Light alloy	Continental	6mm / 6mm
2)	235/60 R18 107V	Winter tyres on Light alloy	Continental	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R20 104V	Summer tyres on Light alloy	Bridgestone	5mm / 5mm
2)	235/50 R20 104V	Summer tyres on Light alloy	Bridgestone	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- | | |
|--|--|
| <ul style="list-style-type: none"> • 7-inch multi-information display • Airbag: Driver's knee airbag • Armrest with door trim in fabric at the front • Electrically adjustable, folding and heated exterior mirrors • Third brake light with LED technology • Entry lighting • electric window regulator • Electric parking brake with hold function • Speed limiter • cup holder • Interior lighting using LED technology • ISOFIX child seat attachment with additional upper attachment point, rear • Headrests (2) • Paint finish: Solid • Cargo area floor, double-stepped • Steering wheel: Leather steering wheel, in a 3-spoke design • Radio: Toyota Smart Connect • Radio accessories: Digital radio (DAB+) • Tire repair kit • Wheels: Tire pressure warning system • Rear view camera • Manual headlight height adjustment • Seats: Passenger seat manually adjustable in height and length • Smart Key System • 12V socket at the front • Toyota Safety Sense • Electronic immobilizer | <ul style="list-style-type: none"> • Airbag: Front airbags for driver and front passenger • Airbag: Side airbags for driver and front passenger and side airbags in the rear • Hill Start Assist (HAC) • Connected Services • Acoustic Vehicle Alerting System (AVAS) • High Beam Assist (AHB) • Extendable luggage compartment cover • Transmission: 1-stage reduction gear • Rear lights, LED technology • Interior mirror automatically and continuously dimming • Automatic climate control, two zones, with heat pump • Console box, front • Rear headrests (3) • Charging cable: • Steering wheel, height and reach adjustable, manually • Light sensor with follow-me-home function • Upholstery: Cloth • Radio accessories: 6 speakers • Radio accessories: USB ports, front (2) and rear (2) • Wheels: Alloy wheels, 18 inches (with aerodynamic wheel covers) • LED headlights • Seats: 2nd row of seats foldable in a 60:40 ratio • Seats: Driver's seat manually adjustable in height and length • Front sun visor with vanity mirror and lighting • LED daytime running lights • Door lock, child safety lock in the rear • Thermal insulation glazing: Tinted |
|--|--|

Extra equipment

- | | |
|---|---|
| <ul style="list-style-type: none"> • charging cable • Winter complete wheel set | <ul style="list-style-type: none"> • Mud flaps front and rear. |
|---|---|

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Tail light	Cover - lower section left side - Scratch(es) - Smart repair
2	Side panel - rear right side	Sill - Scratch(es) - Smart repair
3	Side panel - rear left side	Sill - Scratch(es) - Smart repair
4	Sill - left side	Sill - Scratch(es) - Smart repair
5	Door - front left side	Brightware - lower - Scratch(es) - Replace
6	2nd wheel set	1 tyre (Schraube im Reifen) - Damaged - Replace
7	Front bumper	Cover bumper - front - Scratch(es) - Replace
8	Rear bumper	Rear bumper - Scratch(es) - Paint
9	Front bumper	Spoiler - Scratch(es) - Replace
10	Side panel - rear left side	Side panel - Scratch(es) - Paint
11	Door - rear left side	Door - Scratch(es) - Paint
12	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Repair and paint

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres




Figure 15: Additional tyres




Figure 16: Navigation




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.





Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Damage 1: Tail light: Cover - lower section left side - Scratch(es) - Smart repair




Damage 1: Tail light: Cover - lower section left side - Scratch(es) - Smart repair



Damage 2: Side panel - rear right side: Sill - Scratch(es) - Smart repair




Damage 2: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 2: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Sill - Scratch(es) - Smart repair




Damage 3: Side panel - rear left side: Sill - Scratch(es) - Smart repair




Damage 3: Side panel - rear left side: Sill - Scratch(es) - Smart repair




Damage 4: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 4: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 4: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 4: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 4: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 5: Door - front left side: Brightware - lower - Scratch(es) - Replace



Damage 5: Door - front left side: Brightware - lower - Scratch(es) - Replace



Damage 5: Door - front left side: Brightware - lower - Scratch(es) - Replace



Damage 5: Door - front left side: Brightware - lower - Scratch(es) - Replace




Damage 6: 2nd wheel set: 1 tyre (Schraube im Reifen) - Damaged - Replace



Damage 6: 2nd wheel set: 1 tyre (Schraube im Reifen) - Damaged - Replace



Damage 6: 2nd wheel set: 1 tyre (Schraube im Reifen) - Damaged - Replace



Damage 7: Front bumper: Cover bumper - front - Scratch(es) - Replace



Damage 7: Front bumper: Cover bumper - front - Scratch(es) - Replace




Damage 7: Front bumper: Cover bumper - front - Scratch(es) - Replace



Damage 7: Front bumper: Cover bumper - front - Scratch(es) - Replace



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 9: Front bumper: Spoiler - Scratch(es) - Replace



Damage 9: Front bumper: Spoiler - Scratch(es) - Replace



Damage 9: Front bumper: Spoiler - Scratch(es) - Replace




Damage 9: Front bumper: Spoiler - Scratch(es) - Replace




Damage 9: Front bumper: Spoiler - Scratch(es) - Replace



Damage 9: Front bumper: Spoiler - Scratch(es) - Replace



Damage 10: Side panel - rear left side: Side panel - Scratch(es) - Paint




Damage 10: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 10: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 10: Side panel - rear left side: Side panel - Scratch(es) - Paint




Damage 11: Door - rear left side: Door - Scratch(es) - Paint



Damage 11: Door - rear left side: Door - Scratch(es) - Paint



Damage 11: Door - rear left side: Door - Scratch(es) - Paint



Damage 11: Door - rear left side: Door - Scratch(es) - Paint




Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint




Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: JTMAABAA70A008336

Hersteller / Modell: TOYOTA TOYOTA bZ4X Comfort- und Technik-Paket

Datum	KM-Stand	Beschreibung
08.07.2025	19.196	Bremsflüssigkeit; Regelwartungsdienst; Wartung Sonstiges
11.06.2024	10.507	Regelwartungsdienst; Wartung Sonstiges