



Expertise

Protocol number: 44529452  
Order number / reference: 26003252  
Inspection date: 17 Mar 2026

Manufacturer: Ford

Model: Mondeo Turnier 2.0 EcoBlue Aut. Titanium

VIN: WF0FXXWPCFMR38091



| Vehicle details                               |                          |
|-----------------------------------------------|--------------------------|
| Manufacturer / Type / Model / Equipment       |                          |
| Ford Mondeo Turnier 2.0 EcoBlue Aut. Titanium |                          |
| Vehicle Identification number                 | WF0FXXWPCFMR38091        |
| Mileage (Read)                                | 162,125 km               |
| First registration                            | 28 Jul 2021              |
| Number of holders                             | 1                        |
| Power / Engine displacement                   | 110 kw / 1,995 ccm       |
| Fuel type / Cylinder                          | Diesel / 4               |
| Gearbox / Number of gears                     | Automatic / 8            |
| Type of drive                                 | Front drive              |
| Type of vehicle                               | Station wagon            |
| Colour / colour code                          | Magnetic-Grau (Metallic) |
| Doors / Seats                                 | 5 / 5                    |
| Upholstery type                               | Cloth                    |
| Colour of upholstery                          | Anthracite-Black         |



## Vehicle details

|                                                  |                              |                                |                                                           |
|--------------------------------------------------|------------------------------|--------------------------------|-----------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | digital proof / complete     | <b>Next maintenance in</b>     | 60 %                                                      |
| <b>Last maintenance on / at</b>                  | 06/2025 at 150,015 km        |                                |                                                           |
| <b>Key is / should be</b>                        | 2 / 2                        | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available |
|                                                  |                              | <b>Letter No.</b>              | GD552436                                                  |
| <b>Previous damage / Accident</b>                | Detectable                   | <b>Repainting</b>              | Detectable                                                |
| <b>Inspection conditions</b>                     | sufficient                   | <b>Lifting equipment / pit</b> | yes                                                       |
| <b>Test drive</b>                                | Not performed                | <b>Engine function test</b>    | Performed                                                 |
| <b>Manufacturer key number/ type code number</b> | 8566 / BJB 00111             |                                |                                                           |
| <b>Emission standard</b>                         | EURO6;WLTP;AP;PI/CI; M, N1 I | <b>Fine dust sticker</b>       |                                                           |
| <b>Permitted total weight</b>                    | 2,330 kg                     | <b>Empty weight</b>            |                                                           |

## Tyres

### Mounted tyres

| #  | Tyre size      | Type of tyre                | Manufacturer | Tread depth |
|----|----------------|-----------------------------|--------------|-------------|
| 1) | 215/60 R16 99H | Winter tyres on Light alloy | Goodyear     | 6mm / 6mm   |
| 2) | 215/60 R16 99H | Winter tyres on Light alloy | Goodyear     | 6mm / 6mm   |

### Additional tyres

| #  | Tyre size      | Type of tyre                | Manufacturer | Tread depth |
|----|----------------|-----------------------------|--------------|-------------|
| 1) | 215/55 R17 98V | Summer tyres on Light alloy | Continental  | 5mm / 5mm   |
| 2) | 215/55 R17 98V | Summer tyres on Light alloy | Continental  | 5mm / 5mm   |

### Replacement

| Typ | Tyre size | Type of tyre            | Manufacturer | Tread depth |
|-----|-----------|-------------------------|--------------|-------------|
|     | Tirefit   | Expiration date 06/2025 |              |             |

**Legend:** Tread depth for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel



## Equipment

### Standard equipment

- Activated carbon filter
- Anti-lock braking system (ABS) with electronic brake-force distribution (EBD)
- Attachment points for safety barriers
- Tires: 7 J x 17 alloy wheels (4) with 215/55 R 17 tires
- Tires: Tire pressure monitoring system (TPMS)
- Brake light, third
- Headliner, light
- Diesel particulate filter (DPF)
- Front door sill trim
- Electronic Safety and Stability Program (ESP)
- Lane Assistant including Lane Keeping Assist and Fatigue Warning
- High beam assistant
- Ford Easy Fuel
- FordPass Connect including eCall, live traffic information and Wi-Fi hotspot
- Luggage compartment lighting
- Transmission: 8-speed automatic transmission
- Rear window wiper
- Interior mirror automatically dimming
- Isofix mount
- Air conditioning with automatic temperature control
- Front headrests, 4-way height and tilt adjustable
- Steering wheel: multifunction leather steering wheel
- Reading lights front and rear
- MyKey key system (individually programmable second key)
- Fog light
- Emergency brake light
- Pre-Collision Assist
- Rear seat backrest, foldable, 60:40 split
- Headlight dipped beam with switch-off delay including "welcome function"
- Power steering electro-mechanical speed-dependent
- Seats: Map pocket on the passenger seat backrest
- Seats: Map pocket on the driver's seat backrest
- Seats: Front seats individually and variably heated
- 12 volt socket in the luggage compartment
- Front bumper painted in body color
- Carpet floor mats front and rear
- Lashing eyes in the luggage compartment floor
- Immobiliser
- Central locking
- Ambient lighting at the front including door storage, front door handle and footwell lighting
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated
- Tires: Tire repair kit
- Hill start assist
- Chrome decor
- Roof rails, aluminum look
- tachometer
- Electronic Shifter
- Driver information system - 25.4 cm color display (digital/analog)
- Electric windows front and rear
- Parking brake, electronic
- Ford Power start function
- Heated windscreen
- Luggage compartment cover
- Cruise control system with intelligent speed limiter
- Back window, heater
- Interior lighting with delay circuit
- Intelligent security system
- Electric child safety lock
- Headrests (3) rear, height adjustable
- LED design daytime running lights in the fog lights
- Steering column, adjustable
- Front center console with padded armrests
- Navigation: Ford Navigation including Ford SYNC 3 with AppLink, 8" touchscreen (20.3 cm screen) with DAB/DAB+
- Parking pilot system front and rear
- LED taillights
- Windscreen wipers with rain sensor
- Headlight assistant with day/night sensor
- Side skirts painted in body color
- Seats: Driver and passenger seats, 4-way manually adjustable
- Seats: Sports seats with fabric upholstery
- Start-stop system
- 12 volt socket in the front interior
- Daytime running light
- Traffic sign recognition system
- Warning system for unfastened seat belts in the front and second row
- Cigarette lighter

### Extra equipment

- Electrically swiveling trailer hitch (ESP trailer stabilization - continuous power supply - switched power supply - hill start assist)
- Anti-theft alarm system including double locking (with interior monitoring) (also with independent power supply)
- Paint finish: Magnetic Grey Metallic



- Package: Business 3 (Ford navigation system incl. Ford SYNC 3 with AppLink, 8" touchscreen (20.3 cm) with DAB/DAB+ - 8 speakers - Steering wheel controls - Bluetooth hands-free system and audio streaming - 2 USB ports - Voice control for audio and telephone - SMS text-to-speech function - Front and rear parking sensors - Adaptive LED headlights - LED headlights, adaptively steering, incl. automatic headlight range control - Sequential LED turn signals at the front - LED daytime running lights - Rearview camera)
- Fuel-operated auxiliary heater (including remote control)
- Package: Winter (Heated windscreen - Heated leather steering wheel - 230-volt socket in center console (not in conjunction with hybrid engine) - Individually and variably heated front seats - Variably heated rear bench seat)
- Side windows from 2nd row of seats and rear window, dark tinted
- Safety partition for luggage compartment, 2nd row of seats
- Seats: Ford ergonomic seat (driver and passenger seats 18-way adjustable: - length, height and angle of the seat - extendable thigh support - adjustable backrest - 4-way electrically adjustable lumbar support - fabric upholstery)

## Brief expert findings

|                      |                                                                                                                                                                              |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.    |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and a pit were available for examining the vehicle.                        |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                        |
| Engine function test | An engine test run was performed.                                                                                                                                            |

## Value reducing factors

| No. | Component group        | Description                         |
|-----|------------------------|-------------------------------------|
| 1   | Equipment              | Tirefit filler - Expired - Replace  |
| 2   | 2nd wheel set          | 1 tyre (Flanke) - Damaged - Replace |
| 3   | Door - front left side | Door - Deformed - Repair and paint  |
| 4   | Bonnet                 | Bonnet - Scratched - Paint          |

## Wear and tear

| No. | Component group | Description                                  |
|-----|-----------------|----------------------------------------------|
| 1   | Misc.           | Main inspection - No evidence - No deduction |
| 2   | Vehicle glazing | Windscreen - Stone chips - No deduction      |

The vehicle shows signs of wear commensurate with its age and use.

## Previous damages

| No. | Previous damage                                                                             | Extent of damage (Net) |
|-----|---------------------------------------------------------------------------------------------|------------------------|
| 1   | Side right, Professionally repaired, Invoice of repair done Non-existent, from 19 Sept 2023 | 4.664,44 €             |

## Accident damages

| No. | Accident          |
|-----|-------------------|
| 1   | Side - left       |
| 2   | Front, Side right |

## Repainting

| No. | Repainting                                                                             |
|-----|----------------------------------------------------------------------------------------|
| 1   | Mudguard - right side, Professionally carried out, Invoice of repair done Non-existent |



#### No. Repainting

- 2 Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent
- 3 Door - rear right side, Professionally carried out, Invoice of repair done Non-existent
- 4 Door - front right side, Professionally carried out, Invoice of repair done Non-existent

#### Paint coat thickness measurement

|                        |        |                              |        |
|------------------------|--------|------------------------------|--------|
| Mudguard - right side  | 207 µm | Side panel - rear right side | 264 µm |
| Door - rear right side | 267 µm | Door - front right side      | 230 µm |

#### Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features  
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.  
(Functional tests of driver assistance systems are not included in the scope of services!)
- a photo documentation of the vehicle

#### Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects that can no longer be attributed to normal use or wear and tear according to the underlying standard are listed in the product under value-reducing factors.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

#### Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

#### Comments

Der montierte Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



**Figure 1:** Diagonal front (left)



**Figure 2:** Diagonal front (right)



**Figure 3:** Diagonal rear (left)



**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Additional tyres




Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




**Damage 1:** Equipment: Tirefit filler - Expired - Replace



**Damage 2:** 2nd wheel set: 1 tyre (Flanke) - Damaged - Replace



**Damage 2:** 2nd wheel set: 1 tyre (Flanke) - Damaged - Replace



**Damage 3:** Door - front left side: Door - Deformed - Repair and paint



**Damage 3:** Door - front left side: Door - Deformed - Repair and paint



**Damage 3:** Door - front left side: Door - Deformed - Repair and paint



**Damage 3:** Door - front left side: Door - Deformed - Repair and paint



**Damage 4:** Bonnet: Bonnet - Scratched - Paint



**Damage 4:** Bonnet: Bonnet - Scratched - Paint



**Damage 4:** Bonnet: Bonnet - Scratched - Paint



**Damage 4:** Bonnet: Bonnet - Scratched - Paint



**Accident 1:** Side - left



**Accident 1: Side - left**



**Accident 1: Side - left**




**Accident 1: Side - left**



**Accident 1: Side - left**



**Accident 1: Side - left**



**Accident 1: Side - left**



**Accident 1: Side - left**



**Accident 1: Side - left**



**Accident 1: Side - left**




**Accident 1: Side - left**



**Accident 1: Side - left**



**Accident 1: Side - left**



**Accident 1: Side - left**



**Accident 1: Side - left**



**Accident 1: Side - left**



**Accident 1: Side - left**



**Accident 1: Side - left**



**Accident 1: Side - left**




**Accident 2: Front, Side right**




**Accident 2: Front, Side right**




**Accident 2: Front, Side right**



**Accident 2: Front, Side right**



**Accident 2: Front, Side right**



**Accident 2: Front, Side right**



**Accident 2: Front, Side right**



**Accident 2: Front, Side right**



**Accident 2: Front, Side right**



**Accident 2: Front, Side right**



**Accident 2: Front, Side right**



**Accident 2: Front, Side right**



**Accident 2: Front, Side right**



**Accident 2: Front, Side right**



**Accident 2: Front, Side right**



**Accident 2: Front, Side right**



**Accident 2: Front, Side right**



**Accident 2: Front, Side right**



**Repainting 1:** Mudguard - right side



**Repainting 2:** Side panel - rear right side



**Repainting 3:** Door - rear right side



**Repainting 4:** Door - front right side



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0FXXWPCFMR38091  
Hersteller / Modell: FORD FORD Mondeo Turnier 2.0 EcoBlue Aut. Titanium

| Datum      | KM-Stand | Beschreibung                                                                                                                                                                                                                   |
|------------|----------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 25.06.2025 | 150.015  | Bremse Sonstiges; Bremsflüssigkeit; Bremsklötze vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                                |
| 12.07.2024 | 128.263  | AU                                                                                                                                                                                                                             |
| 16.05.2024 | 120.018  | Bremse Sonstiges; Bremsklötze hinten; Bremsscheiben + Klötze h; Bremsscheiben hinten; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                    |
| 18.07.2023 | 88.765   | Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges |
| 02.12.2022 | 60.909   | Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                                          |
| 14.03.2022 | 30.401   | Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                                                                                       |