



Toyota Corolla (UKL): 2ACV030

Vinnumber:	SB1Z93BE90E196826	Versionname:	Corolla Touring Sports Plus 1.8i Hybrid 122pk/cv 5p eCVT
First Registrationdate:	23/02/2021	Fiscalpower:	
Expertise Mileage:	171816	Power Kw:	72
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	Automatic		
Transmission:			
Fueltype:	Hybrid Petrol		
Maintenance	aucune trace visible d'entretien dans le carnet, pas de témoin au tdb		
Battery functioning	Yes		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
Type of Maintenance book	Maintenance book present	Type of Tow bar	Tow bar fixed
Type of GPS storage	N.A.		

Tyres

195/65/15/91 H				
Summer tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 6,5 mm
	Re.L.	Goodyear: 7,5 mm	Re.R.	Goodyear: 7,5 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				6.5
Tyre profile depth RL				7.5
Tyre profile depth RR				7.5
Tyre size FL				195/65 R 15 91 H
Tyre size FR				195/65 R 15 91 H
Tyre size RL				195/65 R 15 91 H
Tyre size RR				195/65 R 15 91 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Interior, Not original part, Check




Door panel FL, Worn, Acceptable



Seat cover FL, Worn, Acceptable



Backrest cover FL, Worn, Acceptable



Seat cover FR, Worn, Acceptable



Seat cover FL, Stain, Cleaning



Bumper F, Scratch(es), Repair and paint (complete)



Wheel cover FL, Scratch(es), Acceptable



Wing FL, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Wheel cover RL, Scratch(es), Acceptable



Wing RL, Dent(s), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Deformed / Strained, Replace and paint



Bumper moulding R, Deformed / Strained, Replace



Charging cable (normal), Missing, Check



Charging cable (fast), Missing, Check



Wheel cover RR, Scratch(es), Acceptable



Side window trim FR, Scratch(es), Acceptable



Mirror side repeater R, Scratch(es), Acceptable



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Wheel cover FR, Scratch(es), Replace



Kenteken	2ACV030
Merk Model	Toyota Corolla Touring Sports 1.8i Hybrid 122pk/cv 5p eCVT
Brandstofsoort	Benzine
Datum deel1	2/23/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
1/14/26	151,476	luchtfilter	Vervangen
1/14/26	151,476	luchtfilter interieur	Vervangen
1/14/26	151,476	oliezeef	Vervangen
1/14/26	151,476	remvloeistof	Vervangen
9/8/25	136,395	batterij	Vervangen
9/8/25	136,395	halogeenlamp	Vervangen
9/8/25	136,395	luchtfilter interieur	Vervangen
9/8/25	136,395	oliezeef	Vervangen
9/8/25	136,395	ruitenwisserrubber achter	Vervangen
9/8/25	136,395	ruitenwisserrubber vooraan	Vervangen
5/5/25	119,563	pechverhelping buitenland	Uitvoeren
1/15/25	106,184	batterij	Vervangen
1/15/25	106,184	luchtfilter interieur	Vervangen
1/15/25	106,184	nazicht technische keuring	Uitvoeren
1/15/25	106,184	nummerplaat licht	
1/15/25	106,184	oliezeef	Vervangen
9/4/24	92,620	90000 km	Uitvoeren
9/4/24	92,620	bougie	Vervangen
9/4/24	92,620	luchtfilter	Vervangen
9/4/24	92,620	luchtfilter interieur	Vervangen
9/4/24	92,620	oliezeef	Vervangen
9/4/24	92,620	remblokken achter	Uit-/afdraaien
9/4/24	92,620	remblokken vooraan	Uit-/afdraaien
3/27/24	75,272	75000 km	Uitvoeren
3/27/24	75,272	batterij	Vervangen
3/27/24	75,272	luchtfilter interieur	Vervangen
3/27/24	75,272	oliezeef	Vervangen
3/27/24	75,272	universele lampen	Vervangen
9/20/23	61,452	60000 km	Uitvoeren
9/20/23	61,452	batterij	Vervangen
9/20/23	61,452	luchtfilter	Vervangen
9/20/23	61,452	luchtfilter interieur	Vervangen
9/20/23	61,452	oliezeef	Vervangen
9/20/23	61,452	remblokken achter	Reinigen
9/20/23	61,452	ruitenwisserrubber achter	Vervangen
9/20/23	61,452	ruitenwisserrubber vooraan	Vervangen
8/3/22	33,544	batterij	Vervangen
8/3/22	33,544	ruitenwisserrubber achter	Vervangen
3/24/22	20,103	20000 km	Uitvoeren
3/24/22	20,103	luchtfilter interieur	Vervangen

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
3/24/22	20,103	oliezeef	Vervangen