


Vehicle condition report

Vehicle data

Chassis no.	KNAB3511A LT672094	Brand	KIA	Maintenance date	-
		Model	Picanto 1.0 Mpi GT-Line Edition 4-seater	Mileage maintenance	-
Registration date	August 22, 2020	Year of construction	2020	Colour	Yellow Paint
Mileage	124,279 km	Cylinder capacity	998	Interior color	Gray
Fuel	Petrol	Body type	-	APK date	-
Number of seats	4	Transmission	Manually	Emissions	-
Number of doors	5	Number of gears	-		

Inspection data

Inspection date	August 17, 2026	Terminal	
-----------------	-----------------	----------	--



Accessories

- Air conditioning (manual)
- Cruise control
- Leather upholstery
- Navigation system
- Alloy wheels
- Metallic paint


Removable items

- Spare wheel ☒
- Parcel shelf ☒

Document list

- Manual ☒
- Maintenance booklet ☒
- Spare key ☒
- Key with remote control ☒
- Navigation software ☒

Tyres



Exterior damage

1




Element	Entry plate
Position	Rear left
Type	Dent
Scope	-
Editing	For your information

3




Element	Windscreen
Position	-
Type	Crushed stone
Scope	-
Editing	For your information

4




Element	Bumper
Position	Behind
Type	Scratch
Scope	-
Editing	Recover

5



Element	Roof
Position	-
Type	Dent
Scope	Diameter (mm) > 20
Editing	Smart Repair

6



Element	Doorman
Position	Rear right
Type	Dent with paint damage
Scope	Diameter (mm) > 20
Editing	Recover

7



Element	15' alloy rim
Position	Rear right
Type	Scratch
Scope	-
Editing	Repair flat rate

8



Element	15' alloy rim
Position	Front right
Type	Scratch
Scope	-
Editing	Repair flat rate

9



Element	Bumper
Position	For
Type	Scratch
Scope	-
Editing	Recover

10



Element	Grille trim strip
Position	Front left
Type	Scratch
Scope	-
Editing	Recover

11



Element	Hood
Position	-
Type	Crushed stone
Scope	-
Editing	For your information

12



Element	Doorman
Position	Front left
Type	Dent
Scope	Diameter (mm) > 20
Editing	Smart Repair

13



Element	Grille
Position	For
Type	Scratch
Scope	-
Editing	Recover

Interior damage

2



Element	Tailgate/trunk lining
Position	-
Type	Scratch
Scope	-
Editing	For your information

Other damage