



Expertise

Protocol number: 46566119
Order No. / Reference: 26652716
Inspection date: 16 Jul 2026

Manufacturer: Skoda
VIN: TMBLR7NP0R7026412

Model: Superb Combi 2.0 TDI 4x4 DSG Style



Vehicle details	
Manufacturer / Type / Model / Equipment	
Skoda Superb Combi 2.0 TDI 4x4 DSG Style	
Vehicle Identification number	TMBLR7NP0R7026412
Mileage (Read)	139,672 km
First registration	2 Jan 2024
Number of holders	1
Power / Engine displacement	147 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	Station wagon
Colour / colour code	Brillant-Silber Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	9,500 km
Last service on / at	02/2026 at 119,162 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV943771
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8004 / AWC 00688		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,299 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 94W	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	215/55 R17 94W	Summer tyres on Light alloy	Pirelli	6mm / 6mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98V	Winter tyres on Light alloy	Pirelli	6mm / 6mm
2)	215/55 R17 98V	Winter tyres on Light alloy	Pirelli	7mm / 7mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment



Standard equipment

- Closed storage compartments behind the wheel arches in the trunk, including cargo elements
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Anti-lock braking system (ABS)
- Dashboard in black / black, door trim in black, headliner in grey
- Electrically folding exterior mirrors
- Hill start assist
- Grey headliner
- Decorative inlay Dark Brushed
- Digital Cockpit Plus 10.2"
- Third brake light
- Easy Start (start-stop button instead of ignition lock)
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC)
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Front and rear footwell lighting
- Transmission: 7-speed dual-clutch transmission (DSG)
- Heated rear window
- Interior mirror automatically dimming
- Child safety lock for rear doors & windows, electric
- Air Care Climatronic air conditioning (2-zone)
- Front and rear headrests are height-adjustable.
- Metal loading sill protector
- LED reading lights at the front and rear of the headliner
- Steering wheel: Height and reach adjustable leather steering wheel
- Front center armrest with storage compartment
- Engine drag torque control (MSR)
- Multi-collision brake
- Rear parking sensors
- Radio: Bolero infotainment system
- Radio accessories: Voice control
- Radio accessories: Wireless SmartLink
- Umbrella compartments in the front side doors
- Tire mobility kit
- Gearshift and handbrake levers in leather
- Electromechanical power steering
- Seats: Heated front seats
- Seats: Electrically adjustable front seats
- Seats: Height-adjustable front seats
- Seats: Rear seat backrest split 60:40, foldable
- Sun visor on driver and passenger side with illuminated make-up mirror
- 12V socket in the center console, front and rear
- Telephone: Bluetooth hands-free system
- Chrome-plated elements
- Lashing eyes in the trunk
- Central locking with remote control
- Storage compartments
- Airbag, driver and switchable passenger airbag
- Airbag, head airbags
- All-wheel drive 4x4
- Traction control (ASR)
- Electrically adjustable and heated exterior mirrors
- Exterior mirrors and door handles in body color
- Illuminated glove compartment
- Hydraulic brake assist (HBA)
- Roof rails, anodized
- Diesel particulate filter and SCR catalyst
- Tachometer
- Dynamic Light Assistant (Masked Continuous High Beam)
- Electric tailgate opening
- Electronic transverse differential lock (XDS+)
- Driving light assistant and rain sensor (Easy Light Assist)
- Front radar assistant including city emergency braking function
- Cruise control system including speed limiter
- Tinted windows
- Rear window wiper including windshield washer system
- ISOFIX preparation on the outer rear seats, including top tether
- Boot cover, roll-up and removable, semi-automatic
- Radiator grille slats, frame and window surround chrome-plated
- Remote release of the rear seat backrests in the trunk
- Matrix LED headlights
- Rear center armrest with cup holders and pass-through option
- Multifunctional storage compartment under the boot cover
- LED fog lights with integrated cornering lights
- Upholstery: Cloth
- Radio accessories: Digital radio reception DAB+
- Radio accessories: USB ports at the front (Type-C) and USB charging port (Type-A) in the center armrest
- Tire pressure monitoring
- Wheels: 17" Stratos alloy wheels
- Heated windshield washer nozzles
- Superb seat belts
- Seats: Adjustable lumbar support in the front seats
- Seats: Electric operation of the front passenger seat from the rear
- SKODA Care Connect
- Start/stop system including brake energy recuperation
- 12V socket in the trunk
- Sunset (rear window and rear side windows tinted dark)
- Door sill plates
- Glazing: Acoustic glazing in the front side windows
- Immobiliser



Extra equipment

- Package: Business Columbus (Columbus navigation system - voice control - Wi-Fi hotspot - Wireless Smartlink for Apple CarPlay - 9.2" capacitive touchscreen in glass design - Phonebox - Traveller assistance system (traffic sign recognition, predictive lane keeping assist ACC, adaptive lane keeping assist, emergency and traffic jam assist) - 230 V socket and 3 USB ports, tablet holder - Infotainment Online (3-year subscription))
- Steering wheel: Heated steering wheel including paddle shifters
- Chassis: Chassis lift (15 mm increase in ride height - modified damper settings - engine underbody protection)
- Heated windshield, wireless
- Package: Assistance (Lane Change Assist - Reversing Camera - Parking Assist - Preparation for a Trailer Hitch - (Active Tire Pressure Monitoring System) - Driver Fatigue Detection)
- Paint finish: Metallic
- roof rack

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Sill - dent(s) - Smooth repair work
2	Door - front left side	Brightware - lower - Scratched - Smart repair
3	Door - rear right side	Brightware - lower - Scratched - Smart repair
4	Side panel - rear left side	Sill - Dent / paintcoat damage - Smart repair
5	Boot lid / rear door	Boot lid - dent(s) - Smooth repair work
6	Roof	Roof - dent(s) - Smooth repair work
7	Body	Body - Glued / labelled - De-glue / neutralise
8	Rear bumper	Rear bumper - Scratched - Paint
9	Front bumper	Front bumper (Lackplatzer) - Paint defect - Paint
10	Door - rear right side	Door - Scratched - Paint
11	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
12	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint
13	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint
14	Vehicle glazing	Windscreen - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Rear bumper	Spoiler - Scratched - No deduction
2	Door - front right side	Door handle - outside (Schlosskappe) - Scratched - No deduction
3	Door - rear right side	Door handle - outside - Scratched - No deduction
4	Door - front left side	Door - dent(s) - No deduction
5	Roof	Roof rail - right side - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Repainting

No. Repainting

1 Mudguard - left side

Paint coat thickness measurement

Mudguard - left side

210 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Damage 1: Side panel - rear right side: Sill - dent(s) - Smooth repair work



Damage 1: Side panel - rear right side: Sill - dent(s) - Smooth repair work



Damage 2: Door - front left side: Brightware - lower - Scratched - Smart repair



Damage 2: Door - front left side: Brightware - lower - Scratched - Smart repair



Damage 3: Door - rear right side: Brightware - lower - Scratched - Smart repair



Damage 3: Door - rear right side: Brightware - lower - Scratched - Smart repair



Damage 4: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 4: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 4: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair




Damage 5: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 5: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work




Damage 5: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work




Damage 6: Roof: Roof - dent(s) - Smooth repair work



Damage 6: Roof: Roof - dent(s) - Smooth repair work



Damage 6: Roof: Roof - dent(s) - Smooth repair work



Damage 6: Roof: Roof - dent(s) - Smooth repair work




Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 8: Rear bumper: Rear bumper - Scratched - Paint




Damage 8: Rear bumper: Rear bumper - Scratched - Paint



Damage 8: Rear bumper: Rear bumper - Scratched - Paint



Damage 8: Rear bumper: Rear bumper - Scratched - Paint



Damage 9: Front bumper: Front bumper (Lackplatzer) - Paint defect - Paint



Damage 9: Front bumper: Front bumper (Lackplatzer) - Paint defect - Paint




Damage 9: Front bumper: Front bumper (Lackplatzer) - Paint defect - Paint



Damage 9: Front bumper: Front bumper (Lackplatzer) - Paint defect - Paint




Damage 10: Door - rear right side: Door - Scratched - Paint




Damage 10: Door - rear right side: Door - Scratched - Paint




Damage 11: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 11: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 11: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 11: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 13: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 13: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 13: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 13: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 13: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 14: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 14: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 14: Vehicle glazing: Windscreen - Broken / torn - Replace



Wear and tear 1: Rear bumper: Spoiler - Scratched - No deduction



Wear and tear 1: Rear bumper: Spoiler - Scratched - No deduction



Wear and tear 2: Door - front right side: Door handle - outside (Schlosskappe) - Scratched - No deduction



Wear and tear 2: Door - front right side: Door handle - outside (Schlosskappe) - Scratched - No deduction



Wear and tear 3: Door - rear right side: Door handle - outside - Scratched - No deduction




Wear and tear 3: Door - rear right side: Door handle - outside - Scratched - No deduction



Wear and tear 4: Door - front left side: Door - dent(s) - No deduction



Wear and tear 4: Door - front left side: Door - dent(s) - No deduction



Wear and tear 5: Roof: Roof rail - right side - dent(s) - No deduction



Wear and tear 5: Roof: Roof rail - right side - dent(s) - No deduction



Wear and tear 5: Roof: Roof rail - right side - dent(s) - No deduction



Repainting 1: Mudguard - left side



Repainting 1: Mudguard - left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: TMBLR7NP0R7026412
Hersteller / Modell: SKODA SKODA Superb Combi 2.0 TDI 4x4 DSG Style

Datum	KM-Stand	Beschreibung
19.02.2026	119.162	Bremsflüssigkeit; Bremsflüssigkeit ern; Getriebeöl ern/prüfen; Motoröl b. Wartung; Ölfilter ern; Ölwechsel - Hinterachse; Regelwartungsdienst; Reparatur Sonstiges; Wartung Sonstiges
17.12.2025	109.688	Bremse Sonstiges; Bremsklötze hinten; Bremsscheiben + Klötze h; Bremsscheiben hinten
05.09.2025	89.112	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
18.07.2025	81.209	Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne
07.02.2025	59.061	Bremse Sonstiges; Bremsklötze hinten; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
09.10.2024	41.648	Bremsflüssigkeit; Systemtest/Eigendiagnose
07.08.2024	30.292	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges