



Volvo V 90:

Vinnumber:	YV1PW72TDK1106001	Versionname:	
First Registrationdate:	13/03/2019	Fiscalpower:	
Expertise Mileage:	159301	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2611
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	Tow bar collapsible
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

225/55/17/101 V				
Winter tyres:	Fr.L.	BF Goodrich: 4 mm	Fr.R.	BF Goodrich: 3 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 3 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				3.0
Tyre size FL				225/55 R 17 101 V
Tyre size FR				225/55 R 17 101 V
Tyre size RL				225/55 R 17 101 V
Tyre size RR				225/55 R 17 101 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2485
Tyre make FR				2485
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1640,08
Interior, Worn, Acceptable	0,00




Bonnet, Dent(s), Paintless dent repair 127,29



Bumper F, Scratch(es), Repair and paint (complete) 355,89



Wing RL, Scratch(es), Acceptable 0,00



Alloy rim RL, Scratch(es), Acceptable 0,00



Alloy rim FL, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Repair and paint (complete) 355,89






Rear light R, Waterinfiltration, Acceptable 0,00



Rear light L, Scratch(es), Polish 0,00




Rear window, Scratch(es), Replace 0,00



Alloy rim FR, Scratch(es), Repair and paint (complete) 133,03



Wing FR, Scratch(es), Acceptable 0,00



Door FR, Scratch(es), Acceptable 0,00





Door RR, Dent(s) and scratch(es), Repair and paint (complete) 534,95



Door FR, Scratch(es), Acceptable 0,00



Wing RR, Scratch(es), Acceptable 0,00



Alloy rim RR, Scratch(es), Repair and paint (complete) 133,03

