

Description form

Commission

Country of provider  The Netherlands
Commission on purchase €150.00

License plate: [\(chassis number: TMBJR9NE7L0077424\)](#)



SKODA OCTAVIA COMBI 1.5 TSI GREENTECH BUSINESS EDI AUT/ECC/NAV/HALF-LEER/LMV/PDC

Specification according to lease software: 1.5tsi Greentech Business Edition Plus 110kW DSG-7 automatic

Mileage	146,890 km	Type of vehicle	Passenger car	Empty weight	1217 kg
Tank/ Loading capacity		Colour	Black	VAT/Margin	VAT
Fuel	Petrol	Number of doors	5		
Transmission	Automatic	Drive	Front wheel		
Date of first admission	19-08-2020	Number of cylinders	4	Wheelbase	269 cm
Date of first issue NL	19-08-2020	Assets	110 kW	Load capacity	-
First registration	The Netherlands	CO2 emissions	143 g/km	MOT up to and including	19-08-2026

Options specified by inspector

Metallic paint, Climate Control / ECC, 17-inch alloy wheels, Cruise control, Connectivity, Navigation option_other (factory fitted), Audio option_other (factory fitted), Half leather upholstery, Heated seats, Rear Park Distance Control, Roof rails

Inspection

Present at the car

- ✓ Master key
- ✓ Jack
- ✓ Instruction booklet
- ✓ Spare key
- ✓ Spare wheel
- ✓ Parcel shelf/roller cover
- ✓ Maintenance booklet (Digital)

Interior details

Number of seats	: 5	Number of headrests	: 5
Clean inside	: Yes	Normal smell	: Yes
Front seats damaged	: Yes, wear and tear	Windscreen	: Needs attention, replace

Exterior features

Clean on the outside	: Yes	Door frames damaged	: Yes, scratch(es)
User scratches	: Yes	Restyling dents	: Yes
Crushed stone	: Yes		

Tyres

Band	Estimated profile	Kind	Brand	Mate
LV	4 mm	Winter	Continental	225/45 R17
RV	4 mm	Winter	Continental	225/45 R17
LA	4 mm	Winter	Continental	225/45 R17

RA 4 mm Winter Continental 225/45 R17

Number of hubcaps/LMVs LMV
Quantity damaged 0
Dealer maintained Yes
Test drive conducted by inspector No
Has the car ever been used for special purposes? No
Does the car have a deviating BPM depreciation? No

Technical condition Good

Additional details

Damage

Part:
Hood
Description:
Small dent
Solution provided:
Restyling and touching up



Part:
Roof
Description:
Bird droppings
Solution given:
Touch up and polish



Part:
Rear bumper
Description:
Damage with dent
Provided solution:
Repair and paint




Part:
Windshield
Description:
Crack
Given solution:
Replace




Part:
Right taillight
Description:
Crack
Given solution:
Replace



Part:
Upholstery
Description:
Wear
Given solution:
Repair



Part:
Tailgate
Description:
Damage with dent
Provided solution:
Repair and paint



Additional photos



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo




Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo

Documents

No documents found.
