



Expertise

Protocol number: 47130851
Order No. / Reference: 26769473
Inspection date: 18 Aug 2026

Manufacturer: Ford	Model: Mondeo Turnier 2.0 EcoBlue Aut. Titanium
VIN: WF0FXXWPCFNS70173	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Mondeo Turnier 2.0 EcoBlue Aut. Titanium	
Vehicle Identification number	WF0FXXWPCFNS70173
Mileage (Read)	135,496 km
First registration	3 May 2022
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Blue Metallic
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Anthracite



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	54 %
Last service on / at	11/2025 at 121,700 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GK800905
Previous damage / Accident	None detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BJB 00111		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,330 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R18 98Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	235/55 R18 98Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 99H	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	215/60 R16 99H	Winter tyres on Light alloy	Pirelli	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Activated carbon filter
- Anti-lock braking system (ABS) with electronic brake force distribution (EBD)
- Attachment points for safety partition grilles
- Tires: 7 J x 17 alloy wheels (4) with 215/55 R 17 tires
- Tires: Tire pressure monitoring system (TPMS)
- third brake light
- headliner, light
- Diesel particulate filter (DPF)
- Front door sill trim
- Electronic Safety and Stability Program (ESP)
- Lane keeping assist including lane keeping assist and driver fatigue warning
- High Beam Assist
- Ford Easy Fuel
- FordPass Connect including eCall, live traffic information and Wi-Fi hotspot
- Luggage compartment lighting
- Transmission: 8-speed automatic transmission
- rear window wiper
- Interior mirror automatically dimming
- Isofix bracket
- Air conditioning with automatic temperature control
- Front headrests, 4-way height and tilt adjustable
- Steering wheel: Multifunction leather steering wheel
- Reading lights front and rear
- MyKey key system (individually programmable second key)
- Fog light
- Emergency brake light
- Pre-Collision Assist
- Rear seat backrest, foldable, 60:40 split
- Headlight dipped beam with switch-off delay including "greeting function"
- Electromechanical speed-dependent power steering
- Seats: Map pocket on the back of the front passenger seat
- Seats: Map pocket on the driver's seat backrest
- Seats: Front seats can be heated individually and variably.
- 12-volt power outlet in the luggage compartment
- Front bumper painted in body color
- Carpet floor mats front and rear
- Lashing eyes in the luggage compartment floor
- Immobiliser
- Central locking
- Ambient lighting in the front, including door storage compartment, front door handle and footwell lighting.
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated
- Tires: Tire repair kit
- Hill start assist
- Chrome decor
- Roof rails, aluminum look
- Tachometer
- Electronic Shifter
- Driver information system - 25.4 cm color display (digital/analog)
- Electric windows front and rear
- Electronic parking brake
- Ford Power Start function
- Heated windshield
- luggage compartment cover
- Cruise control system with intelligent speed limiter
- Back window, heater
- Interior lighting with delay circuit
- Intelligent security system
- Electric child safety lock
- Rear headrests (3), height adjustable
- LED design daytime running lights in the fog lights
- Adjustable steering column
- Front center console with padded armrests
- Navigation: Ford Navigation including Ford SYNC 3 with AppLink, 8" touchscreen (20.3 cm screen) with DAB/DAB+
- Front and rear parking pilot system
- LED taillights
- Windscreen wipers with rain sensor
- Headlight assistant with day/night sensor
- Side skirts painted in car color
- Seats: Driver and passenger seats, 4-way manually adjustable
- Seats: Sports seats with fabric upholstery
- Start-stop system
- 12-volt socket in the front interior
- Daytime running light
- Traffic sign recognition system
- Warning system for unfastened seat belts in the front and second row of seats
- Cigarette lighter



Extra equipment

- Paint finish: Metallic
- Safety partition net behind the 2nd row of seats for the luggage compartment
- Tires: 8 J x 18 alloy wheels (4) with 235/45 R 18 tires (10 x 2-spoke design in Flash Grey)
- Upholstery: Premium leather (seat center panels in leather, seat back and side bolsters in leather look - driver's seat, 10-way electrically adjustable with memory function - passenger seat, 10-way electrically adjustable)
- Package: Business 2 (Automatic) (Sony Navigation including Ford SYNC 3 with AppLink and 8" (20.3 cm) touchscreen with Premium Sound System, 12 Sony speakers and DAB/DAB+ radio, reversing camera, parking assistant with parallel and perpendicular parking sensors including front and rear parking sensors, blind spot information system including cross traffic alert and dynamic distance detection, power tailgate, adaptive LED headlights, adaptive LED headlights with automatic headlight range control, LED daytime running lights, adaptive cruise control, traffic jam assist with stop & go function)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Gearbox	Gearbox - Leaking - Perform diagnosis
3	Door - front left side	Door edge - Scratch(es) - Smart repair
4	Sill - left side	Sill - dent(s) - Smooth repair work
5	Door - rear left side	Door - dent(s) - Smooth repair work
6	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
7	Door - rear right side	Door - Scratch(es) - Smart repair
8	Engine	Engine cover - Damage caused by marten / rodent - Replace
9	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
10	Equipment	Storage compartment (Brillenfach öffnet/ schließt nicht richtig) - Damaged - Replace
11	Seat - front	armrests - Damaged - Replace
12	Wheel / tyres	Alloy rim - rear right side (Materialabtrag) - Scratched - Replace
13	Wheel / tyres	Alloy rim - rear left side (Materialabtrag) - Scratched - Replace
14	Boot lid / rear door	Boot lid - Scratched - Repair and paint
15	Door - front right side	Door - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Rear bumper	Rear bumper - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Repainting

No. Repainting

1 Mudguard - right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Mudguard - right side 159 µm |

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Der beiliegende Winterradsatz ist kein Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Gearbox: Gearbox - Leaking - Perform diagnosis




Damage 2: Gearbox: Gearbox - Leaking - Perform diagnosis




Damage 2: Gearbox: Gearbox - Leaking - Perform diagnosis




Damage 3: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 3: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 4: Sill - left side: Sill - dent(s) - Smooth repair work



Damage 4: Sill - left side: Sill - dent(s) - Smooth repair work



Damage 5: Door - rear left side: Door - dent(s) - Smooth repair work




Damage 5: Door - rear left side: Door - dent(s) - Smooth repair work



Damage 6: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 6: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 6: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 7: Door - rear right side: Door - Scratch(es) - Smart repair




Damage 7: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 8: Engine: Engine cover - Damage caused by marten / rodent - Replace




Damage 8: Engine: Engine cover - Damage caused by marten / rodent - Replace



Damage 8: Engine: Engine cover - Damage caused by marten / rodent - Replace



Damage 9: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 9: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 10: Equipment: Storage compartment (Brillenfach öffnet/schließt nicht richtig) - Damaged - Replace



Damage 10: Equipment: Storage compartment (Brillenfach öffnet/schließt nicht richtig) - Damaged - Replace



Damage 10: Equipment: Storage compartment (Brillenfach öffnet/schließt nicht richtig) - Damaged - Replace



Damage 11: Seat - front: armrests - Damaged - Replace



Damage 11: Seat - front: armrests - Damaged - Replace



Damage 12: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratched - Replace



Damage 12: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratched - Replace



Damage 12: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratched - Replace




Damage 13: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Scratched - Replace




Damage 13: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Scratched - Replace



Damage 13: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Scratched - Replace



Damage 13: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Scratched - Replace



Damage 14: Boot lid / rear door: Boot lid - Scratched - Repair and paint



Damage 14: Boot lid / rear door: Boot lid - Scratched - Repair and paint



Damage 14: Boot lid / rear door: Boot lid - Scratched - Repair and paint



Damage 14: Boot lid / rear door: Boot lid - Scratched - Repair and paint



Damage 14: Boot lid / rear door: Boot lid - Scratched - Repair and paint




Damage 14: Boot lid / rear door: Boot lid - Scratched - Repair and paint



Damage 15: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 15: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 15: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 15: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 15: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Repainting 1: Mudguard - right side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0FXXWPCFNS70173
Hersteller / Modell: FORD FORD Mondeo Turnier 2.0 EcoBlue Aut. Titanium

Datum	KM-Stand	Beschreibung
13.11.2025	121.700	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
15.05.2025	101.073	AU; Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne
17.01.2025	89.587	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
23.12.2024	88.142	Batterie ern; Systemtest/Eigendiagnose
23.02.2024	61.023	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
12.04.2023	31.332	Motoröl b. Wartung; Regelwartungsdienst