



Expertise

Protocol number: 44485542
Order number / reference: 26040586
Inspection date: 16 Mar 2026

Manufacturer: Opel

Model: Grandland 1.2 DI Automatik GS

VIN: W0VZRHNS7R6025919



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Grandland 1.2 DI Automatik GS	
Vehicle Identification number	W0VZRHNS7R6025919
Mileage (Read)	8,398 km
First registration	19 Aug 2024
Number of holders	1
Next periodical technical inspection	08/2027
(Report not on hand)	
Power / Engine displacement	96 kw / 1,199 ccm
Fuel type / Cylinder	Petrol / 3
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Diamant Schwarz (M2)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black
Re/Import	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	Available / incomplete	Next maintenance in	0 km
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		Letter No.	HB481828
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	1844 / AAN 00266		
Emission standard	EURO6;WLTP;EA;PI/CI;M, N1, N2	Fine dust sticker	
Permitted total weight	2,000 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R18 102V	All-season tyres on Light alloy	Goodyear	6mm / 6mm
2)	225/55 R18 102V	All-season tyres on Light alloy	Goodyear	6mm / 6mm

Legend: Tread depth for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel

Equipment

Standard equipment

- 2 ignition keys, both foldable
- Airbag driver and passenger side
- Airbag: Head airbags, front and rear outside
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Hill Start Assist
- On-board computer
- Decorative strips, Dax/Palladium Medium
- Electric parking brake
- Electronic Stability Program Plus (ESP Plus)
- Front collision warning
- Transmission: 8-speed automatic
- Rear window wiper
- Interior rearview mirror, automatically dimming
- Dual-zone automatic climate control including rear footwell heating
- Leather steering wheel, flattened, with steering wheel remote controls
- Illuminated makeup mirror in sun visor, for driver and front passenger
- Gasoline particulate filter
- Front and rear parking sensors
- Rain sensor
- Wheels: Tire repair kit
- Side windows heavily tinted
- Seat belts
- Seats: Rear seat backrest in 40:60 split and foldable
- Seats: Heated seats, multi-stage, driver and front passenger
- Bumpers painted in high-gloss black
- Traction control TC Plus
- Preparation for ISOFIX child seat fastening system, including Top Tether fastening eyes, rear outside
- Central locking with radio remote control and interior switches
- Storage compartments
- Airbag: Front and side airbags
- Ambient lighting, center console and front door pockets
- Automatic activation of the hazard warning lights
- Exterior mirrors, electrically adjustable and heated, electrically folding
- Roof design line in black
- Third brake light
- Electronic brake force distribution (EBD)
- Electric windows front and rear
- Cruise control with intelligent speed limiter
- Heated rear window
- Interior lighting, front and rear
- Child safety lock in the rear doors, manual
- Headrests (3) rear, height adjustable
- Front headrests, height adjustable
- Steering wheel, height and length adjustable
- Steering wheel: Heated premium steering wheel, vegan
- Center armrest, movable, front, including storage compartment and cup holder
- Package: Style Package
- Radio accessories: Digital radio reception DAB+
- Tire pressure warning
- Reversing camera including parking assistant
- Power steering, speed-dependent
- Seats: Ergonomic active seat with AGR seal of approval, driver and front passenger
- Start/Stop system
- socket, 12 volts
- Blind spot warning system
- Underbody protection look, front and rear, in high-gloss black
- Immobiliser

Extra equipment

- 360-degree camera (Automatic parking assistant (recognition of parallel and perpendicular parking spaces at a driving speed below 20 km/h, exiting from parallel parking spaces, automatic steering of the vehicle), including parking pilot, front and rear parking aid with audiovisual warning - electrically folding exterior mirrors - blind spot warning in both exterior mirrors (active between 12 km/h and 140 km/h))
- Wheels: Light alloy 7.5 J x 18 with 5 spokes in grey (all-weather tires 225/55 R 18 - preparation for run-flat tires)
- Detachable trailer hitch (trailer stability program)
- Paint finish: metallic
- Package: Infotainment package (Multimedia Navi Pro with 10" touchscreen color display - OpelConnect (incl. emergency call/breakdown call, vehicle status) - Wireless Charging)
- Package: Tech Package Pro (Keyless locking and starting system "Keyless open & start" - Electric tailgate - IntelliLux LED® Pixel Matrix light, Adaptive LED pixel matrix headlights with individual light distribution and fog lights)
- safety net



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for examining the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance (Unvollständig) - No evidence - No deduction
2	Misc.	Inspection / maintenance - Due - Perform

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Front bumper	Front bumper - Stone chips - No deduction
4	Interior	Interior - Scratch(es) - No deduction
5	Rear bumper	Rear bumper - Scratch(es) - No deduction

The vehicle shows signs of wear commensurate with its age and use.

Missing parts

Description

Trim / covers - Floor mats (Komplett)

Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
(*Functional tests of driver assistance systems are not included in the scope of services!*)
- a photo documentation of the vehicle



Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects that can no longer be attributed to normal use or wear and tear according to the underlying standard are listed in the product under value-reducing factors.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich.
- Es wurde keine Ausstattungsliste übermittelt.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Damage 2: Misc.: Inspection / maintenance - Due - Perform




Missing part 1: Trim / covers: Floor mats (Komplett) - Missing - Replace



Missing part 1: Trim / covers: Floor mats (Komplett) - Missing - Replace



Missing part 1: Trim / covers: Floor mats (Komplett) - Missing - Replace



Missing part 1: Trim / covers: Floor mats (Komplett) - Missing - Replace