



Expertise

Protocol number: 46681268
Order No. / Reference: 26765854
Inspection date: 23 Jul 2026

Manufacturer: Volkswagen

Model: ID.3 Performance Upgrade Pro Business

VIN: WVVZZZE1ZMP067455



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen ID.3 Performance Upgrade Pro Business	
Vehicle Identification number	WVVZZZE1ZMP067455
Mileage (Read)	62,080 km
First registration	30 Jun 2021
Number of holders	2
Fuel type	Electric
Power	70 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Saloon car
Colour / colour code	Scala Silver Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Grey-Anthracite
Roof colour	Schwarz
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	Available / complete	Next maintenance in	357 Tag(e)
Last service on / at	07/2025 at 52,784 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GC242358
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0603 / CKV 00017		
Emission standard	2017/1151	fine dust sticker	
Permitted total weight	2,270 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R18 95T	Summer tyres on Steel rim with wheel cover	Goodyear	7mm / 7mm
2)	215/55 R18 95T	Summer tyres on Steel rim with wheel cover	Goodyear	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R18 95T	Winter tyres on Steel rim with wheel cover	Continental	6mm / 6mm
2)	215/55 R18 95T	Winter tyres on Steel rim with wheel cover	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
Tirefit		Expiration date 04/2030		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- 30-color ambient lighting
- App-Connect including App-Connect Wireless for Apple CarPlay and Android Auto
- Electrically adjustable, folding, and heated exterior mirrors, passenger-side mirror lowering function
- Car2X
- Dynamic Light Assist high beam control
- e-Sound
- Electronic Stability Program (ESP)
- Transmission: Direct drive, 1-speed
- rear window wiper
- ISOFIX mounting points
- Headrests (5) front and rear
- Charging: 100 kW direct current (DC) charging capacity
- LED matrix headlights
- Illuminated strip between headlights and door handle recesses
- Center console with illuminated storage compartment and roller blind
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Upholstery in "Flow" fabric
- Radio: "Ready 2 Discover"
- Radio accessories: 2 USB-C ports at the front, 2 USB-C charging ports at the rear of the center console
- Tire pressure monitoring system (passive)
- Wheels: Tire Mobility Set with 12-volt compressor and tire sealant
- Keyless locking and starting system "Keyless Access" with safe locking mechanism
- Seat belts: Three-point automatic seat belts at the front with belt tensioners
- Seats: Armrests, front seats
- Seats: Front seats are height-adjustable
- "Comfort" telephone interface with inductive charging function
- Traffic sign recognition
- Electronic immobilizer
- Airbag: Front head and side airbags, with center airbag
- Anti-lock braking system (ABS)
- Adaptive Cruise Control (ACC) "stop & go", including speed limiter
- Vehicle tool kit
- third brake light
- Anti-theft alarm system with interior monitoring, backup horn and tow-away protection
- Parking assistance
- Driving profile selection
- Rear window heated
- Interior mirror automatically dimming
- "Climatronic" air conditioning system
- Mode 3 Type 2 charging cable, 16 A
- Charging: 11 kW AC charging capacity
- LED taillights with dynamic turn signals
- Steering wheel: Multifunction steering wheel in leather
- Illuminated makeup mirrors in the sun visors
- Fatigue detection
- Navigation system "Discover Pro"
- eCall emergency call system
- Stainless steel pedals
- Proactive occupant protection system in conjunction with "Front Assist"
- Radio accessories: 4 + 1 speakers
- Rain sensor
- Wheels: 4 steel wheels 7.5 J x 18
- Rear View reversing camera
- Automatically heated front windshield washer nozzles
- Rear side windows and rear window tinted
- electromechanical power steering
- Seats: 3 rear seats, rear seat backrest asymmetrically split and foldable
- Seats: Heated front seats
- Lane keeping assistant "Lane Assist"
- Ambient lighting with logo projection
- First aid kit, warning triangle and high-visibility vest
- Warning tone and light for unfastened seat belts front and rear

Extra equipment

- Two-tone paintwork with black roof, metallic
- Wheels: 4 winter steel wheels 7.5 J x 18 (additional) (Airstop winter tires 215/55 R 18 T - wheel locking with extended theft protection)
- Charging cable: Mains charging cable for household socket
- Textile floor mats front and rear
- Heat pump for range optimization



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Door trim - rear left side - Soiled - Clean
2	Rear bumper	Rear bumper - Scratch(es) - Smart repair

Wear and tear

No.	Component group	Description
1	Side panel - rear right side	Side panel - Scratch(es) - No deduction
2	Side panel - rear left side	Sill - Scratch(es) - No deduction
3	Front bumper	Front bumper - Stone chips - No deduction
4	Bonnet	Bonnet - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Professionally repaired, Invoice of repair done Non-existent, from 4 Oct 2022	1.401,62 €
2	Side right, Professionally repaired, Invoice of repair done Non-existent, from 13 Oct 2022	2.030,93 €

Repainting

No.	Repainting
1	Mudguard - right side, Professionally carried out, Invoice of repair done Non-existent
2	Door - rear left side, Professionally carried out, Invoice of repair done Non-existent
3	Door - rear right side, Professionally carried out, Invoice of repair done Non-existent
4	Door - front left side, Professionally carried out, Invoice of repair done Non-existent
5	Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Mudguard - right side	208 µm	Door - rear left side	211 µm
Door - rear right side	209 µm	Door - front left side	202 µm
Door - front right side	170 µm		



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Professionally repaired previous damages were found at the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Damage 1: Trim / covers: Door trim - rear left side - Soiled - Clean




Damage 1: Trim / covers: Door trim - rear left side - Soiled - Clean



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Wear and tear 3: Front bumper: Front bumper - Stone chips - No deduction




Wear and tear 3: Front bumper: Front bumper - Stone chips - No deduction



Wear and tear 3: Front bumper: Front bumper - Stone chips - No deduction



Wear and tear 4: Bonnet: Bonnet - Scratch(es) - No deduction



Wear and tear 4: Bonnet: Bonnet - Scratch(es) - No deduction



Repainting 1: Mudguard - right side



Repainting 2: Door - rear left side



Repainting 3: Door - rear right side



Repainting 4: Door - front left side



Repainting 5: Door - front right side