

Condition Report

DEKRA/ /20260507

Ordered By

Ordered By

Vehicle

License Plate		Contract Number		Bodywork Type	Limousine	Transmission	Automatic
Brand	SKODA	VIN	TMBAH7NP8N7052535	Drive Wheel	Front-wheel-drive	First Registration	2022.07.12
Model	Superb	Year Built	2022	Color	Grey	Fuel Type	Diesel
Label	-	Capacity	1.968 cm3	Power	110 kW	Mileage	86.163 km
MOT	2026.07.12						

Equipment

- Automatic air conditioning / digital
- Electrically adjustable front and rear windows
- Multifunction steering wheel
- ESP / DSC
- ASD / EDS / ASR

Documents

- Original Key
- Registration Book
- Vehicle Manual
- Spare tire

Wheels

Position	Rim Type	Dimensions	Thread Depth
FL	Könnyűfém	215/55R17	5.00
FR	Könnyűfém	215/55R17	5.00
RL	Könnyűfém	215/55R17	5.00
RR	Könnyűfém	215/55R17	5.00
SP	Acél	205/55R16	8.00

Paint Thickness [µm]

Part	Left Value	Right Value
Front mudguard	121	225
Engine cover	146	0
Front door	115	182
Rear door	118	173
Roof	131	0
Rear mudguard	113	119
Luggage compartment lid / Rear door	113	0

Last Service

Type	Date	KM
------	------	----


Standard Images








Unacceptable Damage


Első vészháritó

					
Part	Első vészháritó	Damage	Scratched	Repair Method	Painting

Karosszéria

					
					
					
Part	Karosszéria	Damage	Scratched	Repair Method	Polishing

Karosszéria



Part	Karosszéria	Damage	Hail damaged	Repair Method	Smart repairment
------	-------------	--------	--------------	---------------	------------------

Fényezett elemek

No images or videos available.

Part	Fényezett elemek	Damage	Repair Method	Preparation and painting
------	------------------	--------	---------------	--------------------------

Special Notes

A gépjármű szennyezett volt.
A gépjármű jégvert, a pontos kalkuláció csak műhelykörülmények között pontosítható!

Inspection Details

Inspection Place		Inspection Person		Inspection Date	2026.05.05
------------------	--	-------------------	--	-----------------	------------

This condition report was prepared by an expert of DEKRA-Expert Kft.
The vehicle inspection was carried out by external visual examination. No test drive was performed and no parts were disassembled during the inspection.
The calculation of unacceptable defects and deficiencies was prepared using data from the Audatex and Eurotax calculation programs.
The expert inspection was carried out in accordance with DEKRA regulations, applying the client's guidelines regarding acceptable and unacceptable defects and deficiencies for returned vehicles.