




2-esy-944

2-ESY-944 · ST-line 1.0i Ecoboost 100pk 74kw · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-ESY-944	Fuel Type	Gasoline
Manufacturer	FORD	VIN	WF0JXXGAHJPL42100
Model	Fiesta	Cylinder Capacity	998 ^{cm3}
Model Versions	ST-line 1.0i Ecoboost 100pk 74kw	Transmission Type	Handmatig geschakelde transmissie
Body Type	5 door hatchback	First Admission	18-01-2024
Color	Grey	Odometer	74.405 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	74	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Leather steering wheel

Rear parking sensors

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate


Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications


Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 ^{mm}	Continental	205 ^{mm}	45 ^{mm}	17 ^{inch}	Summer
Rear Left	4 ^{mm}	Westlake	205 ^{mm}	45 ^{mm}	17 ^{inch}	All Season
Front Right	2 ^{mm}	Continental	205 ^{mm}	45 ^{mm}	17 ^{inch}	Summer
Rear Right	4 ^{mm}	Continental	205 ^{mm}	45 ^{mm}	17 ^{inch}	Summer
Spare Tire Type	Compressor					

Damages



Damage Part

Skirt – Right



Damage Type

Small scratch(es)

Repair Type

Spray

Acceptable

No



Damage Part

Alloy – Right Front



Damage Type

Damaged

Repair Type

Rim repair


Acceptable

No



Damage Part

Bumper – Front



Damage Type

Scratch(es)



Repair Type

Spray

Acceptable

No



Damage Part
Alloy - Left Front



Damage Type
Damaged

Repair Type
Rim repair

Acceptable
No



Damage Part
Frontdoor - Left



Damage Type
Door-edge chipped

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Interior



Damage Type
Stains & dirt

Repair Type
Cleaning

Acceptable
No



Damage Part

Fender – Rear Left



Damage Type

Small scratch(es)

Repair Type

Acceptable

Acceptable

Yes