



Expertise

Protocol number: 46617204
Order No. / Reference: 26712657
Inspection date: 17 Jul 2026

Manufacturer: Porsche

Model: Panamera 4 E-Hybrid Platinum Edition

VIN: WP0ZZZ97ZNL126611



Vehicle details	
Manufacturer / Type / Model / Equipment	
Porsche Panamera 4 E-Hybrid Platinum Edition	
Vehicle Identification number	WP0ZZZ97ZNL126611
Mileage (Read)	149,255 km
First registration	19 Jul 2022
Number of holders	1
Next periodical technical inspection	07/2027
(Report on hand)	
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	2,894 ccm / 6
Power	243 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	Saloon car
Colour / colour code	Tiefschwarz (C9X)
Doors / Seats	5 / 4
Upholstery type	Leather
Colour of upholstery	Black
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	8,800 km
Last service on / at	12/2025 at 128,024 km		
Key is / should be	3 / 3	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GM313409
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	short drive on the company premises	Engine function test	Performed
Manufacturer key number/ type code number	0583 / AJS 00052		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,710 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	275/40 R20 106Y	Summer tyres on Light alloy	Pirelli	4mm / 4mm
2)	315/35 R20 110Y	Summer tyres on Light alloy	Pirelli	4mm / 4mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment



Equipment

- 2-layer mineral - Deep black (C9X)
- 3-spoke multifunction steering wheel, heated
- 8-speed automatic transmission for all-wheel drive
- from 01.2022
- Storage package
- activated carbon container
- All-wheel drive
- Aluminum package, black
- Silver exhaust trim
- Electrically adjustable/folding/automatically dimming exterior mirrors with memory function
- Exterior mirrors, automatically dimming, electrically folding/adjustable and separately heated & memory
- Components of the basic V6 Bi-Turbo 2.9 liter engine
- Cup holders in the driver's cab
- Operating permit, initial registration
- Black
- BOSE® Surround Sound System
- Front brake 18 inch
- CLIMATRONIC
- Decorative inlays, black anodized aluminum
- Deletion of Logo on Front Doors
- Digital clock
- Dual-tone signal horn
- Entry and exit comfort lighting
- Use for unleaded refueling
- Electrical interface AUX-IN and USB/IPOD
- Standard suspension
- Windscreen, heat-insulating glass with tint stripe
- Pedestrian protection extended
- front and rear floor mats
- luggage compartment cover
- Glass, dark tinted in the background
- Mobile phone preparation with coupling box
- Head-up display
- Exclusive Design taillights
- Rear axle "Standard"
- Premium rear seats (40/20/40) Comfort
- Industrial charging cable, CEE 16A/400V/6H
- Interior lighting package
- Interior sound measures
- Front license plate holder (large)
- Comfort features
- Comfort seats in the front
- Fuel tank
- Fuel system: Otto direct injection (FSI)
- Refrigerant R 1234 YF
- Charging cable for household socket type E/F 16A
- Load group 1 (front axle up to 1344kg)/2 (rear axle from 1490kg)
- 2894ccm (2.9 liters) 243kW (petrol)/340kW (total) DGPA
- 6-cylinder biturbo engine, 2.9 l 243 kW
- 9.5 J x 20/11.5 J x 20 chrome-plated aluminum
- black exhaust tailpipe
- Airbag for driver and front passenger, passenger side can be deactivated
- Aluminum package in black
- Stickers/signs in German
- Aspherical exterior mirrors
- Left-hand aspherical exterior mirror
- Right-hand wing mirror, convex
- Exterior mirror housing black
- Battery charger (Version 2)
- Component set without country-specific building regulations
- Operating voltage 12 V
- Onboard literature in German
- Rear brake 18 inch
- Brake calipers painted red
- connect Package Plus 13
- Decorative parts, aluminum, black
- Theft alarm system, interior monitoring, tow-away protection
- eCall / bCall
- Parking assistance with reversing camera
- Electric rapid heater
- Vehicles with special product enhancement measures
- Front camera (Lane Keeping Assist/PDLS+)
- Pedestrian protection
- Foot lever mechanism "Standard"
- Padded dashboard
- Speed limiter
- Porsche large roof system
- HD radio reception (high definition)
- Electric tailgate with sensor-controlled opening/closing
- Sky Standard
- Rear axle gearbox base
- PHEV hybrid drive system
- Interior lighting basic + ambient
- Instrument cluster "Lowline" speedometer display in km/h
- Not a special vehicle, standard version
- Child seat anchorage for ISOFIX child seat system
- Premium rear comfort seats (40/20/40)
- Headrests with embossed coat of arms
- Fuel Market A
- Short wheelbase
- Charging socket AC type 2 mode2-3 (EU)
- Charging cable for industrial socket CEE 16 A/400 V/6 H
- Load group 1 VA/2 HA
- LED headlights plus dynamic cornering lights (PDLS+)
- Electric steering spindle lock



- heated steering wheel
- Steering column with memory
- LIGHT.AUTH.DYNAMIC.
- Left-hand drive
- Air suspension (PASM)
- Front massage seats
- Mirror Link (Apple® CarPlay)
- front center armrest
- Model designation in Platinum
- Model year 2
- Fog lights and cornering lights
- Non-smoking package
- Location Tracking System (VTS)
- Panoramic roof system
- Platinum Edition
- Porsche Platinum logo
- Premium Plus Package Platinum
- RADIO PREMIUM (MIB3)
- Colored wheel hub cover
- Legal transactions
- Tire pressure monitoring system 433MHz
- Gearshift knob in leather
- Front disc brakes with integrated brake carrier
- Key for locking system
- Rear side airbag
- PRODUCTION VEHICLE
- Speed-sensitive power steering (Servotronic)
- Automatically dimming interior safety mirror
- Side airbags in rear compartment
- Front seat ventilation/massage seats
- Seat covers in embossed partial leather for climate-controlled seats
- Heated seats front/rear
- Ski bag
- Sun visors with illuminated makeup mirrors on driver and passenger side
- Special type plate for EC
- Sport Package (2015) Hybrid
- Sports sedan
- Lane departure warning system
- Lane Change Assist (SWA)
- Start/Stop "default on" with recuperation
- Steering number model designation on side blades
- Partial leather black
- Damper
- TPM valve, silver
- Door & side panel faux leather
- Door sill trims, aluminum, black
- Door windows/side windows/rear window dark tinted (privacy glass)
- First aid kit with warning triangle
- front 275/40 ZR 20 rear 315/35 ZR 20
- Without business package

- Steering column, axially and vertically adjustable with memory
- Air outlet trim painted in Platinum (satin finish)
- Air suspension with level control and height adjustment (PASM)
- with electric steering column lock
- Center console (standard)
- 2022 model year
- Navigation device - High
- Rear fog light, right-hand traffic
- Online service, without OCU, with head unit coding, without WFS network
- PDLS+ incl. Matrix Beam
- Porsche Entry + Drive
- Porsche crest headrest
- Wheel 20" Panamera Design (9.5/11.5X20)
- Wheel hub cover, colored crest (concave)
- Wheel bolts with anti-theft device
- Region code "ECE" for radio
- Tire pressure monitoring system, frequency 433 MHz High
- Rear disc brake
- Headlight LED PDLS+
- Lettering for sales designation
- Side indicator lights
- Standard fuel initial fill
- Power liftgate closing mechanism with virtual pedal (Powerliftgate)
- Active front seat ventilation
- Part-leather seat cover
- Electrically adjustable front seats with memory
- Electric front seat adjustment, both with memory function
- Heated seats front and rear
- Soft-close doors
- Sound box without deactivation
- BOSE sound system
- Sport Chrono Package Plus
- Sport Chrono Package
- Voice control
- Lane change assistant
- Standard climate zones
- Dust and pollen filter
- Tank cap
- Cruise control
- Tire suppliers for EU countries
- Step lighting, driver's cab
- Type testing country Germany
- Door handles in car color
- Ultrasonic parking aid and reversing camera
- Vehicle class differentiation
- Traffic sign recognition
- W/O 48 V ISLAND BOARD VEH. EL. SYSTEM
- Without Connect package
- Without Generator
- Central locking Keyless entry RdW



- Without deviating seams/leather
- Without Traffic Jam Assist
- Black dials
- Door closing aid

- ZR20 tyres (275/40, 315/35)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	A short maneuvering and shunting exercise was carried out on the company premises.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Front bumper	Front bumper (Viele Oberflächenkratzer-Mehrkosten möglich) - Scratch(es) - Conditioning
2	Front axle	Axles / undercarriage (wegen der beschädigten Felgen-Mehrkosten möglich) - Specify findings - Measure
3	Front bumper	Spoiler - Scratched - Loss in value
4	Seat - rear	Ski bag - Missing - Replace
5	Wheel / tyres	Alloy rim - front left side - Scratched - Loss in value
6	Wheel / tyres	Alloy rim - rear left side - Scratched - Loss in value
7	Wheel / tyres	Alloy rim - front right side - Scratched - Loss in value
8	Wheel / tyres	Alloy rim - rear right side (+ Nabendeckel) - Scratched - Loss in value
9	Door - rear right side	Door (Rostunterwandert+ Steinschläge) - Corrosion - Repair and paint

Wear and tear

No.	Component group	Description
1	Door - rear right side	Door edge - Scratch(es) - No deduction
2	Door - front left side	Door edge - Scratch(es) - No deduction
3	Mudguard - left side	Mudguard - left side - Stone chips - No deduction
4	Door - rear left side	Door - Stone chips - No deduction
5	Bonnet	Bonnet - Stone chips - No deduction
6	Mudguard - left side	Mudguard - left side - Soiled - No deduction
7	Side panel - rear right side	Side panel - Scratch(es) - Cover / polish
8	Door - rear left side	Door - Scratch(es) - Cover / polish

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - charging cable

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Underbody, Provided by user / customer, from 16 Apr 2025	14.258,33 €



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents




Figure 18: Documents




Figure 19: Documents




Figure 20: Navigation



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Damage 1: Front bumper: Front bumper (Viele Oberflächenkratzer-Mehrkosten möglich) - Scratch(es) - Conditioning




Damage 1: Front bumper: Front bumper (Viele Oberflächenkratzer-Mehrkosten möglich) - Scratch(es) - Conditioning



Damage 1: Front bumper: Front bumper (Viele Oberflächenkratzer-Mehrkosten möglich) - Scratch(es) - Conditioning




Damage 1: Front bumper: Front bumper (Viele Oberflächenkratzer-Mehrkosten möglich) - Scratch(es) - Conditioning



Damage 1: Front bumper: Front bumper (Viele Oberflächenkratzer-Mehrkosten möglich) - Scratch(es) - Conditioning



Damage 1: Front bumper: Front bumper (Viele Oberflächenkratzer-Mehrkosten möglich) - Scratch(es) - Conditioning



Damage 3: Front bumper: Spoiler - Scratched - Loss in value



Damage 3: Front bumper: Spoiler - Scratched - Loss in value



Damage 3: Front bumper: Spoiler - Scratched - Loss in value



Damage 3: Front bumper: Spoiler - Scratched - Loss in value



Damage 3: Front bumper: Spoiler - Scratched - Loss in value



Damage 5: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 5: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 5: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 6: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 6: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



Damage 8: Wheel / tyres: Alloy rim - rear right side (+ Nabendeckel) - Scratched - Loss in value




Damage 8: Wheel / tyres: Alloy rim - rear right side (+ Nabendeckel) - Scratched - Loss in value



Damage 8: Wheel / tyres: Alloy rim - rear right side (+ Nabendeckel) - Scratched - Loss in value




Damage 9: Door - rear right side: Door (Rostunterwandert+ Steinschläge) - Corrosion - Repair and paint



Damage 9: Door - rear right side: Door (Rostunterwandert+ Steinschläge) - Corrosion - Repair and paint




Damage 9: Door - rear right side: Door (Rostunterwandert+ Steinschläge) - Corrosion - Repair and paint



Damage 9: Door - rear right side: Door (Rostunterwandert+ Steinschläge) - Corrosion - Repair and paint



Wear and tear 2: Door - front left side: Door edge - Scratch(es) - No deduction



Wear and tear 2: Door - front left side: Door edge - Scratch(es) - No deduction




Wear and tear 3: Mudguard - left side: Mudguard - left side - Stone chips - No deduction



Wear and tear 3: Mudguard - left side: Mudguard - left side - Stone chips - No deduction



Wear and tear 3: Mudguard - left side: Mudguard - left side - Stone chips
- No deduction



Wear and tear 3: Mudguard - left side: Mudguard - left side - Stone chips
- No deduction



Wear and tear 4: Door - rear left side: Door - Stone chips - No deduction



Wear and tear 4: Door - rear left side: Door - Stone chips - No deduction




Wear and tear 4: Door - rear left side: Door - Stone chips - No deduction




Wear and tear 5: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 5: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 5: Bonnet: Bonnet - Stone chips - No deduction




Wear and tear 5: Bonnet: Bonnet - Stone chips - No deduction




Wear and tear 6: Mudguard - left side: Mudguard - left side - Soiled - No deduction



Wear and tear 6: Mudguard - left side: Mudguard - left side - Soiled - No deduction




Wear and tear 7: Side panel - rear right side: Side panel - Scratch(es) - Cover / polish



Wear and tear 7: Side panel - rear right side: Side panel - Scratch(es) - Cover / polish



Wear and tear 8: Door - rear left side: Door - Scratch(es) - Cover / polish



Wear and tear 8: Door - rear left side: Door - Scratch(es) - Cover / polish



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WP0ZZZ97ZNL126611
Hersteller / Modell: PORSCHE PORSCHE Panamera 4 E-Hybrid Platinum Edition

Datum	KM-Stand	Beschreibung
17.12.2025	128.024	Luftfiltereinsatz ern; Motoröl b. Wartung; Regelwartungsdienst; Zündkerzen ern
04.06.2025	109.018	Bremsbelagfühler ern; Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben hinten; Bremsscheiben vorne; Systemtest/Eigendiagnose
26.03.2025	98.694	Getriebeöl ern/prüfen; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Wartung Sonstiges
21.02.2025	98.694	Systemtest/Eigendiagnose
06.06.2024	68.914	Bremsentest; Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Ölfilter ern; Regelwartungsdienst; Reparatur Sonstiges; Systemtest/Eigendiagnose; Wartung Sonstiges; Zündkerzen ern
20.11.2023	51.506	Bremsbelagfühler ern; Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben vorne
14.06.2023	34.657	Motoröl b. Wartung; Regelwartungsdienst