



Expertise

Protocol number: 46619019
Order No. / Reference: 26550382
Inspection date: 17 Jul 2026

Manufacturer: Mercedes-Benz

Model: Vito 116 CDI Extralang HA Aut. BASE

VIN: W1V44760513892013



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz Vito 116 CDI Extralang HA Aut. BASE	
Vehicle Identification number	W1V44760513892013
Mileage (Read)	216,098 km
First registration	15 Jul 2021
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	120 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	Stahlblau (ähnlich RAL 5011)
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Grey



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	433 Tag(e)
Last service on / at	09/2025 at 186,087 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GD332621
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / BBJ 01186		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,800 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 107T	Summer tyres on Steel rim with wheel cover	Pirelli	6mm / 6mm
2)	205/65 R16 107T	Summer tyres on Steel rim with wheel cover	Pirelli	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 107T	Winter tyres on Steel	Pirelli	6mm / 6mm
2)	205/65 R16 107T	Winter tyres on Steel	Pirelli	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/65 R16 103H	Summer tyres on Steel	Hankook	6 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- Bott expansion
- Steering wheel adjustable for tilt and height CL1

- Fleet Comfort Package Z7K
- CL 4 multifunction steering wheel

Standard equipment

- AdBlue tank (24 liters)
- Attention Assistant
- Outdoor temperature display
- third brake light
- Ceiling interior light (in driver and passenger area)
- ECO start/stop function
- Electric window regulator driver/passenger (with anti-pinch protection, quick lowering and raising)
- 9G-TRONIC PLUS automatic transmission
- Seatbelt warning device for driver and front passenger seat
- Tailgate with an opening angle of approximately 90°
- Instrument cluster with pixel matrix display (operated via the buttons on the multifunction steering wheel - round instruments for speedometer and tachometer or fuel level and coolant temperature - high-quality pixel matrix display in white and red between the large round instruments)
- Multifunction steering wheel (with trip computer)
- Upholstery: Caluma fabric, black
- Wheels: Steel rims 6.5 J x 16
- Crosswind Assist
- Front stabilizer
- Cruise control
- First aid kit
- Warning triangle
- Immobiliser

- Airbag for driver and front passenger
- Exterior mirrors, manually adjustable (2)
- Hill start assist
- Brake lights, adaptive
- Diesel particulate filter
- Electronic Stability Program (ADAPTIVE ESP) with integrated anti-lock braking system (ABS) (traction control (ASR) - electronic brake force distribution (EBD) - brake assist (BAS))
- Lockable glove box
- Interior trim of cargo area, side
- Headrests (2), front
- Paint finish: Solid color paint
- Steering wheel adjustable for tilt and height
- Mercedes-Benz emergency call system (communication module (LTE) for digital services breakdown management)
- Package: BlueEFFICIENCY (Efficiency Package)
- Tires: 205/65 R 16
- Key: 3-button remote control
- electromechanical power steering
- 12V socket
- continuous partition wall
- Lashing eyes in the cargo area
- Maintenance interval indicator >>ASSYST<
- Central locking with radio remote control

Extra equipment

- Upgrading/downgrading (upgrading to 3.05 t GVW)
- Comfort roof control unit
- Double cup holder in the center of the cockpit
- Fire extinguisher 1 kg
- Tempmatic controlled air conditioning
- Large fuel tank, approx. 70 liters
- LED light strip in the cargo area
- Center console with storage compartment
- Package: Smoker's package
- Radio/Navigation: Multimedia radio and navigation system "Audio 40" (7-inch LCD touchscreen - DAB digital radio - Apple CarPlay and Android Auto - Bluetooth 3.0 - Hands-free system - Live Traffic Information - 2-way front speakers)
- Seats: Comfort passenger seat
- Seat heating on driver's side
- Lane Keeping Assist (including instrument cluster with pixel matrix display)

- Electrically adjustable and heated exterior mirrors, left and right
- Driving light assistant (automatically switching on driving lights)
- Comfort locking system with IR remote control (comfort opening and closing)
- leather steering wheel
- Package: Driver Assistance Package (Blind Spot Assist - Lane Keeping Assist - COLLISION PREVENTION ASSIST)
- Rain sensor
- Spare wheel under the rear of the vehicle with jack
- High-resolution reversing camera with guide lines
- Weld nuts side wall for extensions
- Seat: Lumbar support driver's seat
- Seats: Comfort driver's seat
- Sun visor, driver/passenger side, illuminated mirror
- Windshield washer fluid level warning light
- Auxiliary heater, electric



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Multimedia system	Screen - Non-operational - Perform diagnosis
3	Rear bumper	Rear bumper - Scratch(es) - Loss in value
4	Front bumper	Front bumper - Scratch(es) - Loss in value
5	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
6	Tail light	Tail lamp - left side - Scratch(es) - Replace
7	Side panel - rear left side	Side panel - Scratch(es) - Smart repair
8	Rear axle	Shock absorber - right side - Leaking - Replace
9	Body	Body - Glued / labelled - De-glue / neutralise
10	Bonnet	Bonnet - dent(s) - Repair and paint
11	Sliding door, right	Sliding door - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Body	Underbody panelling - Scratch(es) - No deduction
2	Door - front right side	Door - Dent / paintcoat damage - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Unknown, Provided by user / customer, from 19 Jan 2024	304,27 €
2	Unknown, Provided by user / customer, from 5 Dec 2024	794,17 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.




Figure 30: Misc.



Damage 2: Multimedia system: Screen - Non-operational - Perform diagnosis



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Loss in value



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Loss in value



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Loss in value



Damage 4: Front bumper: Front bumper - Scratch(es) - Loss in value



Damage 4: Front bumper: Front bumper - Scratch(es) - Loss in value



Damage 5: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 5: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 6: Tail light: Tail lamp - left side - Scratch(es) - Replace



Damage 6: Tail light: Tail lamp - left side - Scratch(es) - Replace



Damage 7: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 7: Side panel - rear left side: Side panel - Scratch(es) - Smart repair




Damage 8: Rear axle: Shock absorber - right side - Leaking - Replace




Damage 9: Body: Body - Glued / labelled - De-glue / neutralise




Damage 9: Body: Body - Glued / labelled - De-glue / neutralise



Damage 10: Bonnet: Bonnet - dent(s) - Repair and paint



Damage 10: Bonnet: Bonnet - dent(s) - Repair and paint



Damage 10: Bonnet: Bonnet - dent(s) - Repair and paint



Damage 11: Sliding door, right: Sliding door - Scratch(es) - Paint



Damage 11: Sliding door, right: Sliding door - Scratch(es) - Paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1V44760513892013

Hersteller / Modell: MERCEDES-BENZ MERCEDES-BENZ Vito 116 CDI Extralang HA
Aut. BASE

Datum	KM-Stand	Beschreibung
10.04.2026	212.527	Bremsentest; Reparatur Sonstiges
23.09.2025	186.087	AU; Bremse Sonstiges; Bremsklötze vorne
22.09.2025	186.087	Regelwartungsdienst
03.12.2024	154.425	Bremsscheiben+Beläge v+h; Regelwartungsdienst
19.01.2024	114.213	Regelwartungsdienst
05.05.2023	83.330	Bremsinspektion vo + hi; Regelwartungsdienst
20.06.2022	42.729	Regelwartungsdienst