

Damage Review

Jobnr	156692
Fleet	
Lease	
Driver	Bestuurder
Location	
Date	11-03-2026
Date Hour	13:46

Make	MINI
Model	COOPER SE
Type	
Licenseplate	
Chassisnr	WMW21GC02RTA10602
Color	
First Registration	
Mileage	1017
VP/VU	VP
Fuel	ev
Fuel Level	0/8
Total Keys	1
Seats MVP	5

Check			
COC	No	Safety Kit	Yes
Registration doc	No	Triangle	Yes
Insurance doc	No	GPS	No
Manual	No	Fuel Card	No
Service book	No	Alarm	No
Fire extinguisher	No	Service Needed	No
Rear Shelf	Yes		

Remarks

2

Financial Result Damage Appraisal	
	Acceptable Total
	Not Acceptable Total
	Depreciation
	Not Acceptable Depreciated Total
	Total Damages
	Total Damages (Depreciation incl.)


Signatures

Damage advisor



Client

interior	30 Missing	TYRE KIT	NA	missing	Replace	€ 0
exterior	8 DoorFL	DOOR FL	A	scratch	SR - Touch up	€ 0

General Pictures




Damage Appraisal



interior	30 Missing	TYRE KIT	NA missing	Replace	€ 0
----------	------------	----------	------------	---------	-----

Pomp



exterior	8 DoorFL	DOOR FL	A scratch	SR - Touch up	€ 0
----------	----------	---------	-----------	---------------	-----

1a



Vehicle Condition	Interior: clean
	Exterior: dirty

Tyres			
Type	Summer	Flat/RSC	No
Spare Tyre	No	Repair Kit	Yes
Front Left			
Profile	4	Side Damage	No
Front Right			
Profile	4	Side Damage	No
Rear Left			
Profile	5	Side Damage	No
Rear Right			
Profile	5	Side Damage	No