



Expertise

Protocol number: 46505472
Order No. / Reference: 26601168
Inspection date: 14 Jul 2026

Manufacturer: Opel

Model: Combo Cargo XL 1.5 D EHZ Edition

VIN: W0VEFYHYCMJ728501



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Combo Cargo XL 1.5 D EHZ Edition	
Vehicle Identification number	W0VEFYHYCMJ728501
Mileage (Read)	47,321 km
First registration	18 Jun 2021
Number of holders	1
Next periodical technical inspection	01/2028
(Report on hand)	
Power / Engine displacement	75 kw / 1,499 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 5
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Jade Weiß
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Grey-Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	33,660 km
Last service on / at	09/2025 at 40,981 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA214940
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / AIQ 00565		
Emission standard	EURO6;WLTP;AN;PI/CI; N1 II	fine dust sticker	
Permitted total weight	2,345 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Summer tyres on Steel rim with wheel cover	Michelin	7mm / 7mm
2)	205/60 R16 96V	Summer tyres on Steel rim with wheel cover	Sonstige	8mm / 8mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Steel	Goodyear	6mm / 6mm
2)	205/60 R16 96H	Winter tyres on Steel	Fulda	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 09/2030		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Cover strip for sliding door track
- ABS including brake assist and adaptive brake light
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Exterior mirror housings in body color
- Battery discharge protection
- Floor covering: Cargo area floor, painted
- Diesel particulate filter, maintenance-free
- Three-point seat belts in all seats
- Electronic Stability Program (ESP Plus)
- Speed limiter
- Transmission: 5-speed transmission
- Heating and ventilation system with particle and odor filter, front
- Headrests (2), front, height adjustable
- Steering wheel: Comfort steering wheel (PU), flattened at the bottom
- Upholstery: Cloth
- Wheels: Steel wheels 6.5 J x 16
- Side protection strips
- Seats: Driver's seat adjustable in 6 ways: length, height and backrest angle
- Traction control with engine and brake intervention (TC Plus)
- Lashing eyes (6) in the cargo area
- Heat-insulating glazing, tinted
- Central locking: Ignition keys (2), one of which is foldable
- Storage compartments (edition)
- Driver's side airbag
- Automatic dipped headlights
- Exterior mirrors, electrically adjustable, heated and manually folding
- Hill Start Assist
- On-board computer
- Tachometer
- Third brake light
- Electric front windows
- Speed controller
- Rear wing doors, asymmetrically split, sheet metal, 180° opening angle
- Air conditioning, front, with particle and odor filter
- Paint finish: Solid color paint
- Steering column, adjustable for reach and height
- Rear parking pilot
- Wheels: Tire repair kit
- Side impact protection
- Speed-sensitive power steering
- 12-volt power outlet in the center console
- Daytime running light
- Partition wall, closed
- Doors: Sliding door, passenger side, sheet metal
- Immobiliser
- Central locking with remote control

Extra equipment

- Trailer hitch (trailer stability control (this additional ESP function dampens the vibrations of the trailer or brakes the vehicle to a safe speed as needed) - preparation for trailer hitch)
- Parking sensors, front and rear (fog lights)
- Seats: Passenger seat adjustable in 4 ways (length and backrest angle adjustable)
- Heated seats for driver and front passenger (in conjunction with double passenger seat, the middle seat is not heated)
- Electric windows, front, with one-touch function and anti-pinch protection (as well as comfort closing function via remote control of the central locking system - electrically adjustable, heated and folding exterior mirrors)
- Radio: Multimedia Navi Pro with 8" color touchscreen display and voice control for audio, telephone, and navigation (Automatic music recognition (title, album, artist, cover art) for audio devices with USB connection, Bluetooth audio streaming, hands-free calling via Bluetooth, phonebook and call list display, up to 10 mobile phones can be paired, image display via USB interface, navigation with integrated memory, 3D European road map, TMC, smartphone integration (Apple/Android), USB interface, dual tuner, graphic equalizer, 4 speakers, cruise control, steering wheel controls, DAB+, OpelConnect with telematics).



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Deformed - Loss in value
2	Boot lid / rear door	Rear door - left side - dent(s) - Smart repair
3	Door - front left side	Door edge - Scratch(es) - Smart repair
4	Door - front right side	Door edge - Scratch(es) - Smart repair
5	Boot lid / rear door	Boot lid - Glued / labelled - De-glue / neutralise
6	Front bumper	Front bumper - Broken / torn - Replace
7	Front bumper	Front bumper - Scratch(es) - Paint

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.



Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.



Damage 1: Rear bumper: Rear bumper - Deformed - Loss in value



Damage 1: Rear bumper: Rear bumper - Deformed - Loss in value



Damage 1: Rear bumper: Rear bumper - Deformed - Loss in value



Damage 1: Rear bumper: Rear bumper - Deformed - Loss in value



Damage 1: Rear bumper: Rear bumper - Deformed - Loss in value



Damage 1: Rear bumper: Rear bumper - Deformed - Loss in value



Damage 1: Rear bumper: Rear bumper - Deformed - Loss in value



Damage 1: Rear bumper: Rear bumper - Deformed - Loss in value



Damage 2: Boot lid / rear door: Rear door - left side - dent(s) - Smart repair




Damage 2: Boot lid / rear door: Rear door - left side - dent(s) - Smart repair



Damage 3: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 3: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 4: Door - front right side: Door edge - Scratch(es) - Smart repair



Damage 4: Door - front right side: Door edge - Scratch(es) - Smart repair




Damage 5: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise



Damage 6: Front bumper: Front bumper - Broken / torn - Replace



Damage 6: Front bumper: Front bumper - Broken / torn - Replace



Damage 6: Front bumper: Front bumper - Broken / torn - Replace



Damage 7: Front bumper: Front bumper - Scratch(es) - Paint



Damage 7: Front bumper: Front bumper - Scratch(es) - Paint



Damage 7: Front bumper: Front bumper - Scratch(es) - Paint



Damage 7: Front bumper: Front bumper - Scratch(es) - Paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VEFYHYCMJ728501

Hersteller / Modell: OPEL OPEL Combo Cargo XL 1.5 D EHZ Edition

Datum	KM-Stand	Beschreibung
20.01.2026	42.453	Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben vorne
19.01.2026	42.392	HU + AU
12.11.2025	41.732	Systemtest/Eigendiagnose
08.09.2025	40.981	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges