



Expertise

Protocol number: 46662077
Order No. / Reference: 26598411
Inspection date: 22 Jul 2026

Manufacturer: Citroën

Model: Berlingo 1.5 BlueHDi 100 M S&S Club

VIN: VR7EFYHYCMN507175



Vehicle details	
Manufacturer / Type / Model / Equipment	
Citroën Berlingo 1.5 BlueHDi 100 M S&S Club	
Vehicle Identification number	VR7EFYHYCMN507175
Mileage (Read)	144,514 km
First registration	9 Apr 2021
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	75 kW
Gearbox / Number of gears	Manual / 5
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Polar-Weiß
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	24,340 km
Last service on / at	05/2025 at 128,878 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FU350321
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1889 / ABB 00945		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	1,985 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/65 R15 91T	Winter tyres on Steel	Continental	4mm / 4mm
2)	195/65 R15 91T	Winter tyres on Steel	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/65 R15 91H	Summer tyres on Steel	Continental	6mm / 6mm
2)	195/65 R15 91H	Summer tyres on Steel	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	195/65 R15 91H	Summer tyres on Steel	Continental	6 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- ABS with electronic brake force distribution
- Analog instrument cluster
- Exterior mirror housing in black plastic
- Hill start assist
- On-board computer
- CITROËN Connect Box: Emergency call and assistance system
- Three-point seat belts
- Electric front windows (with one-touch operation on the driver's side)
- Speed controller and speed limiter
- Manual air conditioning
- Paint finish: Solid color paint
- Fog light
- Particulate filter: Soot particle filter for diesel engines
- Radio: Audio system RD6 (AUX input - Bluetooth - voice recognition - USB)
- Tires: 195/65 R 15
- Tire repair kit with puncture spray
- Shift point indicator
- Seat: Single passenger seat with fixed backrest (storage compartment under the seat)
- Start/Stop System
- Daytime running light
- Doors: Rear wing doors, panelled, opening 180°, 1/3 (right), 2/3 (left)
- Lashing eyes (6 pieces) in the cargo area
- Central locking
- Driver's side airbag
- Electrically adjustable and heated exterior mirrors
- "Follow me home" accompanying light function
- Floor covering: Rubber flooring in row 1
- third brake light
- Front overhead storage compartment with (lighting in the cargo area - grab handles in row 1)
- Electronic Stability Program (ESP) with Traction Control (ASR)
- High beam assist
- Transmission: 5-speed transmission
- Headrests (2), front
- Manual headlight range adjustment
- Electric parking brake
- Upholstery: Cloth
- Radio accessories: Speakers (tweeter at the rearview mirror corner (2) - speakers at the front doors (2))
- Tire pressure monitoring system
- Wheels: 15-inch steel rims with hubcaps, "Demi-Style"
- Electric power steering
- Seat: Driver's seat height-adjustable with armrest and lumbar support (manually adjustable armrest storage compartment under the driver's seat)
- Partition wall clad in sheet metal
- Doors: Sliding side door on the right
- Doors unlock automatically in case of an accident.
- Immobiliser

Extra equipment

- Airbag: 4 airbags (driver and front passenger airbags, front passenger airbag deactivatable - front side airbags)
- Seat: Single passenger seat with adjustable backrest
- Seating: Extenso cabin (double passenger bench seat with adjustable writing surface - storage compartment under the middle seat - outer passenger seat foldable - modular partition)
- Visibility Package (High Beam Assist - Fog Lights - Rain Sensor - Light Sensor - Multifunction Steering Wheel)
- Wheels: Spare wheel
- Exterior mirrors, electrically adjustable, heated and foldable
- Flooring: Rubber flooring in the cargo area
- Package: Easy Package (front and rear parking aid - reversing camera - blind spot assist)
- Radio: Citroën Connect Nav (20-cm/8" touchscreen - 3D navigation system - Integrated European map - Mirror Screen function - Digital radio reception DAB - AUX input - Bluetooth - USB)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Door - front left side	Door edge - Scratch(es) - Smart repair
2	Door - front left side	Door - Scratch(es) - Smart repair
3	Interior	Interior (Muffig) - Odour - Ozone treatment
4	Body	Body (Flugrost) - Soiled - Conditioning
5	Vehicle glazing	Windscreen - Broken / torn - Replace
6	Boot lid / rear door	Rear door - right side - Dent / paintcoat damage - Repair and paint
7	Roof	Roof (Lack löst sich ab, zusätzlich Korrosion) - Paint defect - Repair and paint

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper (unpainted) - Scratch(es) - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Body	A-pillar - left side - Stone chips - No deduction
4	Body	A-pillar - right side - Stone chips - No deduction
5	Rear bumper	Rear bumper (unpainted) - dent(s) - No deduction
6	Instrument panel	Instrument panel (Leuchte) - Differs from the original configuration - No deduction
7	Side panel - rear right side	Side panel - dent(s) - No deduction
8	Boot lid / rear door	Rear door - left side - dent(s) - No deduction
9	Wheel / tyres	Tyre - front - Worn - No deduction
10	Side panel - rear left side	Side panel (länglich, weich) - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Engine - Engine cover

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 20 May 2025	4.605,53 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 2: Door - front left side: Door - Scratch(es) - Smart repair



Damage 2: Door - front left side: Door - Scratch(es) - Smart repair



Damage 4: Body: Body (Flugrost) - Soiled - Conditioning



Damage 4: Body: Body (Flugrost) - Soiled - Conditioning



Damage 4: Body: Body (Flugrost) - Soiled - Conditioning



Damage 4: Body: Body (Flugrost) - Soiled - Conditioning



Damage 4: Body: Body (Flugrost) - Soiled - Conditioning




Damage 4: Body: Body (Flugrost) - Soiled - Conditioning




Damage 4: Body: Body (Flugrost) - Soiled - Conditioning



Damage 4: Body: Body (Flugrost) - Soiled - Conditioning



Damage 4: Body: Body (Flugrost) - Soiled - Conditioning



Damage 5: Vehicle glazing: Windscreen - Broken / torn - Replace




Damage 5: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 6: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 6: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 6: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 7: Roof: Roof (Lack löst sich ab, zusätzlich Korrosion) - Paint defect - Repair and paint



Damage 7: Roof: Roof (Lack löst sich ab, zusätzlich Korrosion) - Paint defect - Repair and paint




Damage 7: Roof: Roof (Lack löst sich ab, zusätzlich Korrosion) - Paint defect - Repair and paint



Damage 7: Roof: Roof (Lack löst sich ab, zusätzlich Korrosion) - Paint defect - Repair and paint



Wear and tear 7: Side panel - rear right side: Side panel - dent(s) - No deduction



Wear and tear 7: Side panel - rear right side: Side panel - dent(s) - No deduction




Wear and tear 7: Side panel - rear right side: Side panel - dent(s) - No deduction



Wear and tear 7: Side panel - rear right side: Side panel - dent(s) - No deduction



Wear and tear 7: Side panel - rear right side: Side panel - dent(s) - No deduction



Wear and tear 7: Side panel - rear right side: Side panel - dent(s) - No deduction



Wear and tear 8: Boot lid / rear door: Rear door - left side - dent(s) - No deduction




Wear and tear 8: Boot lid / rear door: Rear door - left side - dent(s) - No deduction



Wear and tear 8: Boot lid / rear door: Rear door - left side - dent(s) - No deduction



Wear and tear 8: Boot lid / rear door: Rear door - left side - dent(s) - No deduction



Wear and tear 9: Wheel / tyres: Tyre - front - Worn - No deduction



Wear and tear 9: Wheel / tyres: Tyre - front - Worn - No deduction



Wear and tear 9: Wheel / tyres: Tyre - front - Worn - No deduction



Wear and tear 9: Wheel / tyres: Tyre - front - Worn - No deduction




Wear and tear 10: Side panel - rear left side: Side panel (länglich, weich) - dent(s) - No deduction



Wear and tear 10: Side panel - rear left side: Side panel (länglich, weich)
- dent(s) - No deduction



Wear and tear 10: Side panel - rear left side: Side panel (länglich, weich)
- dent(s) - No deduction



Missing part 1: Engine: Engine cover - Missing - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VR7EFYHYCMN507175

Hersteller / Modell: CITROEN CITROEN Berlingo 1.5 BlueHDi 100 M S&S Club

Datum	KM-Stand	Beschreibung
21.05.2025	128.878	Bremse Sonstiges; Bremsklötze hinten; Bremsscheiben hinten; HU + AU; Keilrippenriemen; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
26.06.2024	97.895	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne
29.05.2024	92.771	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
19.12.2023	70.198	Systemtest/Eigendiagnose
31.05.2023	47.097	HU + AU
17.01.2023	43.801	Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Regelwartungsdienst