



Expertise

Protocol number: 46444043
Order No. / Reference: 26606471
Inspection date: 10 Jul 2026

Manufacturer: Skoda
VIN: TMBJC9NY2PF046094

Model: Enyaq iV 80



Vehicle details	
Manufacturer / Type / Model / Equipment	
Skoda Enyaq iV 80	
Vehicle Identification number	TMBJC9NY2PF046094
Mileage (Read)	67,176 km
First registration	25 May 2023
Number of holders	1
Power / Engine displacement	70 kw /
Fuel type / Cylinder	Electric / 0
Gearbox / Number of gears	Direct drive / 1
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Race Blau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Grey-Anthracite
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	278 Tag(e)
Last service on / at	04/2025 at 38,314		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ575354
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8004 / AWS 00124		
Emission standard	2017/1151;WLTP;reine Elektrofz	fine dust sticker	
Permitted total weight	2,657 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 101T	Summer tyres on Light alloy	Pirelli	4mm / 4mm
2)	255/50 R19 103T	Summer tyres on Light alloy	Pirelli	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 105T	Winter tyres on Light alloy	Goodyear	6mm / 6mm
2)	255/50 R19 107T	Winter tyres on Light alloy	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 02/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Storage compartments (Four roof grab handles, rear with coat hooks - Warning vest compartment in the doors - Storage compartments in the front door panels with 1.5l bottle holders - Storage compartments in the rear door panels - Umbrella compartments in the front doors - Ticket holder on the windshield - Ice scraper in the tailgate panel - Coat hooks on the B-pillars - Cup holder in the front center console - Storage compartments in the trunk)
- Evasive steering assist including turning assistant (The turning assistant monitors oncoming vehicles when you turn left (for left-hand drive vehicles). If there is an immediate danger, it brings the vehicle to a standstill and a warning signal sounds.)
- Design Selection Loft (seat covers in fabric/faux leather - decorative trim strips "brushed aluminum" - headliner in grey - front center armrest, including storage compartment - rear center armrest with cup holders and pass-through - floor mats - ambient lighting for front door panels, multicoloured - footwell lighting and illuminated door handle recesses - umbrella)
- Front radar assist with pedestrian and cyclist detection and city emergency braking function (The front radar assist is a safety system with collision warning: If confronted with an unavoidable collision, it brakes the vehicle to minimize the consequences. It also performs emergency braking if a pedestrian or cyclist attempts to cross the vehicle's path. The front radar assist recognizes from the way the driver moves the vehicle that they are attempting to avoid an obstacle and actively intervenes in the steering to steer around it.)
- Child safety locks on the rear doors
- Removable boot cover
- Front and rear headrests are height-adjustable.
- Charging cable for AC charging stations (Mode 3 charging cable, Type 2, 16A) (Fast charging connector (CCS / Combo 2))
- Steering wheel: Leather steering wheel with multifunction buttons
- Navigation system
- Front and rear parking sensors
- Radio: Infotainment system with capacitive 13" color display (2 x USB ports (Type-C) at the front - Digital radio reception DAB+ - Bluetooth hands-free phone system - Voice control - SmartLink (Apple CarPlay, Android Auto) - Wireless SmartLink)
- Rear view camera
- Rear seat backrest split 60:40, foldable
- Power steering
- Safety lights in the front side doors
- Seats: Front seats are height-adjustable, including manually adjustable lumbar support.
- Speed limiter
- Lane keeping assistant (Lane Assist)
- 12V socket - in the trunk
- Traffic sign recognition
- Immobiliser
- heat pump
- Airbag, center airbag front
- Airbag for driver and front passenger (passenger airbag can be deactivated)
- Airbag, front and rear head airbags
- Airbag, front side airbags
- acoustic windscreen
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Electrically adjustable, heated and folding exterior mirrors, including automatic dimming.
- Outdoor temperature display
- Hill start assist
- AERO anodized roof rails
- Digital instrument cluster (Virtual Cockpit)
- Third brake light
- E-Sound (external speaker for generating a driving sound)
- Electronic parking brake including auto-hold function
- Increased battery charging power max. 125 kW
- ESC Electronic Stability Control
- Electric windows front and rear (including anti-pinch protection and child safety lock)
- Cruise control
- Transmission: 1-speed (EV)
- Tinted windows
- Heated rear window
- Rear window wiper including windshield washer system
- Automatic interior mirror dimming
- Isofix anchorage on the front passenger seat
- Isofix anchorage on the outer rear seats including top tether
- Climatronic air conditioning (2-zone) (fully automatic, separately adjustable for driver and front passenger, including odor and allergen filter)
- LED headlights with daytime running lights
- LED taillights
- Steering wheel adjustable for height and reach
- Manual headlight range adjustment
- Multi-collision brake
- Package: Chrome (chrome trim strips on the outside of the side windows - AERO anodized roof rails)
- Rain sensor and driving light assistant with coming and leaving home function
- Tire mobility kit (tire repair spray incl. compressor)
- Tire pressure monitoring
- Wheels: 19" Regulus AERO alloy wheels, anthracite polished (8Jx19, tires 235/55 R19 101T front, 255/50 R19 103T rear)
- Seat belts (Height-adjustable three-point seat belts in the front - Three three-point seat belts in the rear - Seat belt reminder indicators on the front and rear seats)



- Central locking including remote control integrated into the key (EASY START (keyless start-stop system))

- Skoda Care Connect (SOS emergency call function (eCall including automatic activation in the event of an accident with airbag deployment) - Free remote vehicle access to iV-specific functions for 10 years (iV Remote Services Basic) such as starting and stopping the charging process, creating charging plans, setting the interior climate control before starting the journey, etc. - Mobility service - Information service - Free remote vehicle access for 3 years (Remote Access) - Skoda Infotainment Online)

Extra equipment

- Airbag, rear side airbags 6C4
- Anti-theft alarm system incl. safe system 7AL
- Paint finish: Metallic
- Package: Drive SPORT PLUS PFC
- Package: Driver Assistance PLUS PSB
- Package: Infotainment PLUS RAB
- Package: Light & Visibility BASIC PK8
- Package: Seating Comfort PLUS PB1
- Wheels: 19" Regulus PJB alloy wheels

- Swiveling trailer hitch (including trailer stabilization)
- 3CX luggage net partition
- Package: Convenience PLUS in conjunction with anti-theft device PDE
- Package: Family PLUS PXB
- Package: Air conditioning PLUS PWB
- Package: Parking PLUS PPC
- Package: Transport PKP
- PHC heat pump

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Side panel - rear right side	Sill - Scratch(es) - Smart repair
3	Rear bumper	Rear bumper - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Rear bumper	Spoiler - Scratch(es) - No deduction
2	Interior	Interior - Abrasion - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Front bumper	Front bumper - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer	2.580,65 €
2	Side - left, Provided by user / customer, from 25 May 2023	5.010,60 €



Accident damages

No. Accident

1 Side right

Repainting

No. Repainting

1 Mudguard - left side, Side panel - rear left side, Door - rear left side, Professionally carried out, Invoice of repair done Available

Paint coat thickness measurement

Mudguard - left side	152 µm	Side panel - rear left side	163 µm
Door - rear left side	176 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument cluster



Figure 9: Instrument panel



Figure 10: Interior 360° view



Figure 11: Cargo area




Figure 12: VIN




Figure 13: Mounted tyres



Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.




Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.



Figure 40: Misc.



Figure 41: Misc.



Figure 42: Misc.




Figure 43: Misc.




Damage 2: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 2: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 3: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 3: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 3: Rear bumper: Rear bumper - Scratched - Repair and paint




Accident 1: Side right




Accident 1: Side right




Accident 1: Side right



Accident 1: Side right



Previous damage 1: Side - left



Previous damage 1: Side - left



RECHNUNG NR. 250663

TEXT	NR.	ANZ.	EH.	E-Preis	EUR
ARBEITSAUFWENDUNGEN:					
BLINDF. A-SÄULE L. A+E					
KOTFLUEGEL V.L. HOHLR.-KONSERVIEREN	0,20	S	113,20		22,64
ABDECKUNG KOTFLUEGEL V.L. A+E	0,30	S	113,20		33,96
LÜFTUNGSGITTER KOTFLUEGEL V.L. A+E	0,20	S	113,20		22,64
SPOILER RADHAUSSCHALE V.L. A+E	0,20	S	113,20		22,64
* VERBUNDARBEIT	0,10	S	113,20		11,32
SCHENKWERFER L. ERS.	0,90	S	113,20		101,88
* VERBUNDARBEIT					
STOSSF.-ABDECKUNG V. ERS.	3,30	S	113,20		373,56
STOSSF.-ABDECKUNG V. BOHREN	0,40	S	113,20		45,28
* EINPARKHILFE					
* VERBUNDARBEIT					
STOSSF.-ABDECKUNG V. BOHREN	0,20	S	113,20		22,64
* PARKLENKASSISTENT					
* VERBUNDARBEIT					
GFS/GEFUEHRTE FUNKTION	0,30	S	113,20		33,96
FUEHRUNGSTUECK STOSSF.-ABDECKUNG V.L. A+E	0,10	S	113,20		11,32
* VERBUNDARBEIT					
SPANNUNGSFREIHEIT HOCHVOLTSYSTEM HERSTELLEN	0,50	S	113,20		56,60
* MANUELL					

more
Priesner Die Autoexperten GmbH · Kirchheimer Str. 86 · 73760 Ostfildern
Tel. 0711-578057-0 · Fax 0711-578057-88 · info@priesner-ax.de · www.priesner-autoexperten.de
Registergericht Stuttgart HRB 214023 · USt-IDNr. DE 813955598
Geschäftsführer: Jutta Pfizenmaier · Peter Priesner · Eberhard Pfizenmaier
Kreissparkasse Esslingen-Nürtingen · IBAN DE47 6115 0020 0000 909149 · BIC ESSLDE66XXX
Mittelweg 111 · 73760 Ostfildern · IBAN DE47 6115 0020 0000 909149 · BIC ESSLDE66XXX

Previous damage 2: Side - left

RECHNUNG NR. 250663 VOM 26.02.2025
FÜR ROBERT BOSCH GMBH HR SERVICE DEUTSCHLAND - GESCHÄFTSWAGEN

SEITE 5/5

ZUSAMMENFASSUNG	STD	EUR / STD	EUR
KAROSSERIE	10,20	113,20	1.154,64
MECHANIK	0,50	113,20	56,60
KALIBRIERUNG			124,52
ACHSVERMESSUNG			169,80
SUMME LOHN	10,70		758,44
LACKIERUNG	6,70	113,20	311,83
LACKMATERIAL			1.070,07
SUMME LACKIERUNG			2.414,97
ERSATZTEILE			20,00
NEBENKOSTEN			
Summe netto			5.010,60
+ MwSt 19%			952,01
SUMME EUR			5.962,61

Zahler sofort nach Rechnungserhalt ohne Abzug.

Wir bedanken uns für Ihren Auftrag und wünschen gute Fahrt.


INFORMATION ZUM VERSICHERUNGSSCHUTZ: VOLLKASKO MIT 0,00 EUR SELBSTBETEILIGUNG

GESAMTER RECHNUNGSBETRAG: 5.962,61 EUR

ÜBERNAHME DURCH DIE VERSICHERUNG: 5.962,61 EUR

VON IHNEN NOCH ZU ZAHLEN: 0,00 EUR

Previous damage 2: Side - left



Repainting 1: Mudguard - left side, Side panel - rear left side, Door - rear left side



Repainting 1: Mudguard - left side, Side panel - rear left side, Door - rear left side



Repainting 1: Mudguard - left side, Side panel - rear left side, Door - rear left side



Repainting 1: Mudguard - left side, Side panel - rear left side, Door - rear left side



Repainting 1: Mudguard - left side, Side panel - rear left side, Door - rear left side



Repainting 1: Mudguard - left side, Side panel - rear left side, Door - rear left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: TMBJC9NY2PF046094
Hersteller / Modell: SKODA SKODA Enyaq iV 80

Datum	KM-Stand	Beschreibung
22.09.2025	52.420	Reparatur Sonstiges; Systemtest/Eigendiagnose
14.04.2025	38.314	Bremsflüssigkeit; Bremsflüssigkeit ern; Regelwartungsdienst