



Expertise

Protocol number: 46505876
Order No. / Reference: 26660744
Inspection date: 14 Jul 2026

Manufacturer: Peugeot

Model: 508 SW Hybrid 225 e-EAT8 GT Pack

VIN: VR3F4DGZTMY551978



Vehicle details	
Manufacturer / Type / Model / Equipment	
Peugeot 508 SW Hybrid 225 e-EAT8 GT Pack	
Vehicle Identification number	VR3F4DGZTMY551978
Mileage (Read)	80,720 km
First registration	19 May 2022
Number of holders	1
Next periodical technical inspection	05/2027
(Report on hand)	
Power / Engine displacement	133 kw / 1,598 ccm
Fuel type / Cylinder	Hybr.B/E ext.aufll / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Perlmutter Weiß Metallic
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	Next maintenance in	0 km
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA854895
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1889 / ADY 00009		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,290 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98V	Winter tyres on Light alloy	Continental	5mm / 5mm
2)	215/55 R17 98V	Winter tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/45 R18 98Y	Summer tyres on Light alloy	Michelin	4mm / 4mm
2)	235/45 R18 98Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 07/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- ABS (Anti-lock Braking System)
- Airbag for driver and front passenger
- Airbag: Curtain airbags front and rear
- Adaptive Cruise Control (ACC) with Stop & Go function
- Electrically adjustable, heated and folding exterior mirrors
- Illuminated glove compartment
- Turn signals with lane change indicator function
- third brake light
- Roof rails in high-gloss black
- Digital instrument cluster with high-resolution 12.3" screen, adjustable and customizable
- EBV (Electronic Brakeforce Distribution)
- Front parking aid, acoustic and visual
- Chassis: Active Suspension Control (adaptive chassis control)
- electric parking brake
- Front collision warning
- front and rear floor mats
- luggage compartment roller blind
- Cup holder in the center console
- tailgate sensor-controlled
- Rear window and side windows in the second row are more heavily tinted.
- Map pockets on the front seatbacks
- Manual child lock
- Height-adjustable headrests
- Charging cable: Mode 2 charging cable (Type 2, up to 2.3 kW), 6 meters long
- Blue LED ambient lighting on the front door panels
- LED daytime running lights
- Steering wheel: Small multifunction leather steering wheel, flattened at the top and bottom.
- Rear center armrest with pass-through flap
- Multifunctional touchscreen
- Fatigue warning
- Emergency brake assist
- Package: Easy Package Plus
- Break warning
- Upholstery: Alcantara/synthetic leather
- Radio: RCC audio system
- Radio accessories: Digital radio reception DAB+
- Rain sensor
- Wheels: Anti-theft wheel bolts
- paddle shifters on the steering wheel
- Seats: Passenger seat height adjustable
- Seats: Driver's seat height adjustable
- Seats: Heated front seats (GT)
- Lane keeping assist with steering intervention
- Glazing: Laminated glass windshield, noise-reducing
- Immobiliser
- Decorative trim in high-gloss black on the side windows
- Active Safety Brake Plus
- Airbag: Side airbag
- Active Blind Spot Assist
- Automatically dimming exterior mirrors
- Exterior mirrors in Perla Nera Black
- Hill start assist
- On-board computer
- Black headliner
- Decorative inlays made of real wood "Zebrano"
- Dual exhaust with chrome-plated tailpipes
- Tachometer
- Rear parking aid, acoustic and visual
- Electronic Stability Program (ESP)
- Electric windows front and rear
- High beam assist
- Follow-me-home function (automatic)
- Full LED headlights
- Guide rails in the trunk
- Transmission: 8-speed automatic transmission EAT8
- Seat belts: 3-point safety belts in all seats
- Heated rear window
- Rear apron with diffuser look in black
- Interior mirror automatically dimming
- Keyless system
- Automatic climate control (2-zone)
- Radiator grille in checkered flag pattern in "Dark Chrome"
- LED ambient lighting in the front footwell
- Blue LED ambient lighting on the dashboard
- LED ceiling lighting at the front
- "Spereone" 18" alloy wheels, two-tone
- light sensor
- makeup mirror
- front center armrest
- Multimedia: Mirror Screen
- Navigation system: 3D navigation system NAC
- On-board charger 3.7 kW, 1-phase
- Particle filter: OPF (Otto particulate filter)
- Aluminum pedals and stainless steel door sills
- Upholstery: Decorative copper stitching on the dashboard
- Radio accessories: 2 USB ports (Type A) in row 2
- Radio accessories: FOCAL sound system
- Tire pressure monitoring system
- Wheels: Tire repair kit (compressor + tire sealant spray)
- Electric power steering
- Seats: Ergonomic comfort seats with AGR seal of approval
- Seats: Rear bench seat and backrest 40/60 split folding
- Sport mode
- Technical Plug-In Hybrid Version
- Traffic sign recognition
- Central locking can be activated from inside using a remote control.



Extra equipment

- Inductive charging station
- Panoramic tilt/slide sunroof with manual blind
- Paint finish: Special metallic paint
- Winter complete wheels aluminum

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratched - Smart repair
2	2nd wheel set	2 alloy rims (Materialabtrag 18 Zoll) - Scratched - Loss in value
3	Misc.	Inspection / maintenance - Due - Perform
4	2nd wheel set	2 alloy rims - Scratched - Loss in value
5	Door - rear left side	Door (Farbabweichung) - Unprofessionally repaired - Lacquer
6	Side panel - rear left side	Side panel (Farbabweichung) - Unprofessionally repaired - Lacquer

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - dent(s) - Smooth repair work
2	Wheel / tyres	Wheel rim - front left side - Scratched - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Side panel - rear left side, Door - rear left side

Paint coat thickness measurement

Side panel - rear left side	766 µm	Door - rear left side	202 µm
-----------------------------	--------	-----------------------	--------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.

Winterradsatz gehört nicht zur Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Documents



Figure 17: Additional tyres




Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Damage 1: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 1: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 1: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 2: 2nd wheel set: 2 alloy rims (Materialabtrag 18 Zoll) - Scratched - Loss in value



Damage 2: 2nd wheel set: 2 alloy rims (Materialabtrag 18 Zoll) - Scratched - Loss in value



Damage 2: 2nd wheel set: 2 alloy rims (Materialabtrag 18 Zoll) - Scratched - Loss in value



Damage 2: 2nd wheel set: 2 alloy rims (Materialabtrag 18 Zoll) - Scratched - Loss in value



Damage 2: 2nd wheel set: 2 alloy rims (Materialabtrag 18 Zoll) - Scratched - Loss in value



Damage 2: 2nd wheel set: 2 alloy rims (Materialabtrag 18 Zoll) - Scratched - Loss in value



Damage 2: 2nd wheel set: 2 alloy rims (Materialabtrag 18 Zoll) - Scratched - Loss in value




Damage 2: 2nd wheel set: 2 alloy rims (Materialabtrag 18 Zoll) - Scratched - Loss in value



Damage 3: Misc.: Inspection / maintenance - Due - Perform



Damage 4: 2nd wheel set: 2 alloy rims - Scratched - Loss in value



Damage 4: 2nd wheel set: 2 alloy rims - Scratched - Loss in value



Damage 4: 2nd wheel set: 2 alloy rims - Scratched - Loss in value




Damage 4: 2nd wheel set: 2 alloy rims - Scratched - Loss in value



Damage 4: 2nd wheel set: 2 alloy rims - Scratched - Loss in value



Damage 5: Door - rear left side: Door (Farbabweichung) - Unprofessionally repaired - Lacquer



Damage 5: Door - rear left side: Door (Farbabweichung) - Unprofessionally repaired - Lacquer



Damage 6: Side panel - rear left side: Side panel (Farbabweichung) - Unprofessionally repaired - Lacquer



Damage 6: Side panel - rear left side: Side panel (Farbabweichung) - Unprofessionally repaired - Lacquer



Wear and tear 1: Bonnet: Bonnet - dent(s) - Smooth repair work



Wear and tear 1: Bonnet: Bonnet - dent(s) - Smooth repair work




Wear and tear 2: Wheel / tyres: Wheel rim - front left side - Scratched - No deduction



Wear and tear 2: Wheel / tyres: Wheel rim - front left side - Scratched - No deduction



Wear and tear 2: Wheel / tyres: Wheel rim - front left side - Scratched - No deduction



Repainting 1: Side panel - rear left side, Door - rear left side



Repainting 1: Side panel - rear left side, Door - rear left side



Repainting 1: Side panel - rear left side, Door - rear left side



Repainting 1: Side panel - rear left side, Door - rear left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VR3F4DGZTMY551978

Hersteller / Modell: PEUGEOT PEUGEOT 508 SW Hybrid e-EAT8 GT Pack

Datum	KM-Stand	Beschreibung
28.05.2025	63.482	AU; Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne
04.12.2024	51.573	Batterie ern; Reparatur Sonstiges; Systemtest/Eigendiagnose