



Expertise

Protocol number: 46609702
Order No. / Reference: 26768057
Inspection date: 21 Jul 2026

Manufacturer: Ford

Model: Transit Connect 220 L2 Trend

VIN: WF0SXXWPGSME31682



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Transit Connect 220 L2 Trend	
Vehicle Identification number	WF0SXXWPGSME31682
Mileage (Read)	41,426 km
First registration	7 Feb 2022
Number of holders	1
Next periodical technical inspection	07/2028
(Report on hand)	
Fuel type	Petrol
Engine displacement / Cylinder	999 ccm / 3
Power	74 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frost-Weiß
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	98 %
Last service on / at	07/2026 at 41,280 km		
Key is / should be	1 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GH400447
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BHA 00534		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,175 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96V	Summer tyres on Steel rim with wheel cover	Continental	7mm / 7mm
2)	205/60 R16 96V	Summer tyres on Steel rim with wheel cover	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/60 R16 96V C	Summer tyres on Steel	Continental	7 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment with 12-volt connection
- Driver's side airbag
- Exterior mirrors, narrow mirror format
- Battery, reinforced
- Rubberized flooring, front
- Double-leaf rear doors without windows
- Third brake light
- Front electric windows
- FordPass Connect
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Front interior lighting with delay function
- Paint finish: Solid
- Cargo area floor protection plastic, molded
- Steering column, adjustable in height and reach
- Center console, front
- Emergency brake light
- Radio: Ford Audio System 2
- Wheels: Steel wheels 6.5 J x 16 with 205/60 R 16 tires and wheel trims
- Electro-mechanical power steering
- Front seat belts are height-adjustable
- Seats: Seat package 4
- Dust and pollen filter
- Front bumper and rear bumper end caps painted in body color
- Child safety lock on sliding doors
- Lashing eyes
- Electronic immobilizer (EPATS)
- Central locking with remote control
- ABS with EBD
- Exterior mirrors, electrically adjustable and heated
- Exterior mirror housing black
- Hill start assist
- On-board computer including outside temperature display
- Tachometer
- Electronic Safety and Stability Program (ESP)
- Ford Easy Fuel
- Heated windshield
- Transmission: 6-speed transmission
- Glove compartment with lid
- Front air conditioning including semi-electronic recirculation system
- Cargo area lining, side, half-height
- Alternator/Generator
- Fog light
- Gasoline particulate filter (GPF)
- Wheels: Tire repair kit
- Sliding door at rear, right
- Side protection strips, plastic
- Safety brake assist
- Automatic door locking mechanism (45 sec.)
- Start-stop system
- Power outlet: 12-volt connection on the front center console
- Daytime running light
- Partition wall to the cargo area without window
- Door handles, black
- Warning system for unfastened seat belts
- Heat-insulating glazing, lightly tinted



Extra equipment

- Airbag: Front airbag for passenger (front airbag for passenger including deactivation function and glove compartment with lid)
- Remote control: 2nd remote control key for central locking (instead of conventional key)
- Cruise control system (with adjustable speed limiter including multifunction leather steering wheel with 4 spokes in aluminium decor)
- Inductive charging station for mobile devices (according to Qi standard, compatibility depends on the device)
- Radio: Ford Audio System 154 (4.2" monochrome display (10.7 cm screen diagonal) - DAB/DAB+ radio, 1 USB port - 4 front speakers - Bluetooth hands-free system and audio streaming - Emergency call assistant - Phase diversity antenna - Audio remote control on the steering wheel)
- Power outlet: 12-volt connection in the charging/luggage compartment
- Partition wall to the cargo area with pass-through opening and window
- Auxiliary electric heater (PTC), front
- Towing device, preparation (preparation set for retrofittable towing device incl. ESP trailer stabilization (includes trailer module and connection preparation for 13-pin socket))
- High beam assist (including windscreen wipers with rain sensor and automatically dimming interior mirror)
- Heated rear windows
- Rear window wiper/washer system
- Cargo area lighting, LED
- Package: Smoker (cigarette lighter and ashtray)
- Front and rear parking pilot system
- Spare wheel: Steel wheel
- Mud flaps front and rear
- Crosswind Assist and Roll Stability Control (RSC)
- Seats: Seat package 30 (fabric "Capitol/City" in Ebony (black) - double passenger seat, variably foldable and collapsible (with storage compartment under smaller seat section) - driver's seat, 3-way manually adjustable (forward/backward, height, backrest) - headrests, height-adjustable - seat heating for driver's seat - lumbar support, manual (driver's seat))

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Wheel cover - front right side - Scratched - Replace
2	Wheel / tyres	Wheel cover - front left side - Scratched - Replace
3	Interior	Interior (Lautes Piepen) - Noise - Diagnosed and repair if necessary
4	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
5	Body	Body - Glued / labelled - De-glue / neutralise
6	Rear bumper	Rear bumper - Scratch(es) - Replace
7	Boot lid / rear door	Rear door - left side - Dent / paintcoat damage - Repair and paint
8	Boot lid / rear door	Rear door - right side - Dent / paintcoat damage - Repair and paint



Wear and tear

No.	Component group	Description
1	Wheel / tyres	Wheel cover - rear right side - Scratched - No deduction
2	Sliding door, right	Sliding door - dent(s) - No deduction
3	Roof	Roof - dent(s) - No deduction
4	Door - front left side	Door - Scratch(es) - No deduction
5	Trim / covers	Boot sill cover - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - Vehicle key

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 9 Feb 2026	3.799,78 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.



Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents

Hauptuntersuchung nach § 29 StVZO
Prüfbescheinigung nach Richtlinie 2014/45/EU - Roadworthiness certificate according to 2014/45/EU

(1) Fz.-Ident.Nr. WF0SXXWPGSME31682 (2) Laufzeit abgelaufen: 41271 km ZGM: 2200 Bericht-Nr. X185732091
(3) Anst. Kennz. 1 (6) Fz.-Art. N18B - Fz.z. Gü.bef. b. 3.5.1 Expresscode: YRUJkpD+
(4) Produkt: 07.01.2020 - 1.0.41 Aufbauart: Van Kennnummer: I1151001
83059 Kolbermoor Hersteller: 8586 - FORD (D) J-Stelle: 6329AI
Rosenheimer Straße 59 Fz.-Typ: BHA00534 - PU2 Auftrag: 6329
Erstellt: 02/2022 letzte HU: 02/2024 474239

Sehr geehrte Kunden, sehr geehrter Kunde,
bei der Untersuchung Ihres Fahrzeuges wurden keine Mängel festgestellt.
Die nächste HU ist fällig im Juli 2028.
Die Bremsenprüfung erfolgte unter Berücksichtigung vorliegender Bezugsbremskräfte.

Betriebsbremsanlage:	Ref.Wert	Links	Rechts	Funktionsw.	Ist	Min	Ergebnis
1. Achse	537	302	304	81.9	64.2	56	LO
2. Achse	230	243	242	80.9	35.8	15	LO

Feststellbremsanlage:
Abbremsung 20 % 2. Achse Blockiert 233 204

(7) Ergebnis
ohne festgestellte Mängel (OM)

HU-Plakette
angebracht
(8) nächste HU:
Juli 2028

(9) Ihr Prüfingenieur
B. Eng. Tobias Treinkler

I1151001

Das Abgasverhalten wurde am 07.07.2026 durch die Werkstatt mit der Nr. BY-4-04-0744-63 überprüft.

Dabei das Fahrzeug nach DIN EN ISO 15707:2012, angewandte Prüfverfahren:
Die Abgasleistung ist für das Fahrzeug bei 1200/1300 U/min (15 min) aufgeführt. Abgasleistung:
Die Abgasleistung ist für das Fahrzeug bei 1200/1300 U/min (15 min) aufgeführt. Abgasleistung:
Die Abgasleistung ist für das Fahrzeug bei 1200/1300 U/min (15 min) aufgeführt. Abgasleistung:

Die Untersuchung wurde im Rahmen und für Rechnung des KUS e.V. durchgeführt.
KUS e.V. - Kfz-Untersuchungsstelle - Wolnzach

Figure 15: Documents



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Damage 1: Wheel / tyres: Wheel cover - front right side - Scratched - Replace



Damage 1: Wheel / tyres: Wheel cover - front right side - Scratched - Replace



Damage 2: Wheel / tyres: Wheel cover - front left side - Scratched - Replace



Damage 2: Wheel / tyres: Wheel cover - front left side - Scratched - Replace



Damage 4: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 4: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 6: Rear bumper: Rear bumper - Scratch(es) - Replace



Damage 6: Rear bumper: Rear bumper - Scratch(es) - Replace



Damage 6: Rear bumper: Rear bumper - Scratch(es) - Replace



Damage 6: Rear bumper: Rear bumper - Scratch(es) - Replace



Damage 7: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Repair and paint



Damage 7: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Repair and paint



Damage 7: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Repair and paint




Damage 8: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 8: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint




Damage 8: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 8: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Wear and tear 1: Wheel / tyres: Wheel cover - rear right side - Scratched - No deduction



Wear and tear 1: Wheel / tyres: Wheel cover - rear right side - Scratched - No deduction



Wear and tear 5: Trim / covers: Boot sill cover - Scratch(es) - No deduction



Wear and tear 5: Trim / covers: Boot sill cover - Scratch(es) - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0SXXWPGSME31682
Hersteller / Modell: FORD FORD Transit Connect 220 L2 Trend

Datum	KM-Stand	Beschreibung
07.07.2026	41.280	AU; Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben hinten; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern
19.12.2025	37.748	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
06.02.2024	18.089	AU; Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges