



Expertise

Protocol number: 46432527
Order No. / Reference: 26546800
Inspection date: 10 Jun 2026

Manufacturer: MAN
VIN: WMA03VUY6P9012523

Model: TGE 3.140 4X2F SB



Vehicle details	
Manufacturer / Type / Model / Equipment	
MAN TGE 3.140 4X2F SB	
Vehicle Identification number	WMA03VUY6P9012523
Mileage (Read)	123,917 km
First registration	14 Dec 2022
Number of holders	1
Next periodical technical inspection	12/2026
(Report on hand)	
Power / Engine displacement	103 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Candy Weiß
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	14,700 km
Last service on / at	07/2025 at 115,369 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS155453
Previous damage / Accident	None detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	1516 / AYN 58721		
Emission standard	EURO6;WLTP;AR;PI/CI;N1 III, N2	fine dust sticker	
Permitted total weight	3,500 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/75 R16 113R	All-season tyres on Steel rim with wheel cover	Falken	5mm / 5mm
2)	205/75 R16 113R	All-season tyres on Steel rim with wheel cover	Falken	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/75 R16 113R C	All-season tyres on Steel	Bridgestone	8 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Retrofitted equipment

- Storage package 2
- Battery with increased capacity
- Fitting point
- Wooden floor in the cargo area with wheel arch cladding
- National registration documents Germany
- Smoker's version
- Rear View reversing camera
- Comfort seat, left
- Lashing rails in the cargo area
- Driver and passenger airbags
- Cab doors, additionally with reinforced door seals
- All-season tyres
- MAN Media Van package with 4 speakers
- Center wheel cover with chrome emblem
- Steel spare wheel with road tires
- Side interior paneling in the cargo area made of plywood
- Rear step, across the entire width



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	A test drive was performed with the described vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Sill - right side	Sill - dent(s) - Smooth repair work
2	Door - front left side	Door (Innen) - dent(s) - Smooth repair work
3	Door - front left side	Door - dent(s) - Smooth repair work
4	Door - front right side	Door (Innen) - dent(s) - Smooth repair work

Missing parts

Description

Equipment - Vehicle tool kit (inkl. Wagenheber)

Repainting

No. Repainting

- 1 Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent
- 2 Door - rear right side, Professionally carried out, Invoice of repair done Non-existent
- 3 Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear right side	180 µm	Door - rear right side	164 µm
Door - front right side	223 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view




Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.




Damage 1: Sill - right side: Sill - dent(s) - Smooth repair work



Damage 1: Sill - right side: Sill - dent(s) - Smooth repair work



Damage 2: Door - front left side: Door (Innen) - dent(s) - Smooth repair work




Damage 2: Door - front left side: Door (Innen) - dent(s) - Smooth repair work



Damage 3: Door - front left side: Door - dent(s) - Smooth repair work



Damage 3: Door - front left side: Door - dent(s) - Smooth repair work



Damage 4: Door - front right side: Door (Innen) - dent(s) - Smooth repair work



Damage 4: Door - front right side: Door (Innen) - dent(s) - Smooth repair work



Repainting 1: Side panel - rear right side



Repainting 1: Side panel - rear right side



Repainting 1: Side panel - rear right side



Repainting 2: Door - rear right side



Repainting 2: Door - rear right side



Repainting 2: Door - rear right side



Repainting 3: Door - front right side



Repainting 3: Door - front right side



Repainting 3: Door - front right side



Side panel - rear right side: 180 µm



Door - rear right side: 164 µm



Door - front right side: 223 µm



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WMA03VUY6P9012523

Hersteller / Modell: MAN MAN TGE 3.140 4X2F SB

Datum	KM-Stand	Beschreibung
01.10.2025	122.977	Systemtest/Eigendiagnose
04.07.2025	115.369	Bremsflüssigkeit; Bremsflüssigkeit ern; Keilriemen ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Regelwartungsdienst; Reparatur Sonstiges; Wartung Sonstiges
17.04.2025	110.126	Systemtest/Eigendiagnose
12.03.2025	104.300	Bremsbelagfühler ern; Bremsklötze vorne; Bremsscheiben vorne; Reparatur Sonstiges; Systemtest/Eigendiagnose
29.01.2025	97.984	Motoröl b. Wartung; Regelwartungsdienst
06.01.2025	99.912	Reparatur Sonstiges
17.12.2024	94.238	Bremsentest; HU + AU; Systemtest/Eigendiagnose
17.09.2024	81.489	Motoröl b. Wartung; Ölwechsel; Systemtest/Eigendiagnose; Systemtest/Eigendiagnose
03.01.2024	45.719	Motoröl b. Wartung; Regelwartungsdienst
28.11.2023	41.477	Regelwartungsdienst
16.10.2023	35.001	Motoröl b. Wartung; Ölfilter ern; Ölwechsel