



Expertise

Protocol number: 45947893
Order No. / Reference: 26466913
Inspection date: 15 Jun 2026

Manufacturer: Mercedes-Benz
VIN: W1K5M1CBXPN353331

Model: CLA 200 d Shooting Brake 8G-DCT



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz CLA 200 d Shooting Brake 8G-DCT	
Vehicle Identification number	W1K5M1CBXPN353331
Mileage (Read)	152,412 km
First registration	2 May 2023
Number of holders	1
Power / Engine displacement	110 kw / 1,950 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	NACHTSCHWARZ UNILACK
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	185 Tag(e)
Last service on / at	12/2025 at 132,213 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GM970677
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / AGV 00076		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,120 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 95Y	Summer tyres on Light alloy	Sonstige	4mm / 4mm
2)	245/45 R18 95Y	Summer tyres on Light alloy	Sonstige	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91H	Winter tyres on Light alloy	Hankook	5mm / 5mm
2)	205/55 R17 91H	Winter tyres on Light alloy	Hankook	5mm / 2mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ADAPTIVE BRAKE with HOLD function, hill start assist, pre-filling and drying brakes in wet conditions
- Airbag: Kneebag for driver
- Airbag: Windowbag for driver and front passenger
- Traction control (ASR)
- ATTENTION ASSIST
- Basic services
- Brake assist, active
- Double cup holder at the front
- Third brake light in LED technology
- ECO start/stop function
- Chassis: Comfort chassis
- electric parking brake
- Speed Limit Assistant
- Halogen headlights with integrated LED daytime running lights
- KEYLESS-GO start function
- Rear headrests (3)
- Paint finish: Solid
- Steering wheel: Multifunction sports steering wheel
- Light and rain sensor
- Package: Light and Visibility Package
- Upholstery: ARTICO leatherette/Bertrix fabric
- Radio: MBUX multimedia system
- Radio accessories: Communication module (LTE) for using Mercedes me connect services
- Tire pressure monitoring system (TPMS)
- Windscreen wipers with rain sensor
- Seat belts CLA-Class
- Seats: iSize child seat anchorages with top tether on the outer seats
- 12V power outlet
- Cruise control
- High-visibility vest for drivers
- Central locking
- Airbag for driver and front passenger
- Airbag: Automatic passenger airbag deactivation
- Airbag: Side airbag for driver and front passenger
- Anti-lock braking system (ABS)
- Foldable armrest for driver and front passenger
- Left and right exterior mirrors, heated and electrically adjustable, painted in body color
- Diesel particulate filter
- Tachometer
- DYNAMIC SELECT
- Electronic Stability Program (ESP)
- Electric windows (4-way)
- Velour floor mats in black
- Transmission: 8G-DCT automatic
- Lockable glove compartment
- Interior headliner fabric crystal grey
- THERMATIC automatic climate control
- Front headrests are height-adjustable
- Steering wheel shift paddles
- Steering: Direct steering
- Mercedes-Benz emergency call system
- Package: Seating comfort
- Radio: Extended MBUX functions
- Radio accessories: Digital radio (DAB)
- Radio accessories: USB interface in the storage compartment & 2 USB interfaces in the rear center console
- Wheels: 43.2 cm (17") alloy wheels, 4-spoke design, 5-twin-spoke design
- Seats: Rear seat backrests foldable
- Seats: Comfort seats
- Lane Keeping Assist, active
- Bumpers in body color
- Touchpad
- Electronic immobilizer



Extra equipment

- Adaptive Highbeam Assist (automatic switching of the high beams on and off - camera on the inside of the windshield - detects oncoming and preceding illuminated vehicles - activated by pressing the steering wheel control lever to the high beam position)
- Navigation accessories: Pre-installation for Live Traffic Information
- Package: Business (Hard drive navigation - Smartphone integration - Traffic sign assistant - Preparation for digital key handover - Connectivity package navigation - Seat heating for driver and front passenger - Active parking assistant with PARKTRONIC)
- Seats: 4-way lumbar support for driver and front passenger
- Active Parking Assist with PARKTRONIC
- Ambient lighting with 64 different colors
- Black fabric headliner
- LED High Performance headlights (The LED High Performance headlights offer greater safety at night and a distinctive, striking look. Thanks to LED technology, they illuminate the road better than conventional headlights – with lower energy consumption.)
- Wheels: 45.7 cm (18") alloy wheels, 4-spoke design (high-gloss black paint and diamond-turned finish with 225/45 R 18 tires on 7.5 J x 18 ET 49 rims)
- Sunroof: Electric panoramic sunroof
- Partition net for luggage compartment separation and occupant protection

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Door - front right side	Door - dent(s) - Smooth repair work
3	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
4	Door - front right side	Window guide (3 dellen) - dent(s) - Replace
5	Side panel - rear right side	Sill (Und kratzer) - dent(s) - Smart repair
6	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
7	Bonnet	Bonnet (Und verätzung [Harz]) - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Body	Body - Scratch(es) - No deduction
2	2nd wheel set	1 alloy rim - Scratched - No deduction
3	2nd wheel set	1 tyre - Broken / torn - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Documents - Log book



Previous damages

No.	Previous damage	Extent of damage (Net)
1	Roof, Provided by user / customer, from 14 May 2025	606,66 €
2	Side right, Provided by user / customer, from 8 May 2025	878,82 €
3	Side right, Provided by user / customer, from 4 Mar 2024	921,62 €
4	Side right, Provided by user / customer, from 27 Feb 2025	1.648,46 €
5	Side - left, Provided by user / customer, from 11 Sept 2025	2.137,44 €

Repainting

No.	Repainting
1	Side panel - rear right side, Professionally carried out

Paint coat thickness measurement

Side panel - rear right side	258 µm
------------------------------	--------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Comments

Parksensoren akustisch



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.



Damage 2: Door - front right side: Door - dent(s) - Smooth repair work



Damage 2: Door - front right side: Door - dent(s) - Smooth repair work



Damage 2: Door - front right side: Door - dent(s) - Smooth repair work



Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value




Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value




Damage 4: Door - front right side: Window guide (3 dellen) - dent(s) - Replace




Damage 4: Door - front right side: Window guide (3 dellen) - dent(s) - Replace



Damage 4: Door - front right side: Window guide (3 dellen) - dent(s) - Replace




Damage 5: Side panel - rear right side: Sill (Und kratzer) - dent(s) - Smart repair



Damage 5: Side panel - rear right side: Sill (Und kratzer) - dent(s) - Smart repair




Damage 5: Side panel - rear right side: Sill (Und kratzer) - dent(s) - Smart repair



Damage 5: Side panel - rear right side: Sill (Und kratzer) - dent(s) - Smart repair



Damage 5: Side panel - rear right side: Sill (Und kratzer) - dent(s) - Smart repair



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value




Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 7: Bonnet: Bonnet (Und verätzung [Harz]) - Scratch(es) - Paint




Damage 7: Bonnet: Bonnet (Und verätzung [Harz]) - Scratch(es) - Paint



Damage 7: Bonnet: Bonnet (Und verätzung [Harz]) - Scratch(es) - Paint



Damage 7: Bonnet: Bonnet (Und verätzung [Harz]) - Scratch(es) - Paint



Damage 7: Bonnet: Bonnet (Und verätzung [Harz]) - Scratch(es) - Paint



Wear and tear 2: 2nd wheel set: 1 alloy rim - Scratched - No deduction



Wear and tear 2: 2nd wheel set: 1 alloy rim - Scratched - No deduction



Wear and tear 2: 2nd wheel set: 1 alloy rim - Scratched - No deduction



Wear and tear 3: 2nd wheel set: 1 tyre - Broken / torn - No deduction



Wear and tear 3: 2nd wheel set: 1 tyre - Broken / torn - No deduction




Wear and tear 3: 2nd wheel set: 1 tyre - Broken / torn - No deduction



Previous damage 1: Roof



Previous damage 1: Roof



Previous damage 4: Side right




Previous damage 4: Side right



Previous damage 4: Side right




Previous damage 4: Side right



Previous damage 4: Side right




Previous damage 4: Side right



Previous damage 4: Side right



Previous damage 4: Side right



Previous damage 4: Side right



Previous damage 4: Side right



Previous damage 5: Side - left




Previous damage 5: Side - left



Previous damage 5: Side - left



Previous damage 5: Side - left



Previous damage 5: Side - left




Previous damage 5: Side - left



Previous damage 5: Side - left



Previous damage 5: Side - left



Repainting 1: Side panel - rear right side



Repainting 1: Side panel - rear right side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1K5M1CBXPN353331

Hersteller / Modell: MERCEDES-BENZ MB CLA 200 d Shooting Brake 8G-DCT

Datum	KM-Stand	Beschreibung
12.12.2025	132.213	Bremsscheiben hinten; Regelwartungsdienst
08.07.2025	103.014	Regelwartungsdienst
27.02.2025	77.552	Bremsscheiben vorne; Regelwartungsdienst
08.10.2024	52.038	Bremsklötze hinten; Regelwartungsdienst
20.02.2024	24.899	Regelwartungsdienst