



Expertise

Protocol number: 46516074
Order No. / Reference: 26430524
Inspection date: 7 Jul 2026

Manufacturer: Peugeot

Model: 508 SW BlueHDi 130 EAT8 Allure Pack

VIN: VR3FCYHZTNY573744



Vehicle details

Manufacturer / Type / Model / Equipment

Peugeot 508 SW BlueHDi 130 EAT8 Allure Pack

Vehicle Identification number	VR3FCYHZTNY573744
Mileage (Read)	76,485 km
First registration	23 Aug 2022
Number of holders	1
Next periodical technical inspection	09/2027
(Report on hand)	

Power / Engine displacement	96 kw / 1,499 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Perlmutter Weiß Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	Available / complete	Next maintenance in	2,800 km
Last service on / at	09/2025 at 60,359 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GC903062
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1889 / AEA 00030		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,043 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98V	Winter tyres on Light alloy	Goodyear	6mm / 6mm
2)	215/55 R17 98V	Winter tyres on Light alloy	Goodyear	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98W	Summer tyres on Light alloy	Michelin	5mm / 5mm
2)	215/55 R17 98W	Summer tyres on Light alloy	Michelin	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS (Anti-lock Braking System)
- Airbag for driver and front passenger
- Airbag: Curtain airbags front and rear
- Adaptive Cruise Control (ACC) with Stop & Go function
- Exterior mirrors in Perla Nera Black
- Hill start assist
- On-board computer
- Roof rails in high-gloss black
- Digital instrument cluster with high-resolution 12.3" screen, adjustable and customizable
- Rear parking aid, acoustic and visual
- Electronic Stability Program (ESP)
- Misfueling protection
- High beam assist
- Follow-me-home function (automatic)
- Full LED headlights with headlight range control
- luggage compartment roller blind
- Cup holder in the center console
- Heated rear window
- Rear apron with diffuser look in black
- Interior mirror automatically dimming
- Keyless system
- Automatic climate control (2-zone)
- Radiator grille with chrome facets and black surround
- Blue LED ambient lighting on the front door panels
- LED daytime running lights
- Steering wheel: Small multifunction leather steering wheel, flattened at the top and bottom.
- Rear center armrest with pass-through flap
- Multifunctional touchscreen
- Multimedia: Mirror Screen
- Navigation system: 3D navigation system NAC
- Particulate filter: FAP diesel particulate filter
- Upholstery: Fabric/faux leather
- Radio accessories: 2 USB ports (Type A) in row 2
- Rain sensor
- Wheels: Tire repair kit (compressor + tire sealant spray)
- paddle shifters on the steering wheel
- Seats: Passenger seat height adjustable
- Seats: Electric lumbar support
- Lane keeping assist with steering intervention
- Chrome-plated decorative exhaust tailpipes
- Traffic sign recognition
- Central locking can be activated from inside using a remote control.
- Active Safety Brake Plus
- Airbag: Side airbag
- Active Blind Spot Assist
- Electrically adjustable, heated and folding exterior mirrors
- Illuminated glove compartment
- Turn signals with lane change indicator function
- third brake light
- Decorative inlays in carbon look
- Tachometer
- EBV (Electronic Brakeforce Distribution)
- Front parking aid, acoustic and visual
- Driving mode selector (Sport - Normal - Eco)
- Electric windows front and rear
- electric parking brake
- Front collision warning
- front and rear floor mats
- Transmission: 8-speed automatic transmission EAT8
- Seat belts: 3-point safety belts in all seats
- Rear window and side windows in the second row are more heavily tinted.
- Map pockets on the front seatbacks
- Manual child lock
- Height-adjustable headrests
- LED ambient lighting in the front footwell
- LED ceiling lighting at the front
- "Merion" 17" alloy wheels, two-tone
- light sensor
- makeup mirror
- Front center armrests with illuminated storage compartment
- Fatigue warning
- Emergency brake assist
- Break warning
- Radio: Audio
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring system
- Reversing camera with 180° surround view
- Electric power steering
- Seats: Driver's seat height adjustable
- Seats: Rear bench seat and backrest 40/60 split folding
- Stop&Start system
- Glazing: Laminated glass windshield, noise-reducing
- Immobiliser
- Decorative trim in high-gloss black on the side windows



Extra equipment

- tailgate sensor-controlled
- Package: Comfort (Ergonomic comfort seats with AGR seal of approval - Extendable thigh support - Electric seat tilt adjustment - Seat heating)
- Paint finish: Special paint finish "Pearl White" or "Elixir Red"
- Wheels: Spare wheel well (Allure Pack)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front left side	Door edge (Perlmutterlack erhöhter Aufwand) - Scratch(es) - Smart repair
2	Rear bumper	Reflector - right side (& Nebelschlussleuchte) - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 26 Jul 2025	2.972,74 €

Repainting

No.	Repainting
1	Mudguard - left side

Paint coat thickness measurement

Mudguard - left side	212 µm
----------------------	--------



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Der angegebene Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Damage 1: Door - front left side: Door edge (Perlmutterlack erhöhter Aufwand) - Scratch(es) - Smart repair



Damage 1: Door - front left side: Door edge (Perlmutterlack erhöhter Aufwand) - Scratch(es) - Smart repair




Damage 2: Rear bumper: Reflector - right side (& Nebelschlussleuchte) - Broken / torn - Replace



Damage 2: Rear bumper: Reflector - right side (& Nebelschlussleuchte) - Broken / torn - Replace



Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction




Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 2: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 2: Vehicle glazing: Windscreen - Stone chips - No deduction



Repainting 1: Mudguard - left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VR3FCYHZTNY573744

Hersteller / Modell: PEUGEOT PEUGEOT 508 SW BlueHDi 130 EAT8 Allure Pack

Datum	KM-Stand	Beschreibung
18.09.2025	60.359	AU; Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben hinten; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
31.07.2024	41.110	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
21.06.2023	23.117	Motoröl b. Wartung; Regelwartungsdienst