



Expertise

Protocol number: 46578865
Order No. / Reference: 26587777
Inspection date: 17 Jul 2026

Manufacturer: Volkswagen

Model: ID.4 Performance Upgrade Pro Tech

VIN: WVGZZZE2ZNP022628



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen ID.4 Performance Upgrade Pro Tech	
Vehicle Identification number	WVGZZZE2ZNP022628
Mileage (Read)	120,644 km
First registration	21 Apr 2022
Number of holders	2
Power / Engine displacement	70 kw / 0 ccm
Fuel type / Cylinder	Electric / 0
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Station wagon
Colour / colour code	Gletscherweiß Metallic / Dach Schwarz
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black
Re-import	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	Next maintenance in	621 Tag(e)
Last service on / at	03/2026 at 117,372 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ120573
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	0603 / CLQ 00046		
Emission standard	2017/1151;WLTP;reine Elektrofz	fine dust sticker	
Permitted total weight	2,540 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 101T	Summer tires (with run-flat tires) on Light alloy	Hankook	6mm / 6mm
2)	255/50 R19 103T	Summer tires (with run-flat tires) on Light alloy	Hankook	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 101T	Winter tires (with run-flat tires) on Light alloy	Pirelli	6mm / 6mm
2)	255/50 R19 103T	Winter tires (with run-flat tires) on Light alloy	Pirelli	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 USB-C ports on the front
- Airbag for driver and front passenger, with front passenger airbag deactivation
- Ambient lighting, 10 colors
- Electrically adjustable, folding and heated exterior mirrors
- Car2X
- e-Sound
- ESP Electronic Stability Program
- Speed limiter
- Back window, heater
- Interior mirror automatically dimming
- "Climatronic" air conditioning system
- Mode 3 Type 2 charging cable, 16 A
- Charging: 125 kW DC charging power (direct current)
- Steering wheel: Multifunction steering wheel with touch controls
- Navigation system "Discover Pro"
- Emergency call service
- Package: Infotainment Package
- Radio accessories: 6 + 1 speakers
- Tire pressure monitoring system
- Keyless Start system
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner
- Seats: Rear bench seat undivided, backrest asymmetrically split and foldable
- Telephone interface
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Central locking including remote control
- Turning brake function and evasive steering support
- Airbags: Front and rear head airbags, front side airbags, center airbag
- App-Connect Wireless for Apple CarPlay and Android Auto
- third brake light
- black roof rails
- Parking assistance
- Driving profile selection
- Transmission: 1-speed automatic
- rear window wiper
- ISOFIX mounting points for child car seats
- Front and rear headrests (5)
- Charging: 11 kW AC charging power (alternating current)
- LED headlights with automatic headlight control
- Makeup mirrors in the sun visors
- Fatigue detection
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Upholstery: Seat center panels of the front seats and the outer rear seats in "Matrix" fabric
- LED taillights
- electromechanical power steering
- Seats: Armrest for front seats
- Seats: Driver's seat height adjustable
- Voice control
- Lane keeping assistant "Lane Assist"
- Ambient lighting with logo projection
- Traffic sign recognition
- Green thermal insulation glazing, sides and rear

Extra equipment

- Exterior Style "Silver" (rear roof trim and roof pillars in silver - silver anodized roof rails)
- Charging cable: Mains charging cable for household socket
- Wheels: Winter wheels (4) "Hamar" 8 J x 19 (total) in Dark Graphite/ gloss-turned (winter tires 235/55 R 19 T / 255/50 R 19 T)
- Textile floor mats front and rear
- Reversible luggage compartment mat
- Paint finish: Metallic, different roof color
- Retrofitting a trailer hitch
- Wheels: Alloy wheels (4) "Hamar" 8 J x 19 in Dark Graphite, polished finish (Airstop all-season tires 235/55 R 19 front, Airstop all-season tires 255/50 R 19 rear - wheel locks with enhanced theft protection)
- Heat pump for range optimization



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Boot lid - Glued / labelled - De-glue / neutralise
2	Side panel - rear left side	Sill - Scratched - Smart repair
3	2nd wheel set	1 alloy rim (Materialveränderung an Glanzgedrehter Stelle) - Corrosion - Loss in value
4	2nd wheel set	1 alloy rim (Materialveränderung an Glanzgedrehter Stelle) - Corrosion - Loss in value
5	2nd wheel set	1 alloy rim - Scratch(es) - Loss in value
6	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
7	Rear bumper	Bumper - rear right side - Scratched - Repair and paint
8	Boot lid / rear door	Boot lid (Unterhalb) - Scratched - Paint
9	Front bumper	Front bumper - Scratched - Repair and paint
10	Vehicle glazing	Windscreen (Größere Abplatzer im Fahrersichtfeld) - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Misc.	Main inspection - No evidence - No deduction
3	Misc.	Inspection / maintenance (Nur letzte Wartung nachgewiesen) - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN




Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents

Einzelnachweis	
Fahrzeugdaten	
Fahrgestellnummer	WVGZZZE2ZNP022628
Typbezeichnung	ID.4 Pro Perla 150/77 E1H
Datum der Auslieferung	2022-04-27
Inspektion	
Datum	2026-03-30
Laufleistung	117372 km
Auftragsnummer	2026004708
Durchgeführte Zusatzarbeiten	✓ Kältemittel ✓ Bremsflüssigkeits Service ✓ Staub- u. Pollenfilter
Durchgeführt von	Hordenberg Murgstraße 9-13 76646 Bruchsal Deutschland
Autorisierter Volkswagen Service Partner	Ja
Mobilitätsgarantie	Bis Anzeige Service, bei allen Fahrzeugen mit individuellen Konditionen bis Laufzeitende

Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.




Figure 40: Misc.



Damage 1: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise




Damage 2: Side panel - rear left side: Sill - Scratched - Smart repair



Damage 2: Side panel - rear left side: Sill - Scratched - Smart repair




Damage 3: 2nd wheel set: 1 alloy rim (Materialveränderung an Glanzgedrehter Stelle) - Corrosion - Loss in value



Damage 3: 2nd wheel set: 1 alloy rim (Materialveränderung an Glanzgedrehter Stelle) - Corrosion - Loss in value



Damage 4: 2nd wheel set: 1 alloy rim (Materialveränderung an Glanzgedrehter Stelle) - Corrosion - Loss in value



Damage 4: 2nd wheel set: 1 alloy rim (Materialveränderung an Glanzgedrehter Stelle) - Corrosion - Loss in value



Damage 5: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value




Damage 5: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Damage 6: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 6: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 7: Rear bumper: Bumper - rear right side - Scratched - Repair and paint



Damage 7: Rear bumper: Bumper - rear right side - Scratched - Repair and paint



Damage 7: Rear bumper: Bumper - rear right side - Scratched - Repair and paint



Damage 7: Rear bumper: Bumper - rear right side - Scratched - Repair and paint



Damage 8: Boot lid / rear door: Boot lid (Unterhalb) - Scratched - Paint



Damage 8: Boot lid / rear door: Boot lid (Unterhalb) - Scratched - Paint



Damage 9: Front bumper: Front bumper - Scratched - Repair and paint



Damage 9: Front bumper: Front bumper - Scratched - Repair and paint



Damage 10: Vehicle glazing: Windscreen (Größere Abplatzer im Fahrersichtfeld) - Stone chips - Replace



Damage 10: Vehicle glazing: Windscreen (Größere Abplatzer im Fahrersichtfeld) - Stone chips - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WVGZZZE2ZNP022628

Hersteller / Modell: VOLKSWAGEN VOLKSWAGEN ID.4 Performance Upgrade Pro
Tech

Datum	KM-Stand	Beschreibung
30.03.2026	117.372	Bremsflüssigkeit; Bremsflüssigkeit ern; Regelwartungsdienst
16.04.2024	71.801	Bremsflüssigkeit; Bremsflüssigkeit ern; Regelwartungsdienst
17.10.2023	63.464	Bremsbelagfühler ern; Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben vorne