



Expertise

Protocol number: 46838950
Order No. / Reference: 26601067
Inspection date: 28 Jul 2026

Manufacturer: Mercedes-Benz

Model: GLC 300 e 4Matic 9G-TRONIC Avantgarde Advanced

VIN: W1NKM5GB7PF059094



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz GLC 300 e 4Matic 9G-TRONIC Avantgarde Advanced	
Vehicle Identification number	W1NKM5GB7PF059094
Mileage (Read)	154,554 km
First registration	5 Sept 2023
Number of holders	1
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,999 ccm / 4
Power	150 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Schwarz uni
Doors / Seats	5 / 5
Upholstery type	Artificial leather
Colour of upholstery	Black
readiness to drive	Not roadworthy / not moveable



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	243 Tag(e)
Last service on / at	02/2026 at 140,230 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV715898
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Not roadworthy / not moveable		
Manufacturer key number/ type code number	2222 / BLC 00001		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,840 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/60 R18 103W	Summer tyres on Light alloy	Goodyear	4mm / 4mm
2)	235/60 R18 103W	Summer tyres on Light alloy	Goodyear	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/60 R18 103H	Winter tyres on Light alloy	Continental	4mm / 4mm
2)	255/55 R18 109H	Winter tyres on Light alloy	Continental	3mm / 3mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- Klimaautomatik

Standard equipment

- Adaptive Highbeam Assist
- Airbag: Kneebag for driver
- Airbag: Windowbag
- Active Lane Keeping Assist
- Ambient lighting
- Traction control (ASR)
- Automatic passenger airbag deactivation
- AVANTGARDE Interior
- Brake system with larger brake discs on the front axle
- Double cup holder
- Tachometer
- EASY-PACK tailgate
- Electronic Stability Program (ESP)
- Chassis: Comfort chassis
- Velour floor mats
- Rear window heated
- Interior headliner fabric crystal grey
- Climate: THERMATIC automatic climate control
- Communication module (LTE) for the use of Mercedes me connect services
- Charging cable for household socket, 5m, smooth
- Charging system: Alternating current charging system (AC charging) up to 11 kW (3-phase)
- Steering wheel: Multifunction sports steering wheel in leather
- Navigation accessories: Pre-installation for Live Traffic Information
- Navigation accessories: Pre-installation for remote and navigation services
- Otto particulate filter
- Package: Avantgarde Advanced (for hybrid models)
- Package: Interior light
- Package: Parking package with reversing camera
- Package: Mirror Package
- Radio accessories: Digital radio (DAB)
- Tire pressure loss warning
- Wheels: 45.7 cm (18") alloy wheels in a 5-spoke design
- Wheel accessories: TIREFIT with tire inflator compressor
- Power steering
- Heated seats for driver and front passenger
- Phone accessories: Smartphone integration
- Cruise control
- High-visibility vest for drivers
- Heat-insulating dark tinted glass
- Central locking with remote control
- Airbag for driver and front passenger
- Airbag: Side airbag for driver and front passenger
- Active Brake Assist
- 4MATIC all-wheel drive
- Anti-lock braking system (ABS)
- ATTENTION ASSIST
- AVANTGARDE Exterior
- Basic services
- Roof rails made of glossy anodized aluminum
- Downhill Speed Regulation (DSR)
- Dynamic front bumper with visual underguard
- EASY-Pack: Cargo area cover
- Driver display
- Fingerprint scanner
- Transmission: 9G-TRONIC
- Rear window wiper/washer system
- Instrument panel in black with contrasting decorative stitching
- Radiator grille with integrated Mercedes star
- Paint finish: Solid
- Charging cable for wallbox and public charging station, 5m, smooth
- LED High Performance Headlights
- Mercedes-Benz emergency call system
- Navigation accessories: Extended MBUX functions
- Navigation accessories: Pre-installation for navigation services
- Navigation: Hard disk navigation
- Navigation: MBUX Navigation Premium
- Package: Storage
- Package: Chrome Interior Package
- Package: Boot Comfort Package
- Package: Seating comfort
- Package: USB package
- Radio accessories: MBUX multimedia system
- Remote and Charging Services Plus
- Wheels: Summer tires
- Windscreen wipers with rain sensor
- Seats: 4-way lumbar support for driver and front passenger
- Phone accessories: Wireless charging system for mobile devices
- Pre-installation for digital key handover
- Immobiliser
- Central display
- Decorative elements in diamond pattern, silver-grey



Extra equipment

- Airbag: Side airbags in the rear
- Charging cable for household socket, 8m, smooth (This charging cable, also called Mode 2 cable, allows you to charge the vehicle battery at the household socket with up to 1.8 kW (230 V, 1-phase, 8A) and fits sockets of type E/F CEE 7/7.)
- Charging system: DC on-board charger (60 kW) (For your optimal charging speed with up to 60 kW)
- Package: ENERGIZING Package Plus (Exclusive comfort programs - warmth - joy - coziness - freshness - vitality - PowerNap - Training: video instructions - Tips: 3-minute audio information for the sustainable promotion of health and well-being in everyday life - ENERGIZING COACH - Multi-contour seats for driver and front passenger - Seat climate control for driver and front passenger - AIR-BALANCE Package)
- Seats: Heated rear seats
- Towbar with ESP trailer stabilization
- Upholstery: ARTICO man-made leather
- Wheels: Complete summer wheel sets fitted at the factory
- Center console diamond pattern silver grey
- Charging cable for wallbox and public charging stations, 8m, smooth (This charging cable, also called Mode 3 cable, allows you to charge the vehicle battery at the wallbox or at public charging stations with up to 11 kW (Type 2, 3-phase, 16 A).)
- Package: Avantgarde Advanced Plus (electrically adjustable driver's seat with memory function - Blind Spot Assist - Illuminated door sills with "Mercedes-Benz" lettering - Traffic Sign Assist - Advanced Plus Package)
- Package: Off-road Engineering Package (comfort suspension with 20 mm higher ground clearance - metal underbody protection at the front - Gemtex durable plastic underbody protection on the sides)
- Package: Winter Package (heated steering wheel - heated windshield washer system)
- Wheels: Winter complete wheels M+S 4-way 45.7 cm (18") light alloy wheels in 5-spoke design (aerodynamically optimized, black painted and gloss-turned with front axle 235/60 R18 on 8.0 J x 18 ET 32.5 and rear axle 255/55 R18 on 9.0 J x 18 ET 30)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not roadworthy at the time of inspection, but only capable of being towed.



Value reducing factors

No.	Component group	Description
1	Equipment	Vehicle key - Empty - Perform
2	Door - rear right side	Door - Scratch(es) - Smart repair
3	Bonnet	Bonnet - dent(s) - Smooth repair work
4	Trim / covers	Roof lining - Soiled - Clean
5	Sill - right side	Sill - Dent / paintcoat damage - Smart repair
6	Side panel - rear right side	Sill - Scratch(es) - Smart repair
7	Door - rear left side	Door (4x) - dent(s) - Smooth repair work
8	Wheel / tyres	Tyre - rear right side (nicht fahrbereit) - Damaged - Replace
9	Wheel / tyres	Tyre - front right side (nicht fahrbereit) - Damaged - Replace
10	Sill - left side	Sill (+ Aufkleber) - Dent / paintcoat damage - Smart repair
11	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - Loss in value
12	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
13	2nd wheel set	2 tyres (3mm) - Does not meet the leasing specifications - Replace
14	Front bumper	Cover bumper - front - Damaged - Replace
15	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Repair and paint
16	Rear bumper	Rear bumper - Scratch(es) - Paint
17	Door - front left side	Door (4x) - Dent / paintcoat damage - Repair and paint
18	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
19	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Door - front left side	Door - Scratch(es) - No deduction
2	Door - rear left side	Door - Abrasion - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 3 Nov 2024	2.099,68 €
2	Front, Side - left, Provided by user / customer, from 26 Jan 2026	2.499,70 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Additional tyres



Figure 18: Additional tyres



Figure 19: Navigation




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.






Figure 36: Misc.



Damage 1: Equipment: Vehicle key - Empty - Perform




Damage 2: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 2: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 3: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 3: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 4: Trim / covers: Roof lining - Soiled - Clean



Damage 4: Trim / covers: Roof lining - Soiled - Clean



Damage 5: Sill - right side: Sill - Dent / paintcoat damage - Smart repair




Damage 5: Sill - right side: Sill - Dent / paintcoat damage - Smart repair



Damage 5: Sill - right side: Sill - Dent / paintcoat damage - Smart repair



Damage 6: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 6: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 7: Door - rear left side: Door (4x) - dent(s) - Smooth repair work



Damage 7: Door - rear left side: Door (4x) - dent(s) - Smooth repair work



Damage 8: Wheel / tyres: Tyre - rear right side (nicht fahrbereit) - Damaged - Replace



Damage 8: Wheel / tyres: Tyre - rear right side (nicht fahrbereit) - Damaged - Replace



Damage 9: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Damaged - Replace



Damage 9: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Damaged - Replace



Damage 9: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Damaged - Replace



Damage 10: Sill - left side: Sill (+ Aufkleber) - Dent / paintcoat damage - Smart repair



Damage 10: Sill - left side: Sill (+ Aufkleber) - Dent / paintcoat damage - Smart repair



Damage 10: Sill - left side: Sill (+ Aufkleber) - Dent / paintcoat damage - Smart repair



Damage 11: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 11: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 12: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 12: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 13: 2nd wheel set: 2 tyres (3mm) - Does not meet the leasing specifications - Replace




Damage 13: 2nd wheel set: 2 tyres (3mm) - Does not meet the leasing specifications - Replace



Damage 13: 2nd wheel set: 2 tyres (3mm) - Does not meet the leasing specifications - Replace



Damage 13: 2nd wheel set: 2 tyres (3mm) - Does not meet the leasing specifications - Replace




Damage 13: 2nd wheel set: 2 tyres (3mm) - Does not meet the leasing specifications - Replace



Damage 13: 2nd wheel set: 2 tyres (3mm) - Does not meet the leasing specifications - Replace




Damage 14: Front bumper: Cover bumper - front - Damaged - Replace



Damage 14: Front bumper: Cover bumper - front - Damaged - Replace



Damage 15: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 15: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 15: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 15: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 15: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 15: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 16: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 16: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 16: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 16: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 16: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 17: Door - front left side: Door (4x) - Dent / paintcoat damage - Repair and paint



Damage 17: Door - front left side: Door (4x) - Dent / paintcoat damage - Repair and paint




Damage 17: Door - front left side: Door (4x) - Dent / paintcoat damage - Repair and paint



Damage 17: Door - front left side: Door (4x) - Dent / paintcoat damage - Repair and paint




Damage 17: Door - front left side: Door (4x) - Dent / paintcoat damage - Repair and paint



Damage 17: Door - front left side: Door (4x) - Dent / paintcoat damage - Repair and paint



Damage 18: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 18: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 18: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 19: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 19: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1NKM5GB7PF059094

Hersteller / Modell: MERCEDES-BENZ MERCEDES-BENZ GLC 300 e 4Matic 9G-TRONIC Avantgarde Advanced

Datum	KM-Stand	Beschreibung
10.02.2026	140.230	Regelwartungsdienst
13.08.2025	109.954	Regelwartungsdienst
26.02.2025	81.910	Regelwartungsdienst
30.10.2024	55.878	Regelwartungsdienst
04.03.2024	29.659	Regelwartungsdienst