

























Vehicle details

VIN	WVGZZZE2Z NP023070	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate		Model	ID.4 77kWh 150kW Pro Auto	Maintenance mileage	-
Registration date	30/12/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	214 271 km	Engine size	-	Interior Color	Grey
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	30/06/2026	Inspection loc.			
					
					
					
					

Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
LED lighting	✓

Removable element


Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✗

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 235/50/20 Summer 4.0 mm



Continental 235/50/20 Summer 3.5 mm



Continental 235/50/20 Summer 6.0 mm



Continental 235/50/20 Summer 6.0 mm

Exterior

4



Part	Wing
Position	Back right
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

5



Part	Wing
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

6



Part	Bonnet
Position	Front
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

7



Part	Roof
Position	-
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

8



Part	Step plate
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

Interior damage

2




Part	Interior tailgate lining
Position	Back
Damages	Misaligned
Severity	-
Repair mode	Adjust

3



Part	Boot carpet
Position	Back
Damages	Scratched
Severity	-
Repair mode	For info

Others

1		Part	Wireless charger
		Position	-
		Damages	Missing
		Severity	-
		Repair mode	For info