



Expertise

Protocol number: 46434067
Order No. / Reference: 26709914
Inspection date: 8 Jul 2026

Manufacturer: Hyundai

Model: TUCSON 1.6 T-GDi Plug-in-Hybrid 4WD

VIN: TMAJE8123SJ384085



Vehicle details	
Manufacturer / Type / Model / Equipment	
Hyundai TUCSON 1.6 T-GDi Plug-in-Hybrid 4WD	
Vehicle Identification number	TMAJE8123SJ384085
Mileage (Read)	12,768 km
First registration	16 Jul 2025
Number of holders	1
Next periodical technical inspection	07/2028
(Report not on hand)	
Power / Engine displacement	118 kw / 1,598 ccm
Fuel type / Cylinder	Hybr.B/E ext.auf / 4
Gearbox / Number of gears	Automatic / 6
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	ATLAS WHITE
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	7,232 km
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HM311368
Previous damage / Accident	None detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	1349 / AGQ 00003		
Emission standard	EURO6;WLTP;EA;PI/CI;M, N1, N2	fine dust sticker	
Permitted total weight	2,415 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R19 103V	Summer tyres on Light alloy	Michelin	5mm / 5mm
2)	235/50 R19 103V	Summer tyres on Light alloy	Michelin	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2030		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- LED daytime running lights
- Steering wheel adjustable for height and reach
- multifunction steering wheel
- light sensor
- Front center armrest with storage compartment
- Emergency call system (eCall)
- Particle filter
- Radio: Audio system (6 speakers including 2 tweeters in the front - RDS radio - USB port - Bluetooth hands-free system)
- Tire pressure monitoring system (TPMS)
- Wheels: Tire repair kit
- Tinted windows all around
- Shift-by-Wire
- Seats: Passenger seat height adjustable
- Seats: Driver's seat height adjustable
- Seats: Driver's seat with adjustable lumbar support
- Seats: Rear seat backrest split 40:20:40, foldable
- 12-volt power outlet, front and in the luggage compartment
- USB charging port, front
- USB charging ports (2), rear
- Glazing: Windscreen with acoustic film
- Electronic immobilizer
- Central locking with remote control
- ABS with EBV
- Adaptive Emergency Stop Signal (ESS)
- Airbag: Center airbag between driver and passenger
- Airbag: Front airbags for driver and front passenger (passenger airbag can be deactivated)
- Active Lane Keeping Assist (LKA)
- Lead Vehicle Approach Warning (LVDA)
- Attention Assistant (DAW)
- Electrically folding exterior mirrors
- Electrically adjustable and heated exterior mirrors (from inside)
- Hill Descent Control (DBC)
- On-board computer (digital cockpit with 10.25-inch color display)
- Tachometer
- Rear parking sensors
- Vehicle Stability Management (VSM)
- High Beam Assist (HBA)
- luggage compartment cover
- Transmission: 6-speed automatic
- Heated rear window (with automatic shut-off)
- Interior mirror manually dimmable
- Child safety locks on the rear doors
- Automatic climate control (dual zones - automatic interior fog control - multi-air mode)
- Leather steering wheel and gearshift lever (contains high-quality synthetic leather)
- Steering wheel: Paddle shifters
- Armrest - centre, rear
- Multi-collision brake (MCB)
- Electronic parking brake (EPB) with Auto Hold
- Upholstery: Cloth
- Radio: Digital radio reception (DAB+)
- Radio accessories: Apple CarPlay, Android Auto
- Rain sensor
- Wheels: Alloy wheels 7.5 J x 19 with tires 235/50 R 19
- Rear view camera
- Power steering
- Seat belts (three-point belt system on all seats - belt tensioners and belt force limiters front and rear (outer seats) - belt warning for all seats - height-adjustable seat belts in front)
- Lane Following Assist (LFA) (The Lane Following Assist keeps the vehicle in the middle of the lane and, in addition to the lane markings, also uses the vehicle in front as a guide)
- Traffic sign recognition (Intelligent traffic sign recognition with speed assist (ISLA))
- Storage options (storage pockets on the back of the front seats - compartment in the center console of the dashboard - compartments under the luggage compartment floor - cup holders in the front and rear)
- Airbag: Front side airbags
- Airbag: Curtain airbags extending to the rear seats
- Alarm system
- Trailer Stability Assist (TSA)
- Autonomous emergency braking assistant including front collision warning (with pedestrian/cyclist detection (FCA-Ped./FCA-Cyc.))
- Exterior mirrors with integrated turn signals
- Hill Start Assist (HAC)
- Roof rails
- Roof spoiler with 3rd brake light
- Drive Modes (including Terrain Selector)
- Electronic Stability Control (ESC)
- Electric front windows (with automatic up/down function and anti-pinch protection, front)
- Cruise control with limiter
- Halogen projection headlights
- Rear window wiper concealed under roof spoiler
- ISOFIX child seat attachment at the rear (on the outer seats including top tether anchor points)
- Headrests (5) front and rear height adjustable
- Paint finish: Solid



Extra equipment

- Paint finish: Solid special color

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction
2	Bonnet	Bonnet - dent(s) - Smooth repair work
3	Rear bumper	Spoiler - Scratch(es) - Replace
4	Rear bumper	Protection strip - centre - Scratched - Replace

Repainting

No. Repainting

- | | |
|---|---|
| 1 | Bonnet, Professionally carried out, Invoice of repair done Non-existent |
|---|---|

Paint coat thickness measurement

Bonnet	237 µm
--------	--------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Navigation



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Damage 2: Bonnet: Bonnet - dent(s) - Smooth repair work




Damage 2: Bonnet: Bonnet - dent(s) - Smooth repair work




Damage 3: Rear bumper: Spoiler - Scratch(es) - Replace




Damage 3: Rear bumper: Spoiler - Scratch(es) - Replace



Damage 4: Rear bumper: Protection strip - centre - Scratched - Replace



Damage 4: Rear bumper: Protection strip - centre - Scratched - Replace



Repainting 1: Bonnet



Repainting 1: Bonnet