



Expertise

Protocol number: 46654839
Order No. / Reference: 26660791
Inspection date: 22 Jul 2026

Manufacturer: Opel

Model: Vivaro 1.5 D Cargo M Edition

VIN: VXEVBYHVMN7022790



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Vivaro 1.5 D Cargo M Edition	
Vehicle Identification number	VXEVBYHVMN7022790
Mileage (Read)	104,847 km
First registration	29 Jun 2022
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	88 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Jade Weiß
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Grey-Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	33,520 km
Last service on / at	03/2026 at 99,043 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ671971
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	3003 / BAL 00380		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,695 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R17 104H	All-season tyres on Steel rim with wheel cover	Continental	6mm / 6mm
2)	215/60 R17 104H	All-season tyres on Steel rim with wheel cover	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	215/70 R17 104H C	Winter tyres on Steel	Michelin	7 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Driver and passenger side airbags
- Exterior mirrors, electrically adjustable, heated and manually folding
- Hill Start Assist
- Floor covering: Cargo area floor, painted
- third brake light
- Tachometer
- Electronic Stability Program (ESP Plus)
- Front and rear aprons in black
- Transmission: 6-speed transmission
- Grab handle in the first row of seats, passenger side
- Paint finish: Solid color paint
- Steering column, adjustable for reach and height
- Fatigue detection level 1 coffee break
- Upholstery: Fabric / faux leather with grey dashboard underside
- Visibility equipment
- Sun visors, driver and passenger
- 12-volt power outlet in the center console
- Traction control with engine and brake intervention (TC Plus)
- Doors: Rear wing doors, sheet metal with a 180° opening angle
- Electronic immobilizer
- Central locking with remote control
- ABS including brake assist and adaptive brake light
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Exterior mirror housings in black
- Sheet metal insert, driver's side in the 2nd row of seats
- On-board computer
- Diesel particulate filter, maintenance-free
- Three-point seat belts in all seats
- Electric front windows
- Speed controller and limiter
- Halogen headlights with daytime running lights
- Glove compartment closed at the top
- Steering wheel: Comfort steering wheel (PU), flattened at the bottom
- Rear fog lights with integrated reversing lights
- Side impact protection
- Speed-sensitive power steering
- Seats: Comfort driver and comfort passenger seats
- Start/Stop System
- 12V power outlet in the cargo area and in the lower glove compartment
- Partition wall: closed, without windows
- Doors: Sliding door, passenger side
- Lashing eyes (6) in the cargo area
- Heat-insulating glazing, tinted
- Ignition keys (2), both foldable

Extra equipment

- GPS
- Park pilot, front and rear parking aid (with acoustic warning signal when parking forwards and backwards - blind spot warning - electrically folding exterior mirrors - fog lights)
- Price protection minimum amount
- Tires: Winter tires, usable all year round (tire size 215/60 R 17 C 104 H 3PMSF)
- Wheels: Spare wheel, steel
- Wheels: Steel wheels 7 J x 17 with wheel cover, full surface (tires 215/60 R 17 C 104H)
- 180° panoramic reversing camera (displays the area behind the vehicle up to 180 degrees, including steering guidelines, when reverse gear is engaged, in the color display of the infotainment system.)
- Safety package including whisk
- Seats: Comfort driver's seat and double passenger seat (comfort driver's seat adjustable in 6 ways, with armrest and lumbar support - double passenger seat with storage under the seat - height-adjustable headrests, front)
- Automatic climate control: Dual-zone automatic climate control, front (with particle and odor filter - recirculation mode, manual - automatic air distribution - sun position sensor - activated carbon filter)
- Radio: Multimedia radio with 7" color touchscreen display (Automatic music recognition for audio devices with USB connection, Bluetooth audio streaming, Digital radio reception DAB+, Hands-free system via Bluetooth interface, Display of phonebook and call lists, Up to 10 mobile phones can be paired, Display of pictures/films/videos via USB interface, Smartphone integration, Voice control, 1 USB interface, Dual tuner, Graphic equalizer, 4 speakers (8 in double cab Edition or Elegance))
- Keyless locking and starting system "Keyless Open & Start"
- Würth: Sanitary ware
- Würth: Voltage converters



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Wheel cover - front right side - Scratched - Replace
2	Wheel / tyres	Wheel cover - front left side - Scratched - Replace
3	Wing mirror - right side	Cap - Scratch(es) - Loss in value
4	Door - front right side	Door edge - Scratch(es) - Smart repair
5	Door - front left side	Door edge - Scratch(es) - Smart repair
6	Body	Body - Glued / labelled - De-glue / neutralise

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 1 Dec 2022	1.877,78 €
2	Side right, Provided by user / customer, from 13 Dec 2024	3.687,55 €
3	Side right, Provided by user / customer, from 13 Nov 2025	7.555,74 €

Repainting

No.	Repainting
1	Mudguard - left side, Professionally carried out, Invoice of repair done Non-existent
2	Mudguard - right side, Professionally carried out, Invoice of repair done Non-existent
3	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent
4	Door - front left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Mudguard - left side	190 µm	Mudguard - right side	246 µm
Side panel - rear right side	379 µm	Door - front left side	228 µm



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Damage 1: Wheel / tyres: Wheel cover - front right side - Scratched - Replace



Damage 1: Wheel / tyres: Wheel cover - front right side - Scratched - Replace



Damage 1: Wheel / tyres: Wheel cover - front right side - Scratched - Replace



Damage 2: Wheel / tyres: Wheel cover - front left side - Scratched - Replace



Damage 2: Wheel / tyres: Wheel cover - front left side - Scratched - Replace



Damage 2: Wheel / tyres: Wheel cover - front left side - Scratched - Replace



Damage 3: Wing mirror - right side: Cap - Scratch(es) - Loss in value



Damage 3: Wing mirror - right side: Cap - Scratch(es) - Loss in value



Damage 4: Door - front right side: Door edge - Scratch(es) - Smart repair



Damage 4: Door - front right side: Door edge - Scratch(es) - Smart repair



Damage 5: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 5: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 6: Body: Body - Glued / labelled - De-glue / neutralise



Damage 6: Body: Body - Glued / labelled - De-glue / neutralise



Repainting 1: Mudguard - left side



Repainting 1: Mudguard - left side



Repainting 2: Mudguard - right side



Repainting 2: Mudguard - right side



Repainting 3: Side panel - rear right side



Repainting 3: Side panel - rear right side



Repainting 4: Door - front left side



Repainting 4: Door - front left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VXEVBHVMN7022790
Hersteller / Modell: OPEL OPEL Vivaro 1.5 D Cargo M Edition

Datum	KM-Stand	Beschreibung
26.03.2026	99.043	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
16.02.2026	95.460	Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne
08.10.2025	86.891	Kraftstofffilter ern; Luftfiltereinsatz ern; Regelwartungsdienst
13.03.2025	68.737	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
03.02.2025	64.493	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne
22.07.2024	50.548	AU; Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
01.08.2023	29.128	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges