



Expertise

Protocol number: 46641427
Order No. / Reference: 26716594
Inspection date: 21 Jul 2026

Manufacturer: Mercedes-Benz

Model: E 220 d T 9G-TRONIC

VIN: W1K2132041B005862



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz E 220 d T 9G-TRONIC	
Vehicle Identification number	W1K2132041B005862
Mileage (Read)	157,573 km
First registration	28 Oct 2021
Number of holders	1
Next periodical technical inspection (Report on hand)	12/2026
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	143 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Hightechsilber Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	273 Tag(e)
Last service on / at	04/2026 at 154,658 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GF717265
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / AEA 00217		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,525 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 97Y	Summer tyres on Light alloy	Goodyear	5mm / 5mm
2)	225/55 R17 97Y	Summer tyres on Light alloy	Goodyear	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 97H	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	225/55 R17 97H	Winter tyres on Light alloy	Goodyear	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ADAPTIVE BRAKE with hill start assist, pre-filling and drying braking in wet conditions
- Airbag: Automatic passenger airbag deactivation
- Airbag: Side airbag for driver and front passenger
- Anti-lock braking system (ABS)
- Foldable armrest for driver and front passenger
- Left and right exterior mirrors, heated and electrically adjustable, painted in body color
- Brake assist, active
- Tachometer
- DYNAMIC SELECT
- EASY-PACK tailgate
- Electronic Stability Program (ESP)
- Chassis: Air suspension on the rear axle with level control
- Vehicle Setup
- Electric window regulator with comfort operation and anti-pinch protection, 4-way
- Heated rear window with timer
- KEYLESS START
- Communication module (LTE) for the use of Mercedes me connect services
- LED High Performance Headlights
- Steering wheel: Multifunction sports steering wheel in Nappa leather
- Mercedes-Benz emergency call system
- Package: Interior lighting package
- Upholstery: Marseille fabric, black
- Radio: Audio 20
- Trip computer and on-board computer
- Service interval indicator ASSYST
- Seats: i-Size child seat attachment
- Seats: Front seats electrically adjustable
- Cruise control
- Electronic immobilizer
- Central locking
- AdBlue container with a volume of 25 liters
- Airbag for driver and front passenger
- Airbag: Kneebag for driver
- Airbag: Windowbags left/right
- Traction control (ASR)
- ATTENTION ASSIST
- Exterior mirror housings with integrated ambient lighting
- Basic services
- Diesel particulate filter
- Third brake light
- EASY-PACK cargo cover including EASY-PACK safety net
- ECO start/stop function
- Chassis: AGILITY CONTROL chassis with selective damping system and lowered suspension
- Vehicle key in high-gloss black with matte chrome trim.
- Transmission: 9-speed automatic, 9G-TRONIC
- LED taillights
- Interior headliner in Crystal Grey fabric
- THERMATIC automatic climate control
- Headrests 5-way adjustable for driver and front passenger, 4-way adjustable, and 2-way adjustable in the rear.
- Steering column mechanically adjustable in height and length
- Center console piano black finish
- Package: Standard Exterior Equipment
- PRE-SAFE system
- Tire pressure monitoring system
- Windscreen wipers with rain sensor
- Power steering
- Seats: Rear seat backrests foldable, 40/20/40 split
- Power outlet: 12V socket in the cargo area
- High-visibility vest for drivers
- Green, heat-insulating glass all around
- Decorative elements, silver effect lacquer



Extra equipment

- Paint finish: Metallic
- Package: Business (66l fuel tank (60l for 300 de) - SD card navigation: expands the Audio 20 GPS into an online-enabled multimedia system with SD card navigation, live traffic information, voice recognition - pre-installation for navigation including live traffic and SDHC card slot - 12.3" media display - smartphone integration (Apple CarPlay and Android Auto) - parking package with reversing camera - heated seats for driver and front passenger)
- Package: Seating comfort (various electric and manual adjustment options for the front seats to adapt to the specific body and comfort requirements of the driver and front passenger - electro-pneumatic 4-way lumbar support with control element on the seat - electric seat cushion tilt adjustment - electric height adjustment - electric backrest adjustment - mechanical seat cushion depth adjustment by 6 cm with leg rest pad - mechanical longitudinal adjustment - mechanical headrest adjustment)
- MULTIBEAM LED (with 84 individually controllable LEDs, Adaptive Highbeam Assist Plus. The MULTIBEAM LED headlights enable permanent high beam without dazzling other road users. Individually controllable LEDs precisely mask other vehicles while simultaneously illuminating the surroundings with near-daylight brightness. Another design highlight: the blue illuminated accents in the headlight.)
- Package: Parking package with reversing camera (The parking package with reversing camera makes it easier to find and select parking spaces, as well as to park and exit in parallel and perpendicular parking spaces or garages. The active parking assistant steers the vehicle into parking spaces, including speed control and automatic gear changes.)
- Radio accessories: Burmester surround sound system (with 13 speakers, a 9-channel DSP amplifier and a total system output of 590 W. 13 high-performance speakers and electronic and acoustic elements precisely tuned to the interior ensure first-class Burmester sound. The surround function or sound optimization for the front and rear seats makes the listening experience even more immersive.)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Rear of vehicle	Boot floor (Verkleidung) - Broken / torn - Replace
2	Seat - front	Seat cover - left side - Soiled - Clean
3	Boot lid / rear door	Boot lid - Glued / labelled - De-glue / neutralise
4	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - Loss in value
5	Wheel / tyres	Alloy rim - front left side - Scratch(es) - Loss in value
6	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
7	Sill - left side	Sill - dent(s) - Smooth repair work
8	Front bumper	Front bumper (+ Steinschläge) - Scratch(es) - Paint
9	Rear bumper	Rear bumper - Scratch(es) - Paint
10	Bonnet	Bonnet (+ Delle) - Scratch(es) - Repair and paint



Wear and tear

No.	Component group	Description
1	Instrument panel	Centre console - front - Scratched - No deduction
2	Seat - front	Seat cover - left side - Scratched - No deduction
3	Side panel - rear right side	Sill - Dent / paintcoat damage - No deduction
4	Engine	Engine cowling lower front - Scratched - No deduction
5	Engine	Engine cowling - lower - Scratched - No deduction
6	Body	Body (Waschanlagenkratzer) - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.

Die Beiliegenden Räder sind kein Teil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Documents




Figure 16: Documents




Figure 17: Documents




Figure 18: Documents




Figure 19: Documents



Figure 20: Additional tyres




Figure 21: Navigation



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.



Figure 40: Misc.





Figure 41: Misc.



Figure 42: Misc.




Damage 1: Rear of vehicle: Boot floor (Verkleidung) - Broken / torn - Replace




Damage 1: Rear of vehicle: Boot floor (Verkleidung) - Broken / torn - Replace



Damage 2: Seat - front: Seat cover - left side - Soiled - Clean



Damage 2: Seat - front: Seat cover - left side - Soiled - Clean



Damage 2: Seat - front: Seat cover - left side - Soiled - Clean



Damage 3: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise



Damage 3: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise




Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value




Damage 5: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 5: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 5: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value




Damage 5: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 7: Sill - left side: Sill - dent(s) - Smooth repair work



Damage 7: Sill - left side: Sill - dent(s) - Smooth repair work



Damage 8: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint




Damage 8: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 8: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 8: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 8: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 8: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 10: Bonnet: Bonnet (+ Delle) - Scratch(es) - Repair and paint




Damage 10: Bonnet: Bonnet (+ Delle) - Scratch(es) - Repair and paint




Damage 10: Bonnet: Bonnet (+ Delle) - Scratch(es) - Repair and paint




Damage 10: Bonnet: Bonnet (+ Delle) - Scratch(es) - Repair and paint




Damage 10: Bonnet: Bonnet (+ Delle) - Scratch(es) - Repair and paint



Wear and tear 2: Seat - front: Seat cover - left side - Scratched - No deduction



Wear and tear 2: Seat - front: Seat cover - left side - Scratched - No deduction



Wear and tear 2: Seat - front: Seat cover - left side - Scratched - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1K2132041B005862

Hersteller / Modell: MERCEDES-BENZ MERCEDES-BENZ E 220 d T 9G-TRONIC

Datum	KM-Stand	Beschreibung
20.04.2026	154.658	Bremsbelagfühler ern; Bremsklötze hinten; Bremsklötze vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Regelwartungsdienst
25.09.2025	129.250	Regelwartungsdienst
20.12.2024	105.589	Bremsscheiben+Beläge v+h; Regelwartungsdienst
13.12.2024	102.935	AU; Reparatur Sonstiges
17.05.2024	77.671	Regelwartungsdienst
31.07.2023	55.417	Bremsscheiben+Beläge v+h
14.06.2023	52.658	Regelwartungsdienst
07.10.2022	26.273	Regelwartungsdienst