



Expertise

Protocol number: 46599191
Order No. / Reference: 26626460
Inspection date: 20 Jul 2026

Manufacturer: Ford

Model: Transit Connect 230 L2 S&S Autm. Trend

VIN: WF0SXXWPGSKM34804



Vehicle details

Manufacturer / Type / Model / Equipment

Ford Transit Connect 230 L2 S&S Autm. Trend

Vehicle Identification number	WF0SXXWPGSKM34804
Mileage (Read)	63,639 km
First registration	3 Apr 2020
Number of holders	1
Next periodical technical inspection	07/2026
(Report on hand)	

Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	88 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Van

Colour / colour code	Frost Weiß
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle with smoke odor	no
-------------------------	----



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	17,000 km
Last service on / at	04/2026 at 60,412 km		
Key is / should be	3 / 3	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FR781415
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BMN 01347		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,380 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96V	Summer tyres on Steel rim with wheel cover	Continental	6mm / 6mm
2)	205/60 R16 96V	Summer tyres on Steel rim with wheel cover	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Steel	Continental	7mm / 7mm
2)	205/60 R16 96H	Winter tyres on Steel	Fulda	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/60 R16 96H	Summer tyres on Steel	Continental	8 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- ABS with EBD
- Exterior mirrors, narrow mirror format
- Hill start assist
- On-board computer including outside temperature display
- Double-leaf rear doors without windows
- Third brake light
- Front electric windows
- Heated windshield and windshield washer nozzles
- Glove compartment with lid
- Front interior lighting with delay function
- Front air conditioning including semi-electronic recirculation system
- Cargo area lining, side, half-height
- Center console, front
- Wheels: Steel wheels 6.5 J x 16 with 205/60 R 16 tires and wheel trims
- Electro-mechanical power steering
- Front seat belts are height-adjustable
- Front spoiler lip
- Dust and pollen filter
- Power outlet: 12-volt connection on the front center console
- Front bumper and rear bumper end caps painted in body color
- Partition wall to the cargo area without window
- Lashing eyes
- Heat-insulating glazing, lightly tinted
- Driver's side airbag
- Battery, reinforced
- Rubberized flooring, front
- Diesel particulate filter (DPF)
- Tachometer
- Electronic Safety and Stability Program (ESP)
- Ford Easy Fuel
- Transmission: 8-speed automatic
- Interior lighting in the passenger/cargo area with delay function
- Paint finish: Solid
- Cargo area floor protection plastic, molded
- Steering column, adjustable in height and reach
- Emergency brake light
- Sliding door at rear, right
- Side protection strips, plastic
- Safety brake assist
- Automatic door locking mechanism (45 sec.)
- Start-stop system
- Concealed storage compartment on dashboard
- Power outlet: 12-volt connection in storage compartment on dashboard (driver's side)
- Daytime running light
- Child safety lock on sliding doors
- Electronic immobilizer (EPATS)
- Auxiliary electric heater (PTC), front



Extra equipment

- Electrically adjustable and heated exterior mirrors with blind spot assist (blind spot assist including cross traffic alert)
- Adaptive cruise control (with intelligent speed limiter - including radar- and camera-based pre-collision assist, with pedestrian and cyclist detection, distance display and distance warning, as well as lane keeping assist including lane keeping assist and driver drowsiness detection - including traffic sign recognition system - leather multifunction steering wheel with 4 spokes in aluminum trim)
- Tire pressure monitoring system
- Spare wheel: Steel wheel
- Headlight assistant with day/night sensor including automatically dimming interior mirror (including headlight dimming with switch-off delay, windscreen wipers with rain sensor, heated windscreen and windscreen washer nozzles)
- SORTIMO CNRN 124833
- SORTIMO CNRN 141019
- SORTIMO CNRN 143251
- Auxiliary heating
- Winter complete wheels
- Third key, rubber mats, seat cover
- Remote control: 2nd remote control key for central locking (instead of conventional key)
- Fog lights with static cornering lights
- Active parking assistant with parking and exiting function (front and rear parking pilot system)
- Radio: Ford Audio System 9 (Ford navigation system incl. Ford SYNC 3 with AppLink, 6" touchscreen radio (FM/AM), 2 USB ports, audio remote control on the steering wheel, Bluetooth hands-free system and audio streaming, emergency call assistant, SMS text-to-speech function, SMS sending function, voice control, reversing camera, phase diversity antenna, DAB/DAB+, acoustic and visual route guidance, road map for Europe, TMCpro live traffic, detailed 3D visualization, Michelin travel guide for Europe)
- Crosswind Assist and Roll Stability Control (RSC)
- Seats: Seat Package 42 (Driver's seat, 3-way manually adjustable (forward/backward, height, backrest) - Single passenger seat, 2-way adjustable (forward/backward, backrest) - Height-adjustable headrests - Heated seats for driver and front passenger - Manually adjustable lumbar support in driver's seat - Airbag Package (Front airbag for front passenger, side airbags for driver and front passenger) - "Capitol/City" fabric in Ebony (black) - Seatbelt warning system for driver)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Wheel cover - rear left side - Broken / torn - Replace
2	Instrument panel	Glove box - Loose - Repair
3	Cab	Insulation lining (Stirnwand) - Damage caused by marten / rodent - Replace
4	Door - front left side	Door - dent(s) - Smart repair
5	Boot lid / rear door	Rear door - left side - dent(s) - Smart repair
6	Sill - left side	Sill - Scratch(es) - Smart repair
7	Boot lid / rear door	Rear door - right side - dent(s) - Smart repair
8	Roof	Roof - dent(s) - Smart repair
9	Front bumper	Bumper with Parktronic (Unterteil) - Deformed - Replace



Wear and tear

No.	Component group	Description
1	Wheel / tyres	Wheel cover - front right side - Scratch(es) - No deduction
2	Bonnet	Bonnet - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side - left, Provided by user / customer, from 16 Mar 2021	1.535,08 €
2	Rear, Side right, Provided by user / customer, from 5 Nov 2020	2.270,86 €
3	Rear, Side - left, Provided by user / customer, from 2 Jul 2024	3.079,28 €

Accident damages

No.	Accident
1	Rear, Side right

Repainting

No.	Repainting
1	Side panel - rear left side, Side panel - rear right side, Door - rear right side, Professionally carried out

Paint coat thickness measurement

Side panel - rear left side	547 µm	Side panel - rear right side	610 µm
Door - rear right side	329 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung erhebliche Mehrkosten und somit Abweichung der für den Unfall ausgewiesenen Reparaturkosten nicht ausgeschlossen werden.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Documents



Figure 17: Additional tyres



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.




Damage 1: Wheel / tyres: Wheel cover - rear left side - Broken / torn - Replace



Damage 1: Wheel / tyres: Wheel cover - rear left side - Broken / torn - Replace



Damage 1: Wheel / tyres: Wheel cover - rear left side - Broken / torn - Replace



Damage 2: Instrument panel: Glove box - Loose - Repair



Damage 2: Instrument panel: Glove box - Loose - Repair



Damage 3: Cab: Insulation lining (Stirnband) - Damage caused by marten / rodent - Replace



Damage 3: Cab: Insulation lining (Stirnband) - Damage caused by marten / rodent - Replace




Damage 4: Door - front left side: Door - dent(s) - Smart repair



Damage 4: Door - front left side: Door - dent(s) - Smart repair



Damage 5: Boot lid / rear door: Rear door - left side - dent(s) - Smart repair



Damage 5: Boot lid / rear door: Rear door - left side - dent(s) - Smart repair



Damage 6: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 6: Sill - left side: Sill - Scratch(es) - Smart repair




Damage 7: Boot lid / rear door: Rear door - right side - dent(s) - Smart repair



Damage 7: Boot lid / rear door: Rear door - right side - dent(s) - Smart repair



Damage 8: Roof: Roof - dent(s) - Smart repair



Damage 8: Roof: Roof - dent(s) - Smart repair



Damage 8: Roof: Roof - dent(s) - Smart repair



Damage 8: Roof: Roof - dent(s) - Smart repair



Damage 8: Roof: Roof - dent(s) - Smart repair



Damage 9: Front bumper: Bumper with Parktronic (Unterteil) - Deformed - Replace



Damage 9: Front bumper: Bumper with Parktronic (Unterteil) - Deformed - Replace



Damage 9: Front bumper: Bumper with Parktronic (Unterteil) - Deformed - Replace



Damage 9: Front bumper: Bumper with Parktronic (Unterteil) - Deformed - Replace



Accident 1: Rear, Side right



Accident 1: Rear, Side right




Accident 1: Rear, Side right




Accident 1: Rear, Side right




Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right




Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right




Accident 1: Rear, Side right




Accident 1: Rear, Side right



Side panel - rear left side: 547 µm



Side panel - rear right side: 610 µm



Door - rear right side: 329 µm



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0SXXWPGSKM34804
Hersteller / Modell: FORD FORD Transit Connect 230 L2 S&S Autm. Trend

Datum	KM-Stand	Beschreibung
10.04.2026	60.412	Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
23.07.2025	50.753	Motoröl b. Wartung; Ölwechsel; Regelwartungsdienst
24.01.2025	45.134	Batterie ern
04.07.2024	40.454	Bremsinspektion vo + hi; AU; Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsklötze vorne; Kraftstofffilter ern; Ladeluftschlauch ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
01.02.2024	36.159	Keilrippenriemen; Reparatur Sonstiges; Spannrolle ern; Systemtest/ Eigendiagnose
26.07.2023	31.849	Motoröl b. Wartung; Regelwartungsdienst
09.02.2023	25.934	Batterie ern; Systemtest/Eigendiagnose
01.08.2022	20.529	Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze vorne; HU + AU; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/ Eigendiagnose; Wartung Sonstiges
22.09.2021	11.222	Motoröl b. Wartung; Ölwechsel