



2-FEG-327


2-FEG-327 · TS 1.8 Hybrid Dynamic + Business pack · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FEG-327	Fuel Type	Hybrid Gasoline
Manufacturer	TOYOTA	VIN	SB1ZB3AE20E099456
Model	Corolla Touring Sports	Cylinder Capacity	1.798 ^{cm3}
Model Versions	TS 1.8 Hybrid Dynamic + Business pack	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	10-04-2024
Color	Blue	Odometer	69.058 ^{km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	72	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance 26-03-2026

Last maintenance odometer 60.770

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 ^{mm}	Vredestein	205 ^{mm}	55 ^{mm}	16 ^{inch}	All Season
Rear Left	5 ^{mm}	Semperit	205 ^{mm}	55 ^{mm}	16 ^{inch}	All Season
Front Right	4 ^{mm}	Vredestein	205 ^{mm}	55 ^{mm}	16 ^{inch}	All Season
Rear Right	5 ^{mm}	Semperit	205 ^{mm}	55 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part

Fender – Rear Right



Damage Type

small dents / small scratches



Repair Type

Panelbeating & Spray


Acceptable

No



Damage Part

Reardoor – Right



Damage Type

small dents / small scratches



Repair Type

Panelbeating & Spray

Acceptable

No



Damage Part

Frontdoor – Right



Damage Type



Scratch(es)

Repair Type

Spray

Acceptable

No



Damage Part	Damage Type	Repair Type	Acceptable
Alloy - Right Front	Damaged	Rim repair	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Dislocated / Loose	Wielkuip bescherming	Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Front	Dent(s) & Scratch(es)	Panelbeating & Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper - Front	Scratch(es)	Mistlampkapje	Replace	No





Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Left	Door-edge chipped	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Left	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Rear Left	Small dent(s)	Restyle	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper - Rear	Dislocated / Loose	Sierstrip	Replace	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper - Rear	Missing	Trekoogkapje	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Scratch(es)	Spray	No