



Expertise

Protocol number: 46652293
Order No. / Reference: 26597927
Inspection date: 21 Jul 2026

Manufacturer: Ford

Model: Mustang Mach-E AWD GT

VIN: WF0TK4SXXPMA15519



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Mustang Mach-E AWD GT	
Vehicle Identification number	WF0TK4SXXPMA15519
Mileage (Read)	51,168 km
First registration	28 Dec 2023
Number of holders	1
Next periodical technical inspection	12/2026
(Report not on hand)	
Fuel type	Electric
Power	200 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	All-wheel drive
Type of vehicle	Saloon car
Colour / colour code	Rapid Red Metallic
Doors / Seats	5 / 5
Upholstery type	Artificial leather
Colour of upholstery	Black-Grey
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	
Key is / should be	2 / 2	FZG documents	Registration and title documents unavailable
		Letter No.	GX232802
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8566 / BVQ 00005		
Emission standard	2017/1151	fine dust sticker	
Permitted total weight	2,717 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R19 103V	Winter tyres on Light alloy	Nokian	6mm / 6mm
2)	225/55 R19 103V	Winter tyres on Light alloy	Nokian	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R20 103Y	Summer tyres on Light alloy	Pirelli	4mm / 4mm
2)	245/45 R20 103Y	Summer tyres on Light alloy	Pirelli	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 09/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- Klimaautomatik

Standard equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • Acoustic Vehicle Alerting System (AVAS) • Ambient lighting, multicolor LEDs • Anti-lock braking system (ABS) • Electrically adjustable and heated exterior mirrors • Tires: 8 J x 20 alloy wheels (4) diamond-cut in a unique design • third brake light • Anti-theft alarm system with interior monitoring • Electronic Stability Program (ESP) • Suspension: MagneRide high-performance suspension (adaptive) • High Beam Assist, Glare-Free • Electric parking brake with auto hold function • Ford EcoCoach • Front trunk with Ford MegaBox • Heated windshield • Transmission: 1-speed direct drive • Heated rear window • Rear spoiler • Intelligent Range • ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row. • Rear headrests (3) height adjustable • Steering wheel: Sensico steering wheel in leather look, heated • Illuminated makeup mirrors in the driver's and passenger's sun visors • Rear center armrest with two cup holders • MyKey key system • Emergency brake light, pulsating illumination of the brake lights during hard braking • Front and rear parking pilot system • Pollen and dust filter • Post-Collision Assist • Radio: Ford SYNC 4A audio system with B&O, digital radio reception DAB/DAB+, touchscreen and navigation • Reversing camera with reversing parking assistant • Headlights: Matrix LED headlights with daytime running lights • Power steering • Seats: Driver and passenger seats, 8-way electrically adjustable • Seats: Ford Performance sports seats, front • Telephone: Inductive charging station for mobile devices • Carpet floor mats front and rear, velour • Traffic sign recognition system • Immobiliser | <ul style="list-style-type: none"> • All-wheel drive • Towbar preparation kit • Electrically folding exterior mirrors • Exterior mirrors in contrasting black color • Tires: Tire repair kit • Brembo brakes 19" • Black woven fabric headliner • Front door sill trim strips with GT logo • Driver information system with digital instrument panel, 10.2" screen diagonal (25.9 cm) • Electric front and rear windows with all-around closing function • Ford Co-Pilot360 incl. Ford Intelligent Drive Assist • FordPass Connect including eCall, live traffic information and Wi-Fi hotspot • Flexible luggage compartment cover and luggage compartment lighting • rear window wiper • Interior mirror, automatically dimming • Intelligent Protection System (IPS) • Air conditioning with automatic temperature control • Integrated front seat headrests, not adjustable • Charging cables: 2 charging cables for charging the high-voltage battery • Steering wheel: Sports steering wheel • Media console with two USB ports at the front and two USB charging ports at the rear of the center console. • Mustang LED taillights • Fatigue warning • One Pedal Drive • Package: Technology Package+ • Standard design pedal assembly • Upholstery: Premium Sensico upholstery in leather look / suede look • Wheel arch trim painted in vehicle color • Tire Pressure Monitoring System (TPMS) • Windscreen wipers with rain sensor • Keys: Two classic car keys • Side windows from the 2nd row of seats and rear window, dark tinted. • Seat: Rear seat backrests, foldable, 60:40 split • Seats: Front seats, individually and variably heated • Power outlet: 12-volt connection in the luggage compartment • Electric door child safety lock • Lashing eyes in the luggage compartment • Central locking system with overall locking function |
|--|---|



Extra equipment

- Paint finish: Premium Metallic

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 1 (registration document) and the vehicle registration certificate Part 2 (title) were not available.
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Valve (Kappe) - Missing - Replace
2	Front bumper	Spoiler (Windabweiser vorne) - Scratched - Smart repair
3	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
4	2nd wheel set	1 tyre - Damaged - Replace
5	Seat - rear	Backrest cover - 2nd row (Druckstellen) - Damaged - Loss in value
6	Bonnet	Bonnet - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Für den montierten Radsatz wurde kein Nachweis erbracht.
- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.
- Service-Restlauf wird nicht angezeigt.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Additional tyres




Figure 17: Additional tyres



Figure 18: Additional tyres




Figure 19: Navigation




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.




Figure 35: Misc.





Figure 36: Misc.




Figure 37: Misc.



Damage 1: Wheel / tyres: Valve (Kappe) - Missing - Replace




Damage 1: Wheel / tyres: Valve (Kappe) - Missing - Replace



Damage 2: Front bumper: Spoiler (Windabweiser vorne) - Scratched - Smart repair



Damage 2: Front bumper: Spoiler (Windabweiser vorne) - Scratched - Smart repair



Damage 3: Side panel - rear left side: Side panel - dent(s) - Smooth repair work




Damage 3: Side panel - rear left side: Side panel - dent(s) - Smooth repair work




Damage 4: 2nd wheel set: 1 tyre - Damaged - Replace




Damage 4: 2nd wheel set: 1 tyre - Damaged - Replace




Damage 5: Seat - rear: Backrest cover - 2nd row (Druckstellen) - Damaged - Loss in value



Damage 5: Seat - rear: Backrest cover - 2nd row (Druckstellen) - Damaged - Loss in value



Damage 6: Bonnet: Bonnet - Scratch(es) - Paint



Damage 6: Bonnet: Bonnet - Scratch(es) - Paint